

March 5, 2021

Federal Energy Regulatory Commission 888 First Street, N.E. Washington, D.C. 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: El Paso Natural Gas Company, L.L.C.;

Docket No. CP20-483-000 Carlsbad South Project

Weekly Environmental Inspector Report No. 27

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP20-483-000, its weekly status report related to the Carlsbad South Project ("Project").

Description of Proceeding

On June 19, 2020, EPNG filed a prior notice request pursuant to Sections 157.205, 157.208(b), and 157.210 of the Commission's regulations under the Natural Gas Act for authorization to construct an approximate 17.1-mile sixteen-inch (16") outside diameter ("O.D.") loop line of its existing sixteen-inch (16") O.D. Line No. 3191 in Eddy County, New Mexico as well as to undertake minor appurtenant facility modifications at an existing compressor station at Lea County, New Mexico. This project is referred to as the Carlsbad South Project. At the conclusion of the notice period for the Carlsbad South Project on August 24, 2020, the project was deemed approved.

Submittal of Status Report

In compliance with Section 157.208(c)(10) of the Natural Gas Act, EPNG is providing Environmental Inspector Report No. 27 for the period of February 22, 2021 through February 28, 2021. Having completed all construction activities on this project, this will be the final weekly status report that will be filed.

Filing Information

EPNG is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.


By_____/s/ Francisco Tarin Director, Regulatory

Enclosures

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 5th day of March 2021.



Two North Nevada Avenue Colorado Springs, Colorado 80903 (719) 667-7517

EPNG's Weekly Environmental Inspection Report No. 27		
Docket No. CP20-483-000		
Project Name:	Carlsbad South Project	
County/State:	Eddy and Lea Counties, New Mexico	Date: 03/05/2021
Reporting Period:	02/22/2021 – 02/28/2021	
Environmental	Raymond Patton, Lead Environmental Inspector.	
Inspection:	Daniel Day, Environmental Inspector.	

1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:

Line No. 31113:

- Restoration complete.
- Fencing and gates installed, minor work in pig launcher yard complete.

Eunice Compressor Station Modifications:

Eunice Compressor Station modifications work completed.

Ancillary Facilities:

No updates during this reporting period.

2. RELEVANT ENVIRONMENTAL ACTIVITIES:

During this reporting period no (0) additional staff received environmental training. In total seven hundred seventy three (773) individuals received training.

3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN:

No environmental problems/issues and corrective actions this reporting period.

4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS:

No environmental compliance issues or resolutions occurred during this reporting period.

5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS:

No landowner issues or concerns identified during this reporting period.

6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD:

Construction and restoration of the Carlsbad South Project is now complete.

Location: Station Number 122+50

Direction of Photo: East **Description:** Moving H braces to install new

gates.

Date: 02/23/2021



Location: Station Number 906+00 Direction of Photo:

South

Description: Removing soil from around concrete pier from under pig receiver. **Date:** 02/24/2021



Location: Station Number 882+00 **Direction of Photo:**

North

Description: Hand seeding ROW by contractor where soil was disturbed while installing sub-mar mats. Date: 02/24/2021



Location: Station Number 238+00

Direction of Photo: East **Description:** Erosion Control Blankets at Dry Wash at Access Road 5.




Location: Station Number 289+00 Direction of Photo:

West

Description: Access

Road #4.

Date: 03/02/2021



North

Description: ROW looking North. **Date:** 03/02/2021



Location: Station Number 330+00 Direction of Photo:

North

Description: Erosion control blanket on banks

of dry wash.

Date: 03/02/2021



Location: Station Number 336+00 Direction of Photo: South

Description: Dry wash

and ROW.



Location: Station Number 460+00 **Direction of Photo:**

North

Description: Access road

and ROW.

Date: 02/27/2021



Location: Station Number 511+00 Direction of Photo: East Description: Access Road #7 and ROW. Date: 02/27/2021



Location: Station Number 511+00 Direction of Photo:

North

Description: Dry wash with erosion control blanket at Access Road

#7.

Date: 02/27/2021



Location: Station Number 568+00 Direction of Photo:

West

Description: Access Road #8 and ROW. **Date:** 02/27/2021



Location: Station Number 745+00 Direction of Photo:

West

Description: Cooksey Ranch Road Access Road

and ROW.

Date: 02/27/2021



Location: Station Number 878+00 Direction of Photo: East Description: Dry wash after sub-mar mats were

installed.



Location: Station Number 876+00 Direction of Photo: East Description: Dry wash

installed.

Date: 03/02/2021

with sub-mar mats

Location: Station Number 888+00 Direction of Photo: East Description: Longhorn Road Access Road and

ROW.

Date: 02/27/2021



Location: Station Number 889+00

Direction of Photo: East **Description:** Dry wash behind El Paso Station. **Date:** 03/02/2021



Location: Station Number 889+00 **Direction of Photo:**

Description: Road approach at Longhorn

Road.

North



Location: Station Number 893+00 Direction of Photo:

South

Description: Dry wash. **Date:** 03/02/2021

