



February 27, 2020

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, DC 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Sierrita Gas Pipeline LLC;
Docket No. CP18-37-000;
Sierrita Compressor Expansion Project;
Project Status Report No. 23

Commissioners:

Sierrita Gas Pipeline LLC ("Sierrita") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-37-000, its biweekly status report related to the Sierrita Compressor Expansion Project.

Description of Proceeding

On December 21, 2017, Sierrita submitted its application, pursuant to Section 7(c) of the Natural Gas Act requesting a certificate of public convenience and necessity for authorization to construct, install, and operate a new compressor ("Sierrita Compressor Station") to be located in Pima County, Arizona. The project is referred to as the "Sierrita Compressor Expansion Project."

Submittal of Status Report

In compliance with Environmental Condition No. 8 of Appendix A to the Order, Sierrita is providing Project Status Report No. 23 for the period of February 9, 2020 through February 22, 2020.

Filing Information

Sierrita is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Federal Energy
Regulatory Commission

-2-

February 27, 2020

Respectfully submitted,

SIERRITA GAS PIPELINE LLC

By /s/
Francisco Tarin
Director, Regulatory

Enclosures



Report No. 23

Sierrita Expansion: Bi-Weekly Environmental Inspector Report		
Docket No. CP18-37-000		
Project Name:	Sierrita Compressor Expansion Project	
County/State:	Pima County, Arizona	Date: 02/27/2020
Reporting Period:	February 9, 2020 to February 22, 2020	
Environmental Inspector:	John Durham	
<p>1. Summary of Construction Activity for Inspection Period: Contractor worked on hydrostatic testing of lead lines and other components. Prepping and painting of components occurred in the paint spraying station. Electrical connection work continued. Component welding, excavation and backfill activities continued. Lube oil flushing and filtration for the Solar Turbine was completed.</p> <p>2. Relevant Environmental Activities: Twelve (12) people received the environmental training during this reporting period. A project total of one hundred eighty-six (186) people have received environmental training.</p> <p>The Environmental Inspector ("EI") monitored the hydrostatic testing water discharge.</p> <p>3. Environmental Problems/Issues and Corrective Actions Taken: No environmental problems or non-compliance issues were identified during this reporting period.</p> <p>4. Environmental Compliance Issues/Resolutions: There were no environmental compliance issues identified during this reporting period.</p> <p>5. Issues and Concerns Identified by Landowners: No landowner issues or concerns were identified during this reporting period.</p> <p>6. Work Planned for the Following Reporting Period: Hydrostatic testing, electrical installation and connection work will continue.</p>		

Report No. 23

Photos

Location: Line
No. 2177 ROW
**Direction/Date of
Photo:** East
02-10-2020
Description:
Preparation for
hydrostatic
testing.



Location:
Compressor
Station Site
**Direction/Date of
Photo:** North
02-10-2020
Description:
Trench
excavation.



Report No. 23

Location:

Compressor
Station Site

Direction/Date of

Photo: West
02-10-2020

Description:
Electrical line
installation.



Location:

Compressor
Station Site

Direction/Date of

Photo: West
02-11-2020

Description:
Waste oil
separator
connection.



Report No. 23

Location:

Compressor
Station Site

Direction/Date of

Photo: North
02-11-2020

Description:

Utility piping
layout.



Location:

Compressor
Station Site

Direction/Date of

Photo: West
02-13-2020

Description:

Welding work.



Report No. 23

Location:

Mainline ROW

Direction/Date of

Photo: North

02-13-2020

Description:

Support forms set up.



Location:

Compressor

Station Site

Direction/Date of

Photo: North

02-14-2020

Description:

Prepping for
hydro test water
discharge.



Report No. 23

Location:

Compressor
Station Site

Direction/Date of

Photo: West

02-18-2020

Description:

Hydro testing of
lines.



Location:

Compressor
Station Site

Direction/Date of

Photo: West

02-18-2020

Description:

Concrete
supports forms.



Report No. 23

Location:

Compressor
Station Site

Direction/Date of

Photo: South

02-22-2020

Description: Pipe
assembly work.



Location:

Compressor
Station Site

Direction/Date of

Photo: West

02-22-2020

Description:
Drying pipe after
hydro test.



Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing document to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 27th day of February, 2020.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517