



June 6, 2019

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, DC 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Sierrita Gas Pipeline LLC;
Docket No. CP18-37-000;
Sierrita Compressor Expansion Project;
Project Status Report No. 4

Commissioners:

Sierrita Gas Pipeline LLC ("Sierrita") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-37-000, its biweekly status report related to the Sierrita Compressor Expansion Project.

Description of Proceeding

On December 21, 2017, Sierrita submitted its application, pursuant to Section 7(c) of the Natural Gas Act requesting a certificate of public convenience and necessity for authorization to construct, install, and operate a new compressor ("Sierrita Compressor Station") to be located in Pima County, Arizona. The project is referred to as the "Sierrita Compressor Expansion Project."

Submittal of Status Report

In compliance with Environmental Condition No. 8 of Appendix A to the Order, Sierrita is providing Project Status Report No. 4 for the period of May 19, 2019 through June 1, 2019.

Filing Information

Sierrita is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Sierrita Expansion Bi-Weekly Environmental Inspector Report No. 4		
Docket No. CP18-37-000		
Project Name:	Sierrita Expansion Project	
County/State:	Pima County, Arizona	Date: 6/6/19
Reporting Period:	May 19, 2019 to June 1, 2019	
Environmental Inspector:	Russell Waldron	
<p>1. Summary of Construction Activity for Inspection Period: During this reporting period, the security fence installation was completed on May 22nd. Seeding was completed using broadcast seeding technique.</p> <p>2. Relevant Environmental Activities: During this reporting period, no one received environmental training. A total of twenty-five (25) people have received environmental training on the Sierrita Compressor Expansion Station Project.</p> <p>No relevant environmental issues were noted during this reporting period.</p> <p>3. Environmental Problems/Issues and Corrective Actions Taken: There were no environmental problems or issues identified during this reporting period.</p> <p>4. Environmental Compliance Issues/Resolutions: There were no environmental compliance issues identified during this reporting period.</p> <p>5. Issues and Concerns Identified by Landowners: No landowner issues or concerns were identified during this reporting period.</p> <p>6. Work Planned for the Following Reporting Period: No work is planned for the next reporting period.</p>		

Report No. 4

Photos	
<p>Location: MP 1.2/MLV2 Direction of Photo: South Description: Looking south from north of the northeast corner of MLV2.</p>	 A wide-angle photograph showing a dirt road with tire tracks leading towards a fenced-in industrial site. The site contains various pieces of equipment and structures. The background shows a clear blue sky and distant mountains.
<p>Location: MP 1.2/MLV2 Direction of Photo: Southwest Description: Looking southwest from north of the site.</p>	 A photograph showing a utility pole with a transformer and a portable toilet in the foreground. In the background, there is a fenced-in industrial site with various structures and equipment. The sky is clear and blue.

Location: MP 1.2/MLV2
Direction of Photo: South
Description: Looking south from northeast of the site after seeding activities were completed.



Location: MP 1.2/MLV2
Direction of Photo: Northeast
Description: Looking southwest from the northeast after seeding activities were completed.



