

November 21, 2018

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Colorado Interstate Gas Company, L.L.C.
Docket No. CP18-94-000
CIG 2018 Line Nos. 5A and 5B Expansion Project
Weekly Environmental Inspector Report No. 21

Commissioners:

Colorado Interstate Gas Company, L.L.C. ("CIG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-94-000 its Weekly Environmental Inspector Report related to the CIG 2018 Line Nos. 5A and 5B Expansion Project.

Description of Proceeding

On February 27, 2018, CIG filed a prior notice request, pursuant to Sections 157.205, 157.208(b), and 157.210 of the Federal Energy Regulatory Commission's ("Commission") Regulations under the Natural Gas Act to modify certain existing compression facilities located at the Cheyenne Hub in Weld County, Colorado. The project is referred to as the "CIG 2018 Line Nos. 5A and 5B Expansion Project" or "Project." On March 9, 2018, the Commission issued a Notice of Request Under Blanket Authorization initiating the 60-day comment period to allow for any person or Commission's staff to file motions or notice to intervene and protests. No protests were filed with the time allowed therefore, the Project was deemed authorized on May 9, 2018.

Submittal of Environmental Inspector Report

In compliance with Section 157.208(c)(10) of the Natural Gas Act, CIG is providing Environmental Inspector Report No. 21 for the period of November 11, 2018 through November 17, 2018.

Colorado Interstate Gas Company, L.L.C.
CIG 2018 Line Nos. 5A and 5B Expansion Project
Docket No. CP18-94-000
Weekly Environmental Inspector Report No. 21

Reporting Period: 11/11/2018 thru 11/17/2018

Environmental Inspector: Tom Blandi

Construction Status: CIG placed into service the 2018 Line Nos. 5A and 5B Expansion Project facilities on November 16, 2018. The contractor continued work on a 2-inch drain line and continued clean up on the 24-inch pipeline ROW. Crews began backfilling the bi-directional manifold.

Grading: N/A

Erosion Control: All erosion controls were inspected and are performing as expected.

Work Planned for the Following Reporting Period (11/18/18-11/24/18): Crews will continue with backfilling, pad building and cleanup operations. The contractor plans to test the 2-inch drain line.

Correspondence from Federal, State, and Local Agencies Concerning Compliance Issues: No federal, state or local permitting agency has notified CIG of instances of noncompliance.


Landowner Complaints: There were no landowner/resident complaints received during the reporting period.

Environmental Training: Environmental training was provided to 2 employees during site safety orientation. To date a total of 267 employees have received environmental training.

**Colorado Interstate Gas Company, L.L.C.
CIG 2018 Line Nos. 5A and 5B Expansion Project
Docket No. CP18-94-000
Weekly Environmental Inspector Report No. 21**



Backfilling of the bi-directional manifold



Installation of the 2-inch drain line

**Colorado Interstate Gas Company, L.L.C.
CIG 2018 Line Nos. 5A and 5B Expansion Project
Docket No. CP18-94-000
Weekly Environmental Inspector Report No. 21**



2-inch drain line installation



24-inch pipeline ROW clean up

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 21st day of November, 2018.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517