

January 17, 2019

Federal Energy Regulatory Commission 888 First Street, N.E. Washington, D.C. 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Colorado Interstate Gas Company, L.L.C. Docket No. CP18-94-000 CIG 2018 Line Nos. 5A and 5B Expansion Project Weekly Environmental Inspector Report No. 29

### Commissioners:

Colorado Interstate Gas Company, L.L.C. ("CIG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-94-000 its Weekly Environmental Inspector Report related to the CIG 2018 Line Nos. 5A and 5B Expansion Project.

## Description of Proceeding

On February 27, 2018, CIG filed a prior notice request, pursuant to Sections 157.205, 157.208(b), and 157.210 of the Federal Energy Regulatory Commission's ("Commission") Regulations under the Natural Gas Act to modify certain existing compression facilities located at the Cheyenne Hub in Weld County, Colorado. The project is referred to as the "CIG 2018 Line Nos. 5A and 5B Expansion Project" or "Project." On March 9, 2018, the Commission issued a Notice of Request Under Blanket Authorization initiating the 60-day comment period to allow for any person or Commission's staff to file motions or notice to intervene and protests. No protests were filed with the time allowed therefore, the Project was deemed authorized on May 9, 2018.

### Submittal of Environmental Inspector Report

In compliance with Section 157.208(c)(10) of the Natural Gas Act, CIG is providing Environmental Inspector Report No. 29 for the period of January 6, 2019 through January 12, 2019.

#### Filing Information

CIG is e-Filing this letter and attachment with the Commission's Secretary in accordance with the Commission's Order No. 703, Filing Via the Internet, guidelines issued on November 15, 2007 in Docket No. RM07-16-000. A copy of this filing is also being provided to all parties of record.

> Respectfully submitted, COLORADO INTERSTATE GAS COMPANY, L.L.C.

By /s/ Francisco Tarin Director, Regulatory

Attachment

**Reporting Period:** 1/6/2018 thru 1/12/2018

### Environmental Inspector: Tom Blandi

**<u>Construction Status</u>**: Contractor is working on slot trenching for existing pipe removal and cleaning up spoil site.

Grading: N/A

**Erosion Control:** All erosion controls were inspected and are performing as expected.

**Work Planned for the Following Reporting Period (1/13/2018 to 1/19/18):** Contractor will work on the pad for the spillover area.

**Correspondence from Federal, State, and Local Agencies Concerning Compliance Issues:** No federal, state or local permitting agency has notified CIG of instances of noncompliance.

**Landowner Complaints:** There were no landowner/resident complaints received during the reporting period.

**Environmental Training:** Environmental training was provided to 1 employee during site safety orientation. To date a total of 287 employees have received environmental training.



## Slot trenching



Restored work area east and south of the bi-directional manifold



Cleaned up ROW for 24-inch pipeline between CIG and Front Range Compressor Station



Cleaned up ROW for 24-inch pipeline between CIG and Front Range Compressor Station



Cleaned up ROW for 24-inch pipeline between CIG and Front Range Compressor Station

## **Certificate of Service**

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 17<sup>th</sup> day of January, 2019.

/s/ Francisco Tarin

Two North Nevada Avenue Colorado Springs, Colorado 80903 (719) 667-7517