



El Paso Natural Gas
Company, L.L.C.
a Kinder Morgan company

August 27, 2020

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: El Paso Natural Gas Company, L.L.C.;
Docket No. CP18-332-000
Project Status Report No. 19

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-332-000, its biweekly project status report related to the South Mainline Expansion Project.

Description of Proceeding

On April 27, 2018, EPNG submitted its application, pursuant to Section 7(c) of the Natural Gas Act requesting a certificate of public convenience and necessity for authorization to construct, own, and operate: (i) an approximately 17-mile, thirty-inch diameter loop line of its existing Line Nos. 1100 and 1103 between Hueco and El Paso, Texas; (ii) the new Red Mountain Compressor Station in Luna County, New Mexico; and (iii) the new Dragoon Compressor Station located in Cochise County, Arizona. This project is referred to as the "South Mainline Expansion Project" or "Project." On November 21, 2019, the Commission issued an Order granting EPNG's requested certificate.¹

Submittal of Project Status Report

In compliance with Environmental Condition No. 8 of Appendix A to the Order, EPNG is providing Project Status Report No. 19 for the period of August 9, 2020 through August 22, 2020.

Filing Information

EPNG is e-Filing this letter and attachment with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

¹ See *El Paso Natural Gas Company, L.L.C.*, 169 FERC ¶ 61,133 (2019).

August 27, 2020

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.

By: _____/s/
Francisco Tarin
Director, Regulatory

Enclosures



EPNG's Biweekly Environmental Inspector Report No. 19		
Docket No. CP18-332-000		
Project Name:	South Mainline Expansion Project	
Project Components:	Dragoon Compressor Station, Red Mountain Compressor Station, 17-Mile Loop Line	
County/State:	Cochise County, Arizona (Dragoon CS); Luna County, New Mexico (Red Mountain CS); Hudspeth and El Paso Counties, Texas (17-Mile Loop Line)	Date: 8/27/2020
Reporting Period:	August 9, 2020 to August 22, 2020	
Environmental Inspectors:	David McCullough (Lead EI, 17-Mile Loop Line EI), Kendrick Moholt (Red Mountain CS EI, Dragoon CS EI)	
1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:		
<u>Dragoon Compressor Station</u>		
<ul style="list-style-type: none">Continued general site clean-up.Completed topsoil replacement, grading in the main yard and installation of gravel.Began reclamation and reseeding.Continued painting of station piping and compressor spools.Continued installing security fencing.Continued addressing final punch-list items.A post-construction noise survey was conducted on 8/19/20. The noise report is being finalized and will be submitted separately to FERC.		
<u>Red Mountain Compressor Station</u>		
<ul style="list-style-type: none">Completed minor clean-up of project site and final punch-list items.Completed demobilization from the site.A post-construction noise survey was conducted on 8/17/20. The noise report is being finalized and will be submitted separately to FERC.All work at Red Mountain Compressor Station is now complete. <p>(Since only minor clean up items were completed and no further reclamation/reseeding activities occurred, no photographs are being submitted for the Red Mountain CS in this report.)</p>		
<u>17-Mile Loop Line</u>		
All work associated with the 17-Mile Loop Line has been completed.		
2. RELEVANT ENVIRONMENTAL ACTIVITIES:		
During this reporting period, no environmental training was conducted.		



3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN:

There were no environmental problems or issues identified during this reporting period.

4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS:

There were no environmental compliance issues identified during this reporting period.

5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS:

No landowner issues or concerns were identified during this reporting period.

6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD:

Dragoon Compressor Station*

Activities planned for the next reporting period include:

- Continue clean-up of site;
- continue miscellaneous-type activities to include painting activities, reclamation and reseeding activities, and installation of security fencing; and
- continue addressing final punch-list items.

*Contractor is scheduled to demobilize from the site on September 11, 2020.

Red Mountain Compressor Station

All work associated with the Red Mountain Compressor Station has been completed.

17-Mile Loop Line

All work associated with the 17-Mile Loop Line has been completed.



Photos

Location: Dagoon Compressor Station

Description:

Looking southeast at station yard after grading, gravel and security fencing completed.



Location: Dagoon Compressor Station

Description:

Looking west at station yard after grading, gravel and security fencing completed.





Photos

Location: Dragoon Compressor Station

Description: Aerial view of station during reporting period.



Location: Dragoon Compressor Station

Description: Suction pipelines tie in yard after painting, grading, gravel and security fencing completed.



Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing document to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 27th day of August, 2020.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517