



El Paso Natural Gas
Company, L.L.C.
a Kinder Morgan company

September 10, 2020

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: El Paso Natural Gas Company, L.L.C.;
Docket No. CP18-332-000
Project Status Report No. 20

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-332-000, its biweekly project status report related to the South Mainline Expansion Project.

Description of Proceeding

On April 27, 2018, EPNG submitted its application, pursuant to Section 7(c) of the Natural Gas Act requesting a certificate of public convenience and necessity for authorization to construct, own, and operate: (i) an approximately 17-mile, thirty-inch diameter loop line of its existing Line Nos. 1100 and 1103 between Hueco and El Paso, Texas; (ii) the new Red Mountain Compressor Station in Luna County, New Mexico; and (iii) the new Dragoon Compressor Station located in Cochise County, Arizona. This project is referred to as the "South Mainline Expansion Project" or "Project." On November 21, 2019, the Commission issued an Order granting EPNG's requested certificate.¹

Submittal of Project Status Report

In compliance with Environmental Condition No. 8 of Appendix A to the Order, EPNG is providing Project Status Report No. 20 for the period of August 23, 2020 through September 5, 2020.

Filing Information

EPNG is e-Filing this letter and attachment with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

¹ See *El Paso Natural Gas Company, L.L.C.*, 169 FERC ¶ 61,133 (2019).

September 10, 2020

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.

By: _____/s/
Francisco Tarin
Director, Regulatory

Enclosures



EPNG's Biweekly Environmental Inspector Report No. 20		
Docket No. CP18-332-000		
Project Name:	South Mainline Expansion Project	
Project Components:	Dragoon Compressor Station, Red Mountain Compressor Station, 17-Mile Loop Line	
County/State:	Cochise County, Arizona (Dragoon CS); Luna County, New Mexico (Red Mountain CS); Hudspeth and El Paso Counties, Texas (17-Mile Loop Line)	Date: 9/10/2020
Reporting Period:	August 23, 2020 to September 5, 2020	
Environmental Inspectors:	David McCullough (Lead EI, 17-Mile Loop Line EI), Kendrick Moholt (Red Mountain CS EI, Dragoon CS EI)	
1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:		
<u>Dragoon Compressor Station</u>		
<ul style="list-style-type: none">• Continued general site clean-up.• Continued painting of station piping.• Continued reclamation and reseeding of all work areas.• Removed construction trailers.• Completed security fencing.• Continued addressing final punch-list items.		
<u>Red Mountain Compressor Station</u>		
All work associated with the Red Mountain Compressor Station has been completed.		
<u>17-Mile Loop Line</u>		
All work associated with the 17-Mile Loop Line has been completed.		
2. RELEVANT ENVIRONMENTAL ACTIVITIES:		
During this reporting period, no environmental training was conducted.		
3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN:		
There were no environmental problems or issues identified during this reporting period.		
4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS:		
There were no environmental compliance issues identified during this reporting period.		
5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS:		
No landowner issues or concerns were identified during this reporting period.		



6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD:

Dragoon Compressor Station

Activities planned for the next reporting period include:

- complete cleanup of remaining work areas;
- complete reclamation and reseeding in work areas;
- install permanent erosion control devices;
- continue addressing final punch-list items; and
- demobilization of the contractor from the site.

Red Mountain Compressor Station

All work associated with the Red Mountain Compressor Station has been completed.

17-Mile Loop Line

All work associated with the 17-Mile Loop Line has been completed.



Photos

Location: Dagoon
Compressor Station

Description:
Painting on
discharge piping.



Location: Dagoon
Compressor Station

Description:
Discharge pipelines
tie-in yard after
gravel and security
fencing completed.





Photos

Location: Dragoon
Compressor Station

Description: Aerial
view of compressor
station yard.



Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing document to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 10th day of September, 2020.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517