



El Paso Natural Gas
Company, L.L.C.
a Kinder Morgan company

March 24, 2022

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: El Paso Natural Gas Company, L.L.C.;
Docket No. CP21-96-000
Vail Enhancement Project
Weekly Environmental Inspector Report No. 25

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP21-96-000, its weekly status report related to the Vail Enhancement Project ("Project").

Description of Proceeding

On March 30, 2021, EPNG filed a prior notice request pursuant to Sections 157.205, 157.208(b), and 157.210 of the Commission's regulations under the Natural Gas Act for authorization to install enhancements at its existing Vail Compressor Station located in Pima County, Arizona. This project is referred to as the Vail Enhancement Project. At the conclusion of the notice period for the Vail Enhancement Project on June 9, 2021, the project was deemed approved.

Submittal of Status Report

In compliance with Section 157.208(c)(10) of the Natural Gas Act, EPNG is providing Environmental Inspector Report No. 25 for the period of March 13, 2022 through March 19, 2022.

Filing Information

EPNG is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.

By /s/
William D. Wible
Vice President, Regulatory

Enclosures

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 24th day of March 2022.

/s/

William D. Wible

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 520-3778

EPNG's Weekly Environmental Inspection Report No. 25		
Docket No. CP21-93-000		
Project Name:	Vail Enhancement Project	
County/State:	Pima County, Arizona	Date: 3/24/2022
Reporting Period:	3/13/2022 – 3/19/2022	
Environmental Inspection:	John Durham, Environmental Inspector.	
<p>1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:</p> <ul style="list-style-type: none"> • Completed mainline tie-ins • Completed painting blow down silencer • Continued site clean-up • Continued regrading and spreading gravel outside the operational fencing • Continued installation of lightning protection on the compressor building • Continued electrical and instrumentation commissioning • Began modifying nozzle water and glycol piping to turbine <p>2. RELEVANT ENVIRONMENTAL ACTIVITIES: During this reporting period, four (4) additional individuals received environmental training. The total number of individuals trained for the project is one-hundred thirty-two (132).</p> <p>3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN: No environmental problems/issues and corrective actions this reporting period.</p> <p>4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS: No environmental compliance issues or resolutions occurred during this reporting period.</p> <p>5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS: No landowner issues or concerns identified during this reporting period.</p> <p>6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD: Glycol piping work and painting tie-in spools will be completed. The contractor will purge and load gas in the station piping and complete leak tests. Restoration and clean-up work will continue. Construction trailers will be removed. The contractor is expected to begin to demobilize from the project.</p>		

Vail Enhancement Project

Location: Material Laydown Area
Direction of Photo: North
Description: Site restoration and clean-up.
Date: 3-21-22



Location: Compressor Station Yard
Direction of Photo: West
Description: Coating prep for tie-in.
Date: 3-16-22



Vail Enhancement Project

Location: Compressor Station Building
Direction of Photo: Northwest
Description: Lightning installation.
Date: 3-16-22



Location: Compressor Station Yard
Direction of Photo: Southeast
Description: Final clean-up and grade.
Date: 3-16-22

