



August 15, 2024

Federal Energy Regulatory Commission  
888 First Street, N.E.  
Washington, D.C. 20426

Attention: Ms. Debbie-Anne A. Reese, Acting Secretary

Re: El Paso Natural Gas Company, L.L.C.;  
Docket No. CP23-546-000  
Line No. 1110 Loop Project  
Weekly Environmental Inspector Report – Aug 5, 2024 through Aug 11, 2024

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP23-546-000, its weekly status report related to the Line No. 1110 Loop Project ("Project").

### **Description of Proceeding**

On September 22, 2023, EPNG submitted a Request for Prior Notice Authorization Pursuant to Blanket Certificate in the above-referenced docket seeking authorization to construct, install, operate and maintain an approximately two-mile 30-inch outside diameter pipeline loop extension, located in Hudspeth County, Texas as part of its Line No. 1110 Loop Project.<sup>1</sup>

### **Submittal of Status Report**

In compliance with Section 157.208(c)(10) of the Natural Gas Act, EPNG is providing Environmental Inspector Report for the period of August 5, 2024 through August 11, 2024.

---

<sup>1</sup> EPNG received a timely protest within 60-days of the date of the notice issued by the Commission. Accordingly, the Project was reviewed as a case-specific certificate application under section 7 of the NGA. On April 25, 2024, the Commission issued an order denying the protest and authorizing EPNG to construct and operate the proposed facilities under its Part 157 blanket certificate.



**Certificate of Service**

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 15<sup>th</sup> day of August 2024.

*/s/*

---

Francisco Tarin

Two North Nevada Avenue  
Colorado Springs, Colorado 80903  
(719) 667-7517

<b>EPNG's Weekly Environmental Inspection Report No. 13</b>		
<b>Docket No. CP23-546-000</b>		
<b>Project Name:</b>	<b>Line No. 1110 Loop Project</b>	
<b>County/State:</b>	Hudspeth County, Texas	<b>Date:</b> 08/15/2024
<b>Reporting Period:</b>	08/05/2024 – 08/11/2024	
<b>Environmental Inspection:</b>	Chennie Castanon	
<p><b>1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:</b></p> <ul style="list-style-type: none"> <li>• Continued restoration along access road.</li> <li>• Completed restoration and cleanup activities at pig launcher site and along the new right-of-way ("ROW") of the mainline pipe.</li> <li>• Completed seeding the ROW and workspaces.</li> </ul> <p><b>2. RELEVANT ENVIRONMENTAL ACTIVITIES:</b> During this reporting period, the Environmental Inspector (EI) conducted biological sweeps for sensitive species and monitored restoration activities.</p> <p><b>3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN:</b> No environmental problems/issues or corrective actions occurred during this reporting period.</p> <p><b>4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS:</b> No environmental compliance issues or resolutions occurred during this reporting period.</p> <p><b>5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS:</b> No landowner issues or concerns identified during this reporting period.</p> <p><b>6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD:</b> Construction contractor will complete access road restoration. The contractor was completely demobilized from project site on 8/13/2024.</p>		

**Line No. 1110 Loop Project**

**Location:** View approximately 140 feet east of relocated pig launcher site.  
**Direction of Photo:** Southwest  
**Description:** Completed pig launcher site.  
**Date:** 08/08/2024



**Location:** Access road  
**Direction of Photo:** North  
**Description:** Access road restoration.  
**Date:** 08/10/2024



**Line No. 1110 Loop Project**

**Location:** MP 53+80  
**Direction of Photo:**  
West  
**Description:** Chain drag  
harrow used to lightly  
blend seed mix into soil  
following seed  
spreading.  
**Date:** 08/06/2024

