



July 26, 2024

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Attention: Ms. Debbie-Anne A. Reese, Acting Secretary

Re: El Paso Natural Gas Company, L.L.C.;
Docket No. CP23-546-000
Line No. 1110 Loop Project
Weekly Environmental Inspector Report – July 15, 2024 through July 21, 2024

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP23-546-000, its weekly status report related to the Line No. 1110 Loop Project ("Project").

Description of Proceeding

On September 22, 2023, EPNG submitted a Request for Prior Notice Authorization Pursuant to Blanket Certificate in the above-referenced docket seeking authorization to construct, install, operate and maintain an approximately two-mile 30-inch outside diameter pipeline loop extension, located in Hudspeth County, Texas as part of its Line No. 1110 Loop Project.¹

Submittal of Status Report

In compliance with Section 157.208(c)(10) of the Natural Gas Act, EPNG is providing Environmental Inspector Report for the period of July 15, 2024 through July 21, 2024.

¹ EPNG received a timely protest within 60-days of the date of the notice issued by the Commission. Accordingly, the Project was reviewed as a case-specific certificate application under section 7 of the NGA. On April 25, 2024, the Commission issued an order denying the protest and authorizing EPNG to construct and operate the proposed facilities under its Part 157 blanket certificate.

Filing Information

EPNG is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.

By _____ /s/
Francisco Tarin
Director, Regulatory

Enclosures

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 26th day of July 2024.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517

EPNG's Weekly Environmental Inspection Report No. 10		
Docket No. CP23-546-000		
Project Name:	Line No. 1110 Loop Project	
County/State:	Hudspeth County, Texas	Date: 07/26/2024
Reporting Period:	07/15/2024 – 07/21/2024	
Environmental Inspection:	Chennie Castanon	
<p>1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:</p> <ul style="list-style-type: none"> • The Line No. 1110 Loop Project was placed into service effective July 19, 2024. • Completed welding tie-in joints. • Completed drying mainline and launcher assembly piping. • Continued backfilling pig launcher and hot tap sites associated with the launcher. • Continued restoration and cleanup activities. <p>2. RELEVANT ENVIRONMENTAL ACTIVITIES:</p> <p>During this reporting period, the Environmental Inspector (EI) conducted daily surveys for sensitive species along the access route and project workspaces. The EI also observed a transport truck carrying a pig cleaning head system get stuck in the mud along the access route as it was leaving the project site. The EI inspected the area around the transport truck for inadvertent spills, and none were observed. The transport truck was towed out of the mud, and the ruts were graded.</p> <p>3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN:</p> <p>No environmental problems/issues or corrective actions this reporting period.</p> <p>4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS:</p> <p>No environmental compliance issues or resolutions occurred during this reporting period.</p> <p>5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS:</p> <p>No landowner issues or concerns identified during this reporting period.</p> <p>6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD:</p> <p>Construction contractor will: Continue restoration and cleanup activities and discharge hydrostatic test water from frac tanks.</p>		

Line No. 1110 Loop Project


Location: MP 0+00
Direction of Photo:
Northwest
Description: Welding
tie-in joints at the
western terminus of the
mainline.
Date: 07/17/2024



Location: 0+60
Direction of Photo:
Southwest
Description: Grading
and topsoil distribution
as part of restoration
activities.
Date: 07/20/2024



Line No. 1110 Loop Project



● 13R 440861 3512597 ±3 m ▲ 1368m



Location: Access Route
PAR #02

Direction of Photo:
Northwest

Description: Stuck
transport truck on
access route PAR #02.

Date: 07/15/2024