

July 3, 2024

Federal Energy Regulatory Commission 888 First Street, N.E. Washington, D.C. 20426

Attention: Ms. Debbie-Anne A. Reese, Acting Secretary

Re: El Paso Natural Gas Company, L.L.C.;

Docket No. CP23-546-000 Line No. 1110 Loop Project

Weekly Environmental Inspector Report – June 24, 2024 through June 30, 2024

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP23-546-000, its weekly status report related to the Line No. 1110 Loop Project ("Project").

Description of Proceeding

On September 22, 2023, EPNG submitted a Request for Prior Notice Authorization Pursuant to Blanket Certificate in the above-referenced docket seeking authorization to construct, install, operate and maintain an approximately two-mile 30-inch outside diameter pipeline loop extension, located in Hudspeth County, Texas as part of its Line No. 1110 Loop Project.¹

Submittal of Status Report

In compliance with Section 157.208(c)(10) of the Natural Gas Act, EPNG is providing Environmental Inspector Report for the period of June 24, 2024 through June 30, 2024.

¹ EPNG received a timely protest within 60-days of the date of the notice issued by the Commission. Accordingly, the Project was reviewed as a case-specific certificate application under section 7 of the NGA. On April 25, 2024, the Commission issued an order denying the protest and authorizing EPNG to construct and operate the proposed facilities under its Part 157 blanket certificate.

Filing Information

EPNG is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.


By /s/
Francisco Tarin
Director, Regulatory

Enclosures

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 3rd day of July 2024.



Two North Nevada Avenue Colorado Springs, Colorado 80903 (719) 667-7517

EPNG's Weekly Environmental Inspection Report No. 5		
Docket No. CP23-546-000		
Project Name:	Line No. 1110 Loop Project	
County/State:	Hudspeth County, Texas	Date: 07/03/2024
Reporting Period:	06/24/2024 – 06/30/2024	
Environmental	Chennie Castanon	
Inspection:		

1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:

- Completed work on foundations for launcher relocation and started installing launcher.
- Continued x-raying pipe joints.
- Continued trenching for mainline pipe and started lowering mainline pipe into trench.
- Continued to grade along access road and applied water for dust suppression where necessary.
- Started delivering frac tanks and water to the right-of-way in preparation for hydrostatic testing activities.

2. RELEVANT ENVIRONMENTAL ACTIVITIES:

During this reporting period, the Environmental Inspector (EI) conducted a Stormwater Pollution Prevention Plan (SWPPP) inspection after the project area received 0.50-inch of rainfall and also conducted daily surveys for sensitive species along the access route and project workspaces.

3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN:

No environmental problems/issues or corrective actions this reporting period.

4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS:

No environmental compliance issues or resolutions occurred during this reporting period.

5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS:

No landowner issues or concerns identified during this reporting period.

6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD:

Construction contractor will: continue grading activities along the access road, complete x-raying pipe, complete ditching and lowering pipe into trench, complete installation of relocated launcher, and begin hydrostatic testing activities.

Line No. 1110 Loop Project

Location: MP 99+60 **Direction of Photo:** Southwest

Description: Pipeline trench with pipe on

supports.

Date: 06/24/2024

Location: MP 37+00 Direction of Photo: East Description: Pipe being lowered into the trench. Date: 06/26/2024





Line No. 1110 Loop Project

Location: Immediately north of MP 53+00 within additional temporary workspace. **Direction of Photo:**

West

Description: Water being delivered and stored in frac tanks for hydrostatic testing activities.

Date: 06/28/2024



Location: MP 105+00 **Direction of Photo:**

North

Description: Installation

of pig launcher assembly.

Date: 06/28/2024

