



June 16, 2026

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Attention: Ms. Debbie-Anne A. Reese, Secretary

Re: El Paso Natural Gas Company, L.L.C.;
Docket No. CP24-520-000
Maricopa Lateral Expansion Project
Weekly Environmental Inspector Report No. 28

Commissioners:

El Paso Natural Gas Company, L.L.C. (“EPNG”) is hereby filing with the Federal Energy Regulatory Commission (“Commission”) in Docket No. CP24-520-000, its weekly construction status report related to EPNG’s Maricopa Lateral Expansion Project (“Project”).

Description of Proceeding

On September 17, 2024, EPNG filed a prior notice request, pursuant to Section 7 of the Natural Gas Act (“NGA”) and Sections 157.205, 157.208 and 157.210 of the Commission’s Part 157 blanket certificate regulations, seeking authorization to construct, install and operate the new Haystack Compressor Station and appurtenances to be located in Yavapai County, Arizona.¹ The Project is designed to provide an additional 50,517 dekatherms per day of firm transportation service to Maricopa County, Arizona.

Submittal of Status Report

In compliance with Section 157.208(c)(10) of the NGA, EPNG is providing its Environmental Inspector Report No. 28.

¹ On October 1, 2024, the Commission issued a Notice of Request Under Blanket Authorization initiating the 60-day comment period. Protests to the Project were timely filed and not withdrawn during the reconciliation period. On July 24, 2025, the Commission issued an Order Denying Protest and Authorizing Construction under EPNG’s blanket certificate. See *El Paso Natural Gas Company, L.L.C.*, 192 FERC ¶ 61,078 (2025).

Filing Information

EPNG is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.

By _____ /s/
Francisco Tarin
Director, Regulatory

Enclosures

Cc: Ms. Sareh Poormahdi, OEP

Weekly Status Report No. 28		
Docket No. CP24-520-000		
Project Name:	Maricopa Lateral Expansion Project	
County/State:	Yavapai County, Arizona	Date: 6/16/2026
Reporting Period:	June 7, 2026 to June 13, 2026	
Environmental Inspector:	Bobby Kimball	
<p>1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD: During this period the contractor conducted the following:</p> <ul style="list-style-type: none"> (i) continued pipe fabrication, x-raying, blasting and painting of pipe in the trench and at tie-in locations; (ii) continued installing conduit, installing cable trays, and pulling wires between the new compressor and auxiliary buildings; (iii) continued bolt torquing and welding activities; (iv) continued backfilling activities as applicable; (v) continued pouring concrete for pipe supports and sleepers; and (vi) installed rip-rap at the channel bed and banks of the new access road. <p>2. RELEVANT ENVIRONMENTAL ACTIVITIES: During this reporting period, the environmental inspector completed training for six (6) new personnel. Dust mitigation activities continued as needed.</p> <p>3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN: No environmental problems or issues occurred during this reporting period.</p> <p>4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS: No environmental compliance issues or resolutions occurred during this reporting period.</p> <p>5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS: No landowner issues or concerns were identified during this reporting period.</p> <p>6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD: In the upcoming reporting period, the contractor plans to continue pipe fabrication, x-raying of piping, bolting up piping, running conduit, installing cable trays and wiring and backfilling as necessary. In addition, the contractor will continue to set forms and pour concrete where applicable, as well as installing pipe at the new compressor and inlet filter separator. Trench backfilling will continue where applicable.</p>		

Maricopa Lateral Expansion Project Photo Documentation

Location:
Haystack
Compressor
Station site.
**Direction of
Photo:**
South
Date;
6/8/26
Description:
Conduit set for
incoming
electricity.



Location:
Haystack
Compressor
Station site.
**Direction of
Photo:**
East
Date: 6/8/26
Description
Pulling cables
to the new
compressor
building.



Location:
Haystack
Compressor
Station site.
**Direction of
Photo:**
East
Date:
6/11/26
Description:
Contractor
torquing bolts.



Location:
Haystack
Compressor
Station site.
**Direction of
Photo:**
North
Date:
6/11/26
Description:
Dust mitigation
on site



Location:
Haystack
Compressor
Station site.
**Direction of
Photo:**
East
Date: 6/9/2026
Description:
Backfill of the
station
discharge line.



Location:
Haystack
Compressor
Station site.
**Direction of
Photo:**
Southwest
Date: 6/8/26
Description
Installed rip-
rap at the new
access road.



