

December 17, 2025

Federal Energy Regulatory Commission 888 First Street, N.E. Washington, D.C. 20426

Attention: Ms. Debbie-Anne A. Reese, Secretary

Re: El Paso Natural Gas Company, L.L.C.;

Docket No. CP24-520-000

Maricopa Lateral Expansion Project

Weekly Environmental Inspector Report No. 2

Commissioners:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP24-520-000, its first weekly construction status report related to EPNG's Maricopa Lateral Expansion Project ("Project").

Description of Proceeding

On September 17, 2024, EPNG filed a prior notice request, pursuant to Section 7 of the Natural Gas Act ("NGA") and Sections 157.205, 157.208 and 157.210 of the Commission's Part 157 blanket certificate regulations, seeking authorization to construct, install and operate the new Haystack Compressor Station and appurtenances to be located in Yavapai County, Arizona.¹ The Project is designed to provide an additional 50,517 dekatherms per day of firm transportation service to Maricopa County, Arizona.

Submittal of Status Report

In compliance with Section 157.208(c)(10) of the NGA, EPNG is providing its Environmental Inspector Report No. 2.

On October 1, 2024, the Commission issued a Notice of Request Under Blanket Authorization initiating the 60-day comment period. Protests to the Project were timely filed and not withdrawn during the reconciliation period. On July 24, 2025, the Commission issued an Order Denying Protest and Authorizing Construction under EPNG's blanket certificate. See *El Paso Natural Gas Company, L.L.C.*, 192 FERC ¶ 61,078 (2025).

Filing Information

EPNG is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.

By /s/
Francisco Tarin
Director, Regulatory

Enclosures

Cc: Ms. Sareh Poormahdi, OEP

Weekly Status Report No. 2		
Docket No. CP24-520-000		
Project Name:	Maricopa Lateral Expansion Project	
County/State:	Yavapai County, Arizona	Date: 12/17/2025
Reporting Period:	December 7, 2025 to December 13, 2025	
Environmental Inspector:	Bobby Kimball	

1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD:

During this reporting period, the contractor finished grading activities at the compressor station site and began the excavation for footings. Construction crews laid down rock gravel for the parking area, began fabrication of piping, constructed guard shacks and began constructing forms for footings and the rebar mats and related cages. Construction crews maintained access roads and oversaw the delivery of materials, tools, trailers, and storage containers. Dust control activities are ongoing and will continue through each reporting period as needed.

2. RELEVANT ENVIRONMENTAL ACTIVITIES:

During this reporting period, the Environmental inspector provided environmental training to twenty-six (26) project personnel.

3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN:

No environmental problems or issues occurred during this reporting period.

4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS:

No environmental compliance issues or resolutions occurred during this reporting period.

5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS:

No landowner issues or concerns were identified during this reporting period.

6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD:

During the next reporting period, the construction contractor plans to perform x-ray activities on initial welds, continue excavation for footings, set rebar mats and related cages in place, and fabricate concrete forms. In addition, the construction contractor will oversee the delivery of station piping, office trailers and related materials.

Maricopa Lateral Expansion Project Photo Documentation

Location:
Haystack
Compressor
Station site.
Direction of
Photo:
Northeast
Date: 12/9/25
Description:
Materials being
unloaded at

the site.



Location:
Haystack
Compressor
Station site.
Direction of
Photo:
North
Date:
12/8/2025
Description
Contractor
performing
dust control
activities.



El Paso Natural Gas Company, L.L.C.

Location: Haystack Compressor Station site. **Direction of** Photo: North Date: 12/10/2025 Description Contractor marking locations for footings on the new compressor station pad site.



Location: Haystack Compressor Station site. **Direction of** Photo: Northwest Date: 12/13/2025 **Description:** Contractor marking footing excavation locations on compressor station pad site.



El Paso Natural Gas Company, L.L.C.

Location:
Haystack
Compressor
Station site.
Direction of
Photo:
Northwest
Date:
12/13/2025
Description:
Contractor
fabricating
rebar mat.




Location:
Haystack
Compressor
Station site.
Direction of
Photo:
Northeast
Date:
12/13/2025
Description:
Contractor
excavating
footers.



Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 17th day of December 2025.



Two North Nevada Avenue Colorado Springs, Colorado 80903 (719) 667-7517