



El Paso Natural Gas
Company, L.L.C.
a Kinder Morgan company

October 9, 2026

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Attention: Ms. Debbie-Anne A. Reese, Secretary

Re: El Paso Natural Gas Company, L.L.C.;
Docket No. CP26-156-000
Permian West Expansion Project
Weekly Environmental Inspector Report No. 10

Dear Ms. Reese:

El Paso Natural Gas Company, L.L.C. ("EPNG") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP26-156-000; its weekly construction status report related to EPNG's Permian West Expansion Project ("Project").

Description of Proceeding

On March 27, 2026, EPNG submitted a Request for Prior Notice Authorization Pursuant to Blanket Certificate in the above-referenced docket seeking authorization to construct, install, operate and maintain an approximately nine-mile, 30-inch outside diameter pipeline loop extension and related appurtenances, located in Hudspeth County, Texas as part of its Project.¹ The Project is designed to provide additional firm transportation capacity on EPNG's Line No. 1100 system.

Submittal of Status Report

In compliance with Section 157.208(c)(10) of the NGA, EPNG is providing its Environmental Inspector Report No. 10.

¹ On April 6, 2026, the Commission issued a Notice of Request Under Blanket Authorization initiating the 60-day comment period that concluded on June 5, 2026.

Filing Information

EPNG is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Respectfully submitted,

EL PASO NATURAL GAS COMPANY, L.L.C.

By _____/s/_____
Francisco Tarin
Director, Regulatory

Enclosures

Cc. Ms. Kristen Trinh, OEP

El Paso Natural Gas Company, L.L.C. (EPNG)


EPNG's Weekly Environmental Inspection Report No. 10		
Docket No. CP26-156-000		
Project Name:	Permian West Expansion Project	
County/State:	Hudspeth County, Texas	Date: 10/9/2026
Reporting Period:	September 27, 2026 to October 3, 2026	
Environmental Inspector:	Casey McGaha	
1. SUMMARY OF CONSTRUCTION ACTIVITY FOR INSPECTION PERIOD: During this reporting period, the contractor conducted the following activities: (1) continued restoration and repair activities within affected areas of the ROW from the week 9 flooding event; (2) initiated efforts to improve ROW accessibility by installing wood mats in soft or saturated areas to maintain safe vehicle and equipment access; (3) performed maintenance and repair of erosion control devices along ROW to ensure functionality and effectiveness; (4) continued welding operations along the right-of-way ("ROW"); (5) continued sandblasting and pipe coating operations; (6) continued trenching operations; and (7) continued lowering pipe into the trench. 2. RELEVANT ENVIRONMENTAL ACTIVITIES: During this reporting period, there were no new personnel on site and, therefore, the environmental inspector did not complete training for any new personnel. The environmental inspector conducted stormwater pollution prevention-related inspections and inspected all work areas each day for the presence of sensitive species. No sensitive species were observed. 3. ENVIRONMENTAL PROBLEMS/ISSUES AND CORRECTIVE ACTIONS TAKEN: No environmental problems or issues occurred during this reporting period. 4. ENVIRONMENTAL COMPLIANCE ISSUES/RESOLUTIONS: No environmental compliance issues or resolutions occurred during this reporting period. 5. ISSUES AND CONCERNS IDENTIFIED BY LANDOWNERS: No landowner issues or concerns were identified during this reporting period. 6. WORK PLANNED FOR THE FOLLOWING REPORTING PERIOD: During the next reporting period, the contractor will continue storm-related erosion control repairs, ROW stabilization, and restoration of areas. Construction activities will include welding, sandblasting, coating, trenching, pipe lowering, backfilling, and associated ROW maintenance activities.		

Permian West Expansion Project Photo Documentation

Location: Project ROW near MP 3.5.
Direction of Photo: Northeast
Date: 9/28/26
Description: Pipeline sandblasting operations.



Location: Project right-of-way near MP 5.
Direction of Photo: East
Date: 9/28/26
Description: Preparing to lower pipeline into trench.



Location: Project right-of-way near MP 8.

Direction of Photo: Southeast

Date: 9/30/2026

Description:
Regrading the ROW as part of rain event repairs.



Location: Access road near MP 8.

Direction of Photo: Southwest

Date: 9/30/26

Description:
Timber mats installed to allow for travel along ROW as part of efforts to improve accessibility following the rain event.



El Paso Natural Gas Company, L.L.C. (EPNG)

Location: Project right-of-way near MP 4.5.

Direction of Photo: East

Date: 10/1/26

Description: Pipeline trenching activities.



Location: Project right-of-way near MP 6.

Direction of Photo: West

Date: 10/1/26

Description: Crews repairing erosion control devices damaged by the rain event.



Location: A Project right-of-way near MP 8.

Direction of Photo: West

Date: 10/2/26

Description:
Moving pipe that floated out of the ditch during the rain event.



Location: Project right-of-way near MP 9.

Direction of Photo: Northeast

Date: 10/2/26

Description: Crews repairing erosion control devices along the ROW damaged by the rain event.



Location: Project right-of-way near MP 3.
Direction of Photo: West
Date: 10/3/26
Description: Pipeline coating activities.



Location: Project right-of-way near MP 6.5.
Direction of Photo: East
Date: 10/3/26
Description: Crews lowering pipeline into trench.



Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 9th day of October 2026.

/s/

Francisco Tarín

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517