

# El Paso Pipeline Maintenance Summary

This document lists major maintenance and construction shutdowns that are being planned on the EPNG pipeline system for the next 12 to 15 months. The purpose of this posting is to make customers aware of **proposed outages** that will affect throughput on the various systems of the pipeline. Dates may change based on changing business conditions or to coordinate with outages on interconnecting pipelines. **Comments regarding alternate dates are welcome.**

**This document is not intended to be an official notice. When shutdowns are finalized, they will be posted as Informational Postings, found on the El Paso Natural Gas Company Home Page. Refer to those notices for current shutdowns.**

This Shutdown Schedule will normally be updated weekly or by special edition if warranted. Please refer to the revision date.

## El Paso Natural Gas Co. Shutdown Schedule

dates are tentative and subject to change. See EBB notices for finalized dates and impacts.



Revised: 5/20/2019

Questions? Contact Vic Villalva 719-520-4251

**\*\*Possible immediate remediation - a placeholder on the schedule for possible outage for immediate remediation based on an ILI (inline inspection, smart pig) assessment report. The outage (remediation) may or may not take place depending on the report findings. If the report states that an immediate remediation must take place, EPNG will post an update for the impact to the system as soon as possible. TBD (To Be Determined)**

SJ= San Juan Basin - NM=North ML - SM=South ML - XO=San Juan Crossover - PR=Permian YU=Yuma - PHX=Phoenix - HX=Havasus Crossover - AN=Anadarko						
Start Date	End Date	Location	Unit	Description	Reduction in MMcf/d	System
11/7/2013	12/31/2019	WINDOW ROCK	3A	Window Rock 3A repair pending	22	NM
11/11/2013	6/28/2019	CAPROCK	1A	Caprock 1A mechanical repair pending	50	XO
1/1/2014	12/31/2019	AFTON STA	2A	Afton 2 mechanical repair pending	65	SM
6/10/2014	12/31/2019	AFTON STA	1A	Afton 1 repair pending	65	SM
1/5/2015	12/31/2019	VAIL STA	1,2,3	Vail Station repair pending	18	SM
7/21/2015	12/31/2019	WILLIAMS	4B	Williams 4B repair pending	10	NM
12/1/2015	12/31/2019	LEUPP	1A	Leupp 1A repair pending	7	NM
12/1/2015	12/31/2019	LEUPP	7A	Leupp 7A mechanical repair pending	7	NM
1/1/2016	12/31/2019	EL PASO D	2D	El Paso 2D repair pending	0	SM
2/26/2016	9/30/2019	LEUPP	6A	Leupp 6A repair pending	10	NM

8/4/2016	12/31/2019	MONUMENT STA	1B	Monument 1B Repair Pending	20	SM
11/30/2016	12/31/2020	SAN SIMON STA	3A	San Simon 3 repair pending	50	SM
12/16/2016	12/31/2019	WINDOW ROCK	1A	Window Rock 1A repair pending	22	NM
9/8/2017	12/31/2019	LEUPP	9A	Leupp 9A repair pending	10	NM
11/6/2018	12/31/2019	WINDOW ROCK	1B	Window Rock 1B repair pending	37	NM
1/9/2019	5/31/2019	CASA GRANDE	1A	Casa Grande 1A repair	65	SM
4/25/2019	6/24/2019	BELEN	2A	Belen 2A repair	70	XO
5/6/2019	6/3/2019	TOPOCK-MOJAVE	1200	Line 1200 pipeline remediation Seligman to Hackberry	89	NM
5/6/2019	6/7/2019	HUECO STA	2A	Hueco 2A maintenance	80	SM
5/17/2019	5/27/2019	Flag-West-PL	1204	Line 1204 pipeline remediation Flagstaff to Williams	157	NM
5/21/2019	5/22/2019	DAGGETT STA	STA	Daggett Station Annual ESD/DOT Test	58	MOJ
5/21/2019	5/24/2019	PECOS RIVER STA	STA	Pecos Station Annual DOT/ESD Test	150	SM
5/21/2019	5/24/2019	WENDEN STA	1A	Wenden 1A inspection	39	HX
5/21/2019	5/24/2019	EL PASO D	D	El Paso Station D DOT/ESD Test	92	SM
5/21/2019	5/24/2019	WINDOW ROCK	5B	Window Rock 5B inspection	23	NM
5/22/2019	5/22/2019	WENDEN STA	STA	Wenden Station Annual DOT/ESD Test	175	HX
5/22/2019	5/22/2019	SAN JUAN PL	1202	Line 1202 pipeline maintenance MLV 0 to MLV 1/2 TW La Plata 30 Inch (INWPLBLA) PIN 314347 & Milagro Plant (IMILAGRO) PIN 314348 shut in	0	SJ
5/25/2019	5/25/2019	ROSWELL PL	1300	L1300 smart pig Lincoln to Belen	110	XO
5/28/2019	5/29/2019	ORACLE STA	STA	Oracle Station DOT/ESD Test	94	SM
5/28/2019	6/1/2019	WINDOW ROCK	5A	Window Rock 5A maintenance	37	NM
5/28/2019	5/31/2019	BONDAD	1A	Bondad 1A maintenance	95	SJ
5/28/2019	6/30/2019	LEUPP	5B	Leupp 5B maintenance		NM
6/3/2019	6/8/2019	WINDOW ROCK	6A	Window Rock 6A maintenance	37	NM
6/3/2019	6/10/2019	PUCKETT	1A	Puckett Station DOT/ESD Test gas from ITERRELL, IMLTERPK and IYUCBUTE must be routed to Wink thru Line 2000 instead of Waha and will be limited to a total of 98,000 Dthd.	135	SM
6/4/2019	6/4/2019	SAN JUAN PL	1205	Line 1205 maintenance pig Bondad to MLV 3 3/4 higher pressures	0	SJ
6/4/2019	6/4/2019	ROSWELL PL	1300	Line 1300 smart pig Lincoln to Belen	110	XO
6/4/2019	6/5/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	117	MOJ
6/4/2019	6/6/2019	BLUEWATER	STA	Blue Water Station Annual DOT/ESD Test	90	XO

6/5/2019	6/5/2019	SAN JUAN PL	1218	Line 1218 maintenance pig MLV 3 1/2 to MLV 3 3/4 higher pressures	0	SJ
6/6/2019	6/6/2019	GALLUP-SAN JUAN PL	L1301	Line 1301 smart pig Belen to Bluewater	30	XO
6/7/2019	6/7/2019	ROSWELL PL	1300	Line 1300 smart pig Lincoln to Belen	110	XO
6/10/2019	6/10/2019	Flag-West-PL	1200	Line 1200 cleaning/gauge pig Dilkon to Flagstaff	14	NM
6/10/2019	6/14/2019	WASHINGTON RANCH	STA	Washington Ranch Spring BHP Survey No injection or withdrawal	250	SM
6/11/2019	6/11/2019	Flag-West-PL	1200	Line 1200 smart pig Dilkon to Flagstaff	14	NM
6/11/2019	6/11/2019	DUMAS EAST PL	STAA	Dumas Station Annual DOT/ESD Test	50	AN
6/11/2019	6/13/2019	WINDOW ROCK	3B	Window Rock 3B maintenance	37	NM
6/11/2019	6/13/2019	MOJAVE STA	2A	Mojave 2A inspection	117	MOJ
6/11/2019	6/14/2019	HUECO STA	STA	Hueco Station Annual ESD/DOT Test & Unit shut down checks	70	SM
6/12/2019	6/12/2019	GALLUP-SAN JUAN X PL	L1301	Line 1301 smart pig Belen to Bluewater	30	XO
6/12/2019	6/12/2019	DAGGETT STA	STA	Daggett Station maintenance	0	MOJ
6/13/2019	6/13/2019	GALLUP-SAN JUAN X PL	L1301	Line 1301 smart pig Belen to Bluewater	30	XO
6/14/2019	6/14/2019	GALLUP-SAN JUAN X PL	L1301	Line 1301 smart pig Belen to Bluewater	30	XO
6/14/2019	6/14/2019	Flag-West-PL	1200	Line 1200 smart pig Dilkon to Flagstaff	14	NM
6/15/2019	6/15/2019	Flag-West-PL	1200	Line 1200 smart pig Flagstaff to Seligman	7	NM
6/16/2019	6/28/2019	GALLUP-SAN JUAN X MEAS	1300	Line 1300 pipeline remediation Blue Water to Valve City	43	XO
6/17/2019	6/26/2019	SAN JUAN PL	1200	Line 1200 Hydro Test MLV 0 to EOL CCI/EPNG (ISJRVPLT) San Juan River Pin 314603 will go to zero	0	SJ
6/18/2019	6/28/2019	FLORIDA STA	1C	Florida 1C repair	52	SM
6/18/2019	6/18/2019	Flag-West-PL	1200	Line 1200 smart pig Flagstaff to Seligman	7	NM
6/18/2019	6/19/2019	HACKBERRY STA	STA	Hackberry unit maintenance	85	NM
6/18/2019	6/18/2019	CARLSBAD PIPE	1110	Line 1110 Hot Tap Pecos to MLV 9	44	SM
6/18/2019	6/20/2019	GRESHAM	STA	Gresham Station Annual DOT/ESD Test	66	SM
6/18/2019	7/1/2019	TOPOCK-MOJAVE	1204	Line 1204 pipeline remediation Seligman to Hackberry	449	NM
6/19/2019	6/19/2019	CARLSBAD PIPE	1103	Line 1103 Hot Tap Pecos to MLV 9	44	SM
6/20/2019	6/20/2019	Flag-West-PL	1200	Line 1200 smart pig Flagstaff to Seligman	7	NM
6/25/2019	6/27/2019	AFTON STA	STA	Afton Station Annual DOT/ESD Test	65	SM
6/25/2019	6/25/2019	SAN JUAN	STA	San Juan Station DOT/ESD Test	30	SJ

6/25/2019	6/25/2019	Flag-West-PL	1200	Line 1200 smart pig Flagstaff to Seligman	7	NM
6/25/2019	6/28/2019	KEYSTONE	11A	Keystone 11A inspection	44	PR
6/25/2019	6/28/2019	KEYSTONE	5A	Keystone 5A inspection	40	PR
6/27/2019	6/27/2019	Flag-West-PL	1200	Line 1200 smart pig Flagstaff to Seligman	7	NM
6/29/2019	7/19/2019	GALLUP-SAN JUAN X PL	1300	Line 1300 pipeline remediation Blue Water to Valve City	43	XO
7/1/2019	7/1/2019	TOPOCK-MOJAVE	1204-1113	Line 1204 smart pig Hackberry to Franconia	155	NM
7/2/2019	7/2/2019	TOPOCK-MOJAVE	1204-1113	Line 1204 smart pig Hackberry to Franconia	155	NM
7/2/2019	7/15/2019	TOPOCK-MOJAVE	1204	Line 1204 pipeline remediation Seligman to Hackberry	TBD	NM
7/3/2019	7/3/2019	TOPOCK-MOJAVE	1204-1113	Line 1204 smart pig Hackberry to Franconia	155	NM
7/6/2019	7/6/2019	TOPOCK-MOJAVE	1204-1113	Line 1204 smart pig Hackberry to Franconia	155	NM
7/9/2019	7/9/2019	SAN JUAN PL	1212	Line 1212 maintenance pig pressures will be higher Blanco	0	SJ
7/9/2019	7/9/2019	Flag-West-PL	1204	Line 1204 smart pig Leupp to Flagstaff	47	NM
7/9/2019	7/10/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	117	MOJ
7/9/2019	7/12/2019	WINDOW ROCK	4B	Window Rock 4B maintenance	23	NM
7/9/2019	7/11/2019	WHITE ROCK	STA	White Rock Station DOT/ESD Test	259	SJ
7/9/2019	7/15/2019	KEYSTONE	4A	Keystone 4A inspection	37	PR
7/9/2019	7/15/2019	Flag-West-PL	1200	Line 1200 pipeline remediation MLV 31 to Williams	0	NM
7/9/2019	9/20/2019	ODESSA PL	1105	Line 1105 hydro test MP 51 to Keystone following locations shut in required Razor Sharp Delivery (DRZRSHRP),Hogg Delivery (DHOGGDEL), Targa - WADDELL PLANT Receipt (IWARWADD),DCP - Dune Booster Delivery (DPHIL311)and ETC - SOUTH KERMIT Fuel Gas Delivery (DKERMFUL)	233	PR
7/10/2019	7/10/2019	SAN JUAN PL	1212	Line 1212 maintenance pig VLV 1 to VLV 3 1/2 pressures will be higher	0	SJ
7/10/2019	12/31/2019	KEYSTONE	7A	Keystone 7A inspection	40	PR
7/11/2019	7/11/2019	Flag-West-PL	1204	Line 1204 smart pig Leupp to Flagstaff	47	NM
7/16/2019	7/18/2019	MOJAVE STA	3A	Mojave Unit 3A inspection	117	MOJ
7/17/2019	7/18/2019	ODESSA PL	3082	Line 3082 maintenance pig Goldsmith to Keystone Field	0	PR
7/17/2019	7/17/2019	LINCOLN	STA	Lincoln Station Annual DOT/ESD Test	70	XO
7/17/2019	10/23/2019	KEYSTONE	3A	Keystone 3A inspection	37	PR
7/20/2019	7/26/2019	GALLUP-SAN JUAN X MEAS	1300	Line 1300 pipeline remediation Blue Water to Valve City	43	XO
7/23/2019	7/23/2019	Flag-West-PL	1204	Line 1204 smart pig MLV 31 to Williams	30	NM
7/23/2019	7/24/2019	LEUPP	2A	Leupp 2A inspection	8	NM

7/23/2019	7/26/2019	WINDOW ROCK	5B	Window Rock 5B maintenance	23	NM
7/23/2019	7/23/2019	SAN JUAN PL	1205	Line 1205 ILI Cleaning Bondad to MLV 3 3/4 higher pressures	70	SJ
7/26/2019	10/30/2019	KEYSTONE	12A	Keystone 12A inspection	40	PR
7/30/2019	7/30/2019	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	PR
8/1/2019	8/2/2019	BELEN	STA	Belen Station Annual DOT/ESD Test	70	XO
8/5/2019	8/5/2019	Flag-West-PL	1201	Line 1201 smart pig Dilkon to Flagstaff	161	NM
8/6/2019	8/6/2019	Flag-West-PL	1201	Line 1201 smart pig Dilkon to Flagstaff	161	NM
8/6/2019	8/8/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	117	MOJ
8/6/2019	8/6/2019	SAN JUAN PL	1219	Line 1219 maintenance pig Chaco to White Rock	0	SJ
8/6/2019	8/9/2019	WINDOW ROCK	5A	Window Rock 5A inspection	22	NM
8/6/2019	8/9/2019	KEYSTONE	6A	Keystone 6A inspection	33	PR
8/7/2019	8/7/2019	SAN JUAN PL	1202	Line 1202 maintenance pig Blanco to White Rock pressures will be higher	0	SJ
8/8/2019	8/8/2019	Flag-West-PL	1201	Line 1201 smart pig Dilkon to Flagstaff	161	NM
8/8/2019	8/9/2019	LAGUNA	STA	Laguna Station Annual DOT/ESD Test	97	XO
8/12/2019	8/12/2019	SAN JUAN PL	1205	Line 1205 ILI tool Bondad to MLV 3 3/4 higher pressures	70	SJ
8/12/2019	8/16/2019	AMARILLO	1A	Amarillo 1A repair	40	AN
8/13/2019	8/14/2019	LEUPP	5B	Leupp 5B inspection	20	NM
8/20/2019	8/20/2019	Flag-West-PL	1204	Line 1200 smart pig MLV 31 to Williams	30	NM
8/20/2019	8/21/2019	LEUPP	10A	Leupp 10A inspection	10	NM
8/20/2019	8/23/2019	WINDOW ROCK	2B	Window Rock 2B inspection	13	NM
8/23/2019	8/23/2019	Flag-West-PL	1204	Line 1200 smart pig MLV 31 to Williams	30	NM
8/27/2019	8/28/2019	LEUPP	2B	Leupp 2B inspection	10	NM
8/27/2019	8/29/2019	PECOS RIVER STA	3A	Pecos River 3 inspection	32	SM
8/27/2019	8/29/2019	PLAINS STA	STA	Station DOT/ESD Test deliveries cannot be made to INN30PLA, IW40-043, or IMUSTANG; during this outage, no gas can be received at INN26PLA.	762	AN
8/28/2019	8/28/2019	CASA GRANDE	1C	Casa Grande 1C inspection	114	SM
9/4/2019	9/5/2019	LEUPP	3A	Leupp 3A inspection	2	NM
9/4/2019	10/29/2019	WILLCOX STA	2A	Willcox 2A repair	99	SM
9/5/2019	9/12/2019	WASHINGTON RANCH	STA	Washington Ranch Fall BHP Survey no injection or withdrawal	250	SM
9/6/2019	9/6/2019	ODESSA PL	1115	Line 1115 maintenance pig Goldsmith to L1102	0	PR
9/10/2019	9/12/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	117	MOJ
9/10/2019	9/10/2019	ALAMO LAKE STA	1A	Alamo Lake 1A inspection	75	HX

9/10/2019	9/10/2019	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	PR
9/10/2019	9/13/2019	CORNUDAS STA	2A	Cornudas 2A inspection	80	SM
9/10/2019	9/13/2019	WINDOW ROCK	4B	Window Rock 4B inspection	15	NM
9/17/2019	9/17/2019	CIMARRON STA	1	Cimarron 1 inspection	88	SM
9/17/2019	9/18/2019	LEUPP	5A	Leupp 5A inspection	2	NM
9/17/2019	9/20/2019	KEYSTONE	STA	Keystone Station Annual DOT/ESD Test	611	PR
9/17/2019	9/17/2019	ODESSA PL	3028	Line 3028 maintenance pig Goldsmith to Keystone Field	0	PR
9/17/2019	9/17/2019	ODESSA PL	3161	Line 3161 maintenance pig Mobil Coyanosa to Waha	0	PR
9/17/2019	9/19/2019	HACKBERRY STA	1A	Hackberry 1 inspection	66	NM
9/17/2019	9/20/2019	PECOS RIVER STA	2A	Pecos 2A inspection	110	SM
9/19/2019	9/19/2019	ODESSA PL	3146	Line 3146 maintenance pig Puckett to Line 1105	0	PR
9/24/2019	9/25/2019	LEUPP	1B	Leupp 1B inspection	10	NM
9/24/2019	9/24/2019	TUCSON	2000	L2000 smart pig Cimarron to Tom Mix		SM
9/24/2019	9/24/2019	EL PASO D	4D	El Paso 4D inspection	42	SM
9/26/2019	9/27/2019	ODESSA PL	3173	Line 3153 maintenance pig Terrell to Puckett	0	PR
9/30/2019	10/27/2019	BAKERSFIELD AREA	1905	Line 1104 smart pig Franconia to Alamo Lake	TBD	NM
10/1/2019	10/3/2019	KEYSTONE	8A	Keystone 8A inspection	35	PR
10/1/2019	10/4/2019	WINDOW ROCK	2A	Window Rock 2A inspection	22	NM
10/2/2019	10/2/2019	ROSWELL	STA	Roswell Station Annual DOT/ESD Test	65	XO
10/2/2019	10/2/2019	BLACK RIVER	1	Black River 1 inspection	119	SM
10/5/2019	10/10/2019	TUCSON	1100	L1100 smart Pig San Simon to Benson	63	SM
10/7/2019	10/11/2019	DIMMITT STA	2A	Dimmitt 2A inspection	30	AN
10/8/2019	10/10/2019	PICACHO STA	1,2,3A	Picacho Station Annual DOT/ESD Test	0	PHX
10/8/2019	10/10/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	117	MOJ
10/8/2019	10/11/2019	WINDOW ROCK	6A	Window Rock 6A inspection	37	NM
10/8/2019	10/11/2019	GUADALUPE STA	STA	Guadalupe Station DOT/ESD Test	160	SM
10/11/2019	10/11/2019	TUCSON	1100	Line 1100 smart pig San Simon to Benson	106	SM
10/13/2019	10/14/2019	TUCSON	1100	Line 1100 smart pig San Simon to Benson	106	SM
10/14/2019	10/21/2019	TOPOCK-MOJAVE	1113	Line 1204/1113 Hydro Test Franconia to MLV 13	378	NM
10/15/2019	10/18/2019	KEYSTONE	2A	Keystone 2A inspection	44	PR
10/15/2019	10/15/2019	WINK	STA	Wink Station Annual DOT/ESD Test	268	SM

10/15/2019	10/15/2019	DUTCH FLATS STA	1A	Dutch Flats 1A shut down checks	30	HX
10/16/2019	10/16/2019	ODESSA PL	1103	Line 1103 smart pig Guadalupe to Cornudas	0	PR
10/16/2019	10/16/2019	DUTCH FLATS STA	2A	Dutch Flats 2A shut down checks	33	HX
10/16/2019	10/16/2019	BONDAD	2A	Bondad 2A inspection	95	SJ
10/17/2019	10/17/2019	DUTCH FLATS STA	STA	Dutch Flats Station Annual DOT/ESD Test	107	HX
10/17/2019	10/17/2019	BONDAD	1B	Bondad 1B inspection	95	SJ
10/21/2019	10/25/2019	BONDAD	1A	Bondad 1A inspection	95	SJ
10/22/2019	10/22/2019	PLAINS PL	30125	Line 30125 smart pig Jal to Eunice Jal 3 (IJALCPLX), Jal Alley(DJALALLY) , Dollarhide (IUTDOLHD), Grobe (ITXGROBE) , Meyers(DTEX JAL). pressures will be higher during pig run	0	PR
10/22/2019	10/25/2019	KEYSTONE	2B	Keystone 2B inspection	70	PR
10/24/2019	10/24/2019	PLAINS PL	30125	Line 3026/30125 smart pig Keystone to Eunice Jal 3 (IJALCPLX), Jal Alley(DJALALLY) , Dollarhide (IUTDOLHD), Grobe (ITXGROBE) , Meyers(DTEX JAL) pressures will be higher during pig run	0	PR
10/31/2019	10/31/2019	ODESSA PL	2000	Line 2000 maintenance pig Black River to Guadalupe	0	PR
11/1/2019	11/1/2019	ODESSA PL	3173	Line 3173 maintenance pig Puckett to Waha	0	PR
11/4/2019	11/4/2019	ODESSA PL	3160	Line 3160 maintenance pig Mobil Coyanosa to Waha	0	PR
11/5/2019	11/7/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	117	MOJ
11/5/2019	11/5/2019	WENDEN STA	2A	Wenden 2A inspection	39	HX
11/5/2019	11/7/2019	FLORIDA STA	2A	Florida 2A inspection	22	SM
11/5/2019	11/8/2019	WINDOW ROCK	6B	Window Rock 6B inspection	37	NM
11/5/2019	11/17/2019	EHRENBERG	1100	Line 1100 pipeline replacement	0	SM
11/6/2019	11/6/2019	TOM MIX STA	1A	Tom Mix 1A inspection	43	SM
11/12/2019	11/13/2019	ORACLE STA	1	Oracle 1 inspection	105	SM
11/19/2019	11/19/2019	LORDSBURG STA	1C	Lordsburg 1C inspection	42	SM
12/2/2019	12/6/2019	KEYSTONE	9AA	Keystone 9A inspection	37	PR
12/3/2019	12/4/2019	BOWIE STA	1	Bowie 1 inspection	38	SM
12/3/2019	12/5/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	117	MOJ
12/3/2019	12/5/2019	FLORIDA STA	1A	Florida 1A inspection	22	SM
12/10/2019	12/11/2019	TOM MIX STA	2A	Tom Mix 2 inspection	43	SM
12/10/2019	12/10/2019	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	SM
12/10/2019	12/12/2019	KEYSTONE	10A	Keystone 10A inspection	40	PR
12/12/2019	12/12/2019	ODESSA PL	3114	L3114 maintenance pig higher pressures	0	PR
12/15/2019	12/31/2019	KEYSTONE	10A	Keystone 10A inspection	40	PR

12/17/2019	12/17/2019	DUTCH FLATS STA	2A	Dutch Flats 2A inspection	33	HX
12/17/2019	12/17/2019	CORNUDAS STA	1C	Cornudas 1C inspection	42	SM
12/18/2019	12/18/2019	CORNUDAS STA	2C	Cornudas 2C inspection	42	SM
12/23/2019	12/31/2019	KEYSTONE	1B	Keystone 1B inspection	45	PR
12/27/2019	12/27/2019	ODESSA PL	3114	Line 3105/3104 maintenance pig to Sweetie Peck Junction	0	PR
12/27/2019	12/27/2019	ODESSA PL	3137	Line 3137 maintenance pig Benedum to Sweetie Peck higher pressures	0	PR
12/31/2019	12/31/2019	ODESSA PL	3133	Line 3133 maintenance pig Sweetie Peck to Goldsmith	0	PR