

El Paso Pipeline Maintenance Summary


This document lists major maintenance and construction shutdowns that are being planned on the EPNG pipeline system for the next 12 to 15 months. The purpose of this posting is to make customers aware of **proposed outages** that will affect throughput on the various systems of the pipeline. Dates may change based on changing business conditions or to coordinate with outages on interconnecting pipelines. **Comments regarding alternate dates are welcome.**

This document is not intended to be an official notice. When shutdowns are finalized, they will be posted as Informational Postings, found on the EPNG Pipeline Company Home Page. Refer to those notices for current shutdowns.

This Shutdown Schedule will normally be updated weekly or by special edition if warranted. Please refer to the revision date.

El Paso Natural Gas Co. Shutdown Schedule

All dates are tentative and subject to change. See EBB Maintenance notices for finalized dates and impacts.



Revised: 9/23/2020

Questions? Call Vic Villalva 719-520-4251

EPNG will post an update for the impact to the system as soon as possible.TBD (To Be Determined)

Start Date	End Date	Location	Unit	Description	Reduction in MMcf/d	System
11/7/2013	12/31/2020	WINDOW ROCK	3A	Window Rock 3A repair pending	22	NM
1/5/2015	12/31/2020	VAIL STA	1,2,3	Vail Station repair pending	18	SM
7/21/2015	12/31/2020	WILLIAMS	4B	Williams 4B repair pending	10	NM
12/1/2015	12/31/2020	LEUPP	1A	Leupp 1A repair pending	7	NM
12/1/2015	12/31/2020	LEUPP	7A	Leupp 7A mechanical repair pending	7	NM
1/1/2016	12/31/2020	EL PASO D	2D	El Paso 2D repair pending	0	SM
8/4/2016	12/31/2020	MONUMENT STA PL	1B	Monument 1B Repair Pending	20	SM

11/30/2016	12/31/2020	SAN SIMON STA	3A	San Simon 3 repair pending	50	SM
9/8/2017	12/31/2020	LEUPP	9A	Leupp 9A repair pending	10	NM
11/6/2018	12/31/2020	WINDOW ROCK	1B	Window Rock 1B repair pending	37	NM
12/2/2018	10/31/2021	DUMAS SOUTH PL	1	Dimmitt 1 repair pending	40	AN
12/31/2019	12/31/2021	KEYSTONE	3A	Keystone 3A repair pending	37	PR
6/11/2020	10/30/2020	LINCOLN	1	Lincoln Unit 1 maintenance	158	XO
6/18/2020	10/16/2020	KEYSTONE	2A	Keystone 2A repair	40	PR
6/19/2020	12/31/2020	WAHA STA	1,2,3,4	WAHA Solar Units 1,2,3 ,4 repair	146	PR
6/22/2020	10/30/2020	LEUPP	1B	Leupp 1B repair	10	NM
6/30/2020	9/20/2020	PHOENIX	1100	Line 1100 pipeline remediation Casa Grande to Wenden	94	SM
7/21/2020	12/17/2020	SAN SIMON STA	3A	San Simon 3A maintenance	39	SM
9/1/2020	10/31/2020	PHOENIX	1100	Line 1100 pipeline remediation Casa Grande to Wenden	251	SM
9/10/2020	10/30/2020	PLAINS STA	15A	Plains Unit 15A repair	0	SM
9/11/2020	10/5/2020	EL PASO C	1C	El Paso 1C repair	39	SM
9/14/2020	9/30/2020	PLAINS STA	7	Plains 7 repair	12	SM
9/22/2020	9/24/2020	HUECO STA	2A	Hueco 2A inspection	22	SM
9/22/2020	9/24/2020	WINDOW ROCK	2B	Window Rock 2B inspection	13	NM
9/23/2020	9/24/2020	ALAMO LAKE STA	1A	Alamo Lake 1A repair	75	HX
9/24/2020	9/24/2020	EHRENBERG	1100	Line 1100 smart pig Wenden to Ehrenbug	220	SM
9/24/2020	9/25/2020	DILKON	ALL	Dilkin "A & B" Station maintenance	294	NM
9/26/2020	9/26/2020	EHRENBERG	1100	Line 1100 smart pig Wenden to Ehrenbug	220	SM
9/29/2020	9/29/2020	ALAMO LAKE STA	2A	Alamo Lake 2A repair	59	HX
9/29/2020	9/29/2020	Dragoon Sta	1A	Dragoon Station repair	128	SM
9/29/2020	9/29/2020	Sierrita Gas	STA	Sierrita Station maintenance PIN 47698 GSDEAGU/SIERRITA SASABE PIMA delivery psig during this maintenance may be below 740 psig	201	SGPL
9/29/2020	10/2/2020	MOJAVE STA	3A	Mojave 3A maintenance	117	MOJ
9/29/2020	10/30/2020	FLORIDA STA	2A	Florida 2A maintenance	22	SM
9/30/2020	9/30/2020	ROSWELL	STA	Roswell Station DOT/ESD Test	65	XO
10/5/2020	10/9/2020	DUMAS SOUTH PL	4A	Dimmit 4A inspection	40	AN
10/6/2020	10/6/2020	GALLUP-SAN JUAN X MEAS	L1300	Line 1300 smart pig Belen to Laguna	250	XO
10/6/2020	10/7/2020	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
10/6/2020	10/6/2020	ALAMO LAKE STA	1A	Alamo Lake 1A inspection	75	HX

10/6/2020	10/8/2020	DIMMITT STA	STA	Dimmitt Station maintenance	65	AN
10/6/2020	10/8/2020	PLAINS STA	STA	Plain Station DOT/ESD Test deliveries cannot be made to INN30PLA, IW40-043, or IMUSTANG; during this outage, no gas can be received at INN26PLA.	762	AN
10/6/2020	10/9/2020	WINDOW ROCK	6A	Window Rock 6A inspection	37	NM
10/6/2020	10/9/2020	GUADALUPE STA	STA	Guadalupe Station DOT/ESD Test	160	SM
10/6/2020	10/9/2020	LORDSBURG STA	1A	Lordsburg 1A maintenance	30	SM
10/12/2020	10/12/2020	FLAGSTAFF - PL	1208	Line 1208 smart pig Navajo to Dilkon	47	NM
10/12/2020	10/15/2020	FLAGSTAFF - PL	1204	Line 1204 pipeline remediation Navajo to Dilkon	223	NM
10/13/2020	10/15/2020	WILLCOX STA	1A	Willcox 1A inspection	130	SM
10/13/2020	10/13/2020	DUTCH FLATS STA	1A	Dutch Flats 1A shut down checks	33	HX
10/13/2020	10/15/2020	WINK	STA	Wink Station DOT/ESD Test	268	SM
10/13/2020	10/16/2020	WINDOW ROCK	1A	Window Rock 1A inspection	37	NM
10/13/2020	10/16/2020	LORDSBURG STA	2A	Lordsburg 2A maintenance	30	SM
10/13/2020	10/19/2020	ODESSA PL	L1106	Line 1106 smart pigging MLV 0 to EOL Edward Plant and Joyce Plant to Zero	128	PR
10/13/2020	11/10/2020	EP W DIST	1103	Line 1103 pipeline hydro test El Paso to Afton	500	SM
10/14/2020	10/14/2020	FLAGSTAFF - PL	1208	Line 1208 smart pig Navajo to Dilkon	611	NM
10/14/2020	10/14/2020	DUTCH FLATS STA	2A	Dutch Flats 2A shut down checks	33	HX
10/15/2020	10/15/2020	DUTCH FLATS STA	STA	Dutch Flats Station Annual DOT/ESD Test	107	HX
10/15/2020	10/15/2020	FLAGSTAFF - PL	1208	Line 1208 smart pig Navajo to Dilkon	47	NM
10/16/2020	10/20/2020	FLAGSTAFF - PL	1204	Line 1204 pipeline remediation Navajo to Dilkon	611	NM
10/20/2020	10/20/2020	CADIZ	METER	Cadiz Meter Station maintenance	250	NM
10/20/2020	10/21/2020	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
10/20/2020	10/22/2020	SELIGMAN	C	Seligman 1C inspection	419	NM
10/20/2020	10/20/2020	BONDAD	1A	Bondad 1A inspection	95	SJ
10/20/2020	10/20/2020	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	PR
10/21/2020	10/21/2020	ODESSA PL	3114	Line 3105/3104 maintenance pig to Sweetie Peck Junction	0	PR

10/21/2020	10/23/2020	FLAGSTAFF - PL	1204	Line 1204 pipeline remediation Navajo to Dilkon	331	NM
10/26/2020	10/30/2020	WINDOW ROCK	B	Window Rock 3B maintenance	208	NM
10/27/2020	10/27/2020	EP W DIST	1136	Line 2000 smart pig Afton to Lordsburg	375	SM
10/27/2020	10/29/2020	HACKBERRY STA	2A	Hackberry 2 inspection	66	NM
10/27/2020	10/29/2020	LORDSBURG STA	2A	Lordsburg 2A inspection	22	SM
10/27/2020	10/30/2020	KEYSTONE	12A	Keystone 12A inspection	40	PR
10/28/2020	10/28/2020	BELEN		Belen Station maintenance	242	XO
10/28/2020	10/28/2020	ODESSA PL	3137	Line 3137 maintenance pig Benedum to Sweetie Peck higher pressures	0	PR
10/28/2020	10/28/2020	ODESSA PL	3161	Line 3161 maintenance pig Mobil Coyanosa to Waha	0	PR
11/3/2020	11/4/2020	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
11/3/2020	11/5/2020	SAN SIMON STA	2	San Simon 2 inspection	10	SM
11/3/2020	11/3/2020	EUNICE C	3CC	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	60	PR
11/3/2020	11/6/2020	WINDOW ROCK	4B	Window Rock 4B inspection	15	NM
11/4/2020	11/4/2020	ODESSA PL	3160	Line 3160 maintenance pig Mobil Coyanosa to Waha	0	PR
11/10/2020	11/12/2020	HACKBERRY STA	STA	Hackberry Station maintenance	240	NM
11/10/2020	11/13/2020	FLORIDA STA	1A	Florida 1A inspection	22	SM
11/11/2020	11/11/2020	HACKBERRY STA	STA	Hackberry Station maintenance	240	NM
11/11/2020	11/11/2020	ODESSA PL	STA	WAHA Station maintenance	160	PR
11/12/2020	11/12/2020	ODESSA PL	3133	Line 3133 maintenance pig Sweetie Peck to Goldsmith	0	PR
11/17/2020	11/18/2020	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
11/17/2020	11/17/2020	BLACK RIVER	1	Black River 1 inspection	119	SM
11/17/2020	11/17/2020	BONDAD	1B	Bondad 1B inspection	95	SJ
11/18/2020	11/18/2020	ODESSA PL	1115	Line 1115 maintenance pig Goldsmith to L1102	0	PR
11/18/2020	11/18/2020	BONDAD	2A	Bondad 2A inspection	95	SJ
11/21/2020	11/24/2020	EP W DIST	2000	Line 2000 smart pig Afton to Lordsburg	356	SM
11/24/2020	11/25/2020	LEUPP	2A	Leupp 2A inspection	8	NM
12/1/2020	12/1/2020	CIMARRON STA	1	Cimarron 1 inspection	88	SM
12/1/2020	12/2/2020	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
12/3/2020	12/3/2020	FLORIDA STA	1C	Florida 1C inspection	42	SM
12/8/2020	12/10/2020	ORACLE STA	STA	Oracle unit inspection	94	SM

12/8/2020	12/10/2020	CORNUDAS STA	2A	Cornudas 2A inspection	22	SM
12/9/2020	12/9/2020	ODESSA PL	3114	L3114 maintenance pig higher pressures	0	PR
12/15/2020	12/16/2020	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
12/15/2020	12/15/2020	CORNUDAS STA	1C	Cornudas 1C inspection	42	SM
12/15/2020	12/15/2020	EL PASO CD PLT	4D	El Paso 4D inspection	42	SM
12/15/2020	12/16/2020	WILLCOX STA	2A	Willcox 2A shut down checks	130	SM
12/16/2020	12/16/2020	CORNUDAS STA	2C	Cornudas 2C inspection	42	SM
12/17/2020	12/17/2020	ALAMO LAKE STA	1A	Alamo Lake 1A inspection	75	HX
12/29/2020	12/30/2020	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ