

El Paso Pipeline Maintenance Summary


This document lists major maintenance and construction shutdowns that are being planned on the EPNG pipeline system for the next 12 to 15 months. The purpose of this posting is to make customers aware of **proposed outages** that will affect throughput on the various systems of the pipeline. Dates may change based on changing business conditions or to coordinate with outages on interconnecting pipelines. **Comments regarding alternate dates are welcome.**

This document is not intended to be an official notice. When shutdowns are finalized, they will be posted as Informational Postings, found on the EPNG Pipeline Company Home Page. Refer to those notices for current shutdowns.

This Shutdown Schedule will normally be updated weekly or by special edition if warranted. Please refer to the revision date.

El Paso Natural Gas Co. Shutdown Schedule

All dates are tentative and subject to change. See EBB Maintenance notices for finalized dates and impacts.



Revised: 1/15/2021

Questions? Call Vic Villalva 719-520-4251

EPNG will post an update for the impact to the system as soon as possible.TBD (To Be Determined)

Start Date	End Date	Location	Unit	Description	Reduction in MMcf/d	System
11/7/2013	12/31/2021	WINDOW ROCK	3A	Window Rock 3A repair pending	22	NM
1/5/2015	12/31/2021	VAIL STA	1,2,3	Vail Station repair pending	18	SM
7/21/2015	12/31/2021	WILLIAMS	4B	Williams 4B repair pending	10	NM
12/1/2015	12/31/2021	LEUPP	7A	Leupp 7A mechanical repair pending	7	NM
12/1/2015	12/31/2021	LEUPP	1A	Leupp 1A repair pending	7	NM
1/1/2016	12/31/2021	EL PASO D	2D	El Paso 2D repair pending	0	SM
8/4/2016	12/31/2021	MONUMENT STA	1B	Monument 1B Repair Pending	20	SM

11/30/2016	12/31/2021	SAN SIMON STA	3A	San Simon 3 repair pending	50	SM
9/8/2017	12/31/2021	LEUPP	9A	Leupp 9A repair pending	10	NM
11/6/2018	12/31/2021	WINDOW ROCK	1B	Window Rock 1B repair pending	37	NM
12/2/2018	12/31/2022	DIMMITT STA	1	Dimmitt 1 repair pending	40	AN
12/31/2019	12/31/2021	KEYSTONE	3A	Keystone 3A repair pending	37	PR
6/11/2020	12/31/2021	LINCOLN	1	Lincoln Unit 1 maintenance	158	XO
6/19/2020	12/31/2021	WAHA COMP	1,2,3,4	WAHA Solar Units 1,2,3 ,4 repair	146	PR
6/22/2020	3/31/2021	LEUPP	1B	Leupp 1B repair	45	NM
7/21/2020	1/31/2021	SAN SIMON STA	3A	San Simon 3A maintenance	12	SM
9/29/2020	1/31/2021	FLORIDA STA	2A	Florida 2A maintenance	22	SM
12/1/2020	2/25/2021	KEYSTONE	5A	Keystone 5A repair	40	PR
1/4/2021	1/8/2021	EL PASO C	1C	El Paso 1C inspection	22	SM
1/5/2021	1/6/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
1/5/2021	1/6/2021	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	76	SM
1/11/2021	1/15/2021	AFTON STA	3A	Afton 3A inspection	65	SM
1/12/2021	1/13/2021	Dragoon Sta	1A	Dragoon Station maintenance	128	SM
1/12/2021	1/14/2021	HACKBERRY STA	1A	Hackberry 1A inspection	113	NM
1/12/2021	1/13/2021	ODESSA PL	6071	Line 6071 pipeline maintenance MLV 1 to EOL locations shut in required WTG - KERMIT WINKLER (DWTG KWX), ETC - Sid Rich Delivery (DWTGFUEL)	0	PR
1/12/2021	1/14/2021	WINDOW ROCK	6A	Window Rock 6A inspection	37	NM
1/12/2021	1/14/2021	FLORIDA STA	1A	Florida 1A inspection	22	SM
1/20/2021	1/21/2021	MOJAVE STA	UNIT	Mojave Unit maintenance	117	MOJ
1/26/2021	1/28/2021	ORACLE STA	STA	Oracle unit inspection	94	SM
1/26/2021	2/26/2021	CORNUDAS STA	1A	Cornudas 1A maintenance	22	SM
2/2/2021	2/2/2021	TOM MIX STA	1A	Tom Mix 1A inspection	43	SM
2/2/2021	2/3/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
2/3/2021	2/3/2021	LORDSBURG STA	1C	Lordsburg 1C inspection	42	SM
2/8/2021	2/12/2021	LORDSBURG STA	1B	Lordsburg 1B inspection	46	SM
2/9/2021	2/9/2021	EP W PIPE	2058	Line 2058 smart pig - flow assistance request Rio Grande Plant (DEPECAFT) - Informational only	0	SM
2/9/2021	2/9/2021	BELEN	1300	Belen Station maintenance	70	XO

2/9/2021	2/11/2021	LEUPP	3B	Leupp 3B inspection	20	NM
2/9/2021	2/11/2021	SAN SIMON STA	1A	San Simon 1 inspection	28	SM
2/9/2021	2/11/2021	HACKBERRY STA	2A	Hackberry 2 inspection	83	NM
2/10/2021	2/12/2021	EL PASO C	C	El Paso Station "C" Annual DOT/ESD Test	50	SM
2/11/2021	2/11/2021	EP W PIPE	2058	Line 2058 smart pig - flow assistance request Rio Grande Plant (DEPECAFT) - Informational only	0	SM
2/16/2021	2/17/2021	CIMARRON STA	1	Cimarron 1 inspection	88	SM
2/16/2021	2/17/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
2/16/2021	2/17/2021	LEUPP	8A	Leupp 8A inspection	10	NM
2/16/2021	2/16/2021	CORNUDAS STA	1C	Cornudas 1C inspection	42	SM
2/18/2021	2/18/2021	HACKBERRY STA	STA	Line 1204 pipeline maintenance Hackberry to MLV 34 3/4	240	NM
2/18/2021	3/5/2021	ODESSA PL	1103	Line 1103 pipeline remediation MLV 15 to Cornudas	175	SM
2/23/2021	2/23/2021	Dragoon Sta	1A	Dragoon Station DOT/ESD Test	128	SM
2/23/2021	2/25/2021	FLORIDA STA	1C	Florida "C" Station DOT/ESD Test	40	SM
2/23/2021	2/26/2021	PECOS RIVER STA	2A	Pecos 2A inspection	110	SM
2/24/2021	2/24/2021	EL PASO D	4D	El Paso 4D inspection	42	SM
3/2/2021	3/2/2021	WILLCOX STA	STA	Willcox Station Annual DOT/ESD Test	208	SM
3/2/2021	3/3/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
3/2/2021	3/4/2021	CORNUDAS STA	2A	Cornudas 2A inspection	22	SM
3/3/2021	3/3/2021	WILLCOX STA	2A	Willcox 2A shut down checks	130	SM
3/2/2021	3/4/2021	LORDSBURG STA	1C	Lordsburg 1C shut down checks	50	SM
3/2/2021	3/5/2021	KEYSTONE	5A	Keystone 5A inspection	40	PR
3/2/2021	4/9/2021	CORNUDAS STA	1B	Cornudas 1B maintenance	76	SM
3/3/2021	3/5/2021	BLACK RIVER	STA	Black River Station DOT/ESD Test	107	SM
3/9/2021	3/26/2021	FLAGSTAFF - PL	1201	Line 1201 pipeline remediation Dilkon to Leupp	TBD	NM
3/9/2021	3/9/2021	ALAMO LAKE STA	STA	Alamo Lake Station DOT/ESD Test	150	HX
3/9/2021	3/10/2021	LORDSBURG STA	A	Lordsburg Station "A" DOT/ESD Test	65	SM
3/9/2021	3/10/2021	LEUPP	2A	Leupp 2A inspection	8	NM
3/9/2021	3/11/2021	HACKBERRY STA	STA	Hackberry Station DOT/ESD Test	263	NM
3/9/2021	3/9/2021	ODESSA PL	3028	Line 3028 maintenance pig Goldsmith to Keystone Field	0	PR

3/10/2021	3/10/2021	ALAMO LAKE STA	1A	Alamo Lake 1A shut down checks	10	HX
3/10/2021	3/10/2021	ODESSA PL	3028	Line 3006 Goldsmith to Keystone Field	0	PR
3/11/2021	3/11/2021	ALAMO LAKE STA	2A	Alamo Lake 2A shut down checks	100	HX
3/16/2021	3/16/2021	DUTCH FLATS STA	1A	Dutch 1A inspection	33	HX
3/16/2021	3/17/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
3/16/2021	3/16/2021	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	PR
3/16/2021	3/16/2021	CORNUDAS STA	2C	Cornudas 2C inspection	42	SM
3/16/2021	3/18/2021	CORNUDAS STA	STAC	Cornudas Station "C" DOT/ESD Test	83	SM
3/16/2021	5/31/2021	EHRENBERG	1100	Line 1100 Hydro Test Wenden to Ehrenburg	100	SM
3/23/2021	3/25/2021	LEUPP	5A	Leupp 5A inspection	2	NM
3/23/2021	3/23/2021	DEMING PL	1100	Line 1100 smart pig Deming to San Simon	159	SM
3/23/2021	3/24/2021	DILKON	STA	Dilkon Station DOT/ESD Test	78	NM
3/23/2021	3/23/2021	RIO VISTA	STA	Rio Vista Station DOT/ESD Test	150	SJ
3/24/2021	3/24/2021	RIO VISTA	2A	Rio Vista 2A shut down checks	99	SJ
3/25/2021	3/25/2021	DEMING PL	1100	Line 1100 smart pig Deming to San Simon	159	SM
3/27/2021	3/27/2021	DEMING PL	1100	Line 1100 smart pig Deming to San Simon	159	SM
3/30/2021	3/30/2021	EHRENBERG	1100	Line 1100 smart pig Wenden to Ehrenbug	220	SM
3/30/2021	3/31/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
3/30/2021	3/30/2021	EUNICE B	STAB	Eunice Station "B" DOT/ESD Test	50	PR
3/30/2021	3/30/2021	BONDAD	STAA	Bondad Station "A" DOT/ESD Test	466	SJ
3/30/2021	3/30/2021	BONDAD	STAB	Bondad Station "B" DOT/ESD Test	200	SJ
3/31/2021	3/31/2021	BONDAD	1B	Bondad "B" Station maintenance	95	SJ
4/1/2021	4/1/2021	EHRENBERG	1100	Line 1100 smart pig Wenden to Ehrenbug	220	SM
4/1/2021	4/1/2021	WINK	2	Wink 2 inspection	104	SM
4/3/2021	4/3/2021	EHRENBERG	1100	Line 1100 smart pig Wenden to Ehrenbug	220	SM
4/6/2021	5/30/2021	EP W PIPE	2034	Line 2034 Hydro test MLV 2 to MLV 3 during this hydro Rio Grande Power Plant (DEPECAFT) will be limited to 25,000 Dthd	25	SM
4/6/2021	4/7/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
4/6/2021	4/6/2021	GALLUP-N ML MEAS	1200	Line 1200 smart pig Window Rock to Dilkon	140	NM
4/6/2021	4/6/2021	Sierrita Gas	1A	Sierrita Station maintenance PIN 47698 GSDEAGU/SIERRITA SASABE PIMA delivery psig during this maintenance may be below 740 psig	201	SGPL
4/6/2021	4/6/2021	SAN SIMON STA	STA	San Simon Station DOT/ESD Test	139	SM

4/6/2021	4/8/2021	LEUPP	STA	Leupp Station DOT/ESD Test	108	NM
4/6/2021	4/8/2021	SAN SIMON STA	1	San Simon 1 inspection	20	SM
4/6/2021	7/30/2021	PHOENIX	1100	Line 1100 pipeline remediation Casa Grande to Wenden	TBD	SM
4/6/2021	4/6/2021	CASA GRANDE	1C	Casa Grande 1C shutdown checks	65	SM
4/6/2021	4/6/2021	FLORIDA STA	1A	Florida 1A shutdown checks	22	SM
4/6/2021	4/8/2021	MOJAVE STA	1,2,3A	Mojave Station Unit shut down checks	117	MOJ
4/6/2021	4/8/2021	EUNICE C	2C	Eunice 2C inspection	40	PR
4/6/2021	5/7/2021	WILLCOX STA	1A	Willcox 1A maintenance	130	SM
4/6/2021	4/6/2021	AMARILLO	STA	Amarillo Station DOT/ESD Test and Unit shutdown checks	80	AN
4/7/2021	4/7/2021	FLORIDA STA	2A	Florida 2A shut down checks	22	SM
4/7/2021	4/7/2021	SAN SIMON STA	UNIT #3	San Simon Station Annual DOT/ESD Test	10	SM
4/13/2021	4/13/2021	GALLUP-N ML MEAS	1200	Line 1200 smart pig Window Rock to Dilkon	140	NM
4/13/2021	4/13/2021	SCHAFER	STA	Schafer Station DOT/ESD Test and Unit shutdown checks	50	AN
4/13/2021	4/19/2021	FLORIDA STA	1C	Florida 1C maintenance	42	SM
4/13/2021	4/13/2021	SAN JUAN PL	1205	Line 1205 maintenance pig Bondad to VIV 1 pressures will be higher	0	SJ
4/13/2021	4/15/2021	EUNICE C	1C	Eunice C1 inspection	40	PR
4/13/2021	4/16/2021	KEYSTONE	7A	Keystone 7A inspection	40	PR
4/13/2021	4/13/2021	SAN JUAN PL	1218	Line 1218 maintenance pig Bondad to VLV 1 pressures will be higher	0	SJ
4/14/2021	4/14/2021	CASTLE DOME STA	STA	Castle Dome Annual DOT/ESD Test no compression available DSWG YUM Yuma Co -Gen ,Yucca Power PLT DAPS YUM	19	YU
4/15/2021	4/15/2021	MOJAVE STA	STA	Mojave Station ESD/DOT Test No flow for 12 hours starting 8:00 AM	235	MOJ
4/15/2021	4/16/2021	SCHAFER	2A	Schafer 2 inspection	50	AN
4/15/2021	4/15/2021	GALLUP-N ML MEAS	1200	Line 1200 smart pig Window Rock to Dilkon	140	NM
4/20/2021	4/21/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
4/20/2021	4/20/2021	TOM MIX STA	STAALL	Tom Mix Station Annual DOT/ESD Test	146	SM
4/20/2021	4/20/2021	BLUEWATER	2B	Bluewater 2B inspection	10	XO
4/20/2021	4/21/2021	NAVAJO	STA	Navajo Station "C" Annual DOT/ESD Test	120	NM
4/20/2021	4/21/2021	NAVAJO	STA	Navajo Station "D" Annual DOT/ESD Test	120	NM
4/20/2021	4/23/2021	WINDOW ROCK	3B	Window Rock 3B inspection	37	NM
4/20/2021	4/20/2021	Dimmit Station	STA	Dimmit Station DOT/ESD Test	65	AN
4/21/2021	4/21/2021	DUTCH FLATS STA	STA	Dutch Flats Station inspection	128	HX

4/21/2021	4/21/2021	FLORIDA STA	STAA	Florida Station "A" DOT/ESD Test	65	SM
4/22/2021	4/22/2021	HACKBERRY STA	STA	Hackberry Station electrical inspection	142	NM
4/22/2021	4/23/2021	LORDSBURG STA	1B	Lordsburg Station B DOT/ESD & Shut down checks	46	SM
4/27/2021	4/27/2021	WINDOW ROCK	B	Window Rock Station "B" DOT/ESD Test	190	NM
4/27/2021	4/28/2021	WINDOW ROCK	A	Window Rock Station "A" DOT/ESD Test	314	NM
4/27/2021	4/29/2021	WINDOW ROCK	7A	Window Rock 7A Shut down checks	245	NM
4/27/2021	4/29/2021	CORNUDAS STA	B	Cornudas Station "B" DOT/ESD Test	119	SM
4/27/2021	5/28/2021	FLORIDA STA	1B	Florida 1B maintenance	22	SM
5/3/2021	6/11/2021	GALLUP-SAN JUAN X MEAS	1300	Line 1300 hydro test Bluewater to MLV 38	TBD	XO
5/4/2021	5/5/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
5/4/2021	5/6/2021	WILLIAMS	STA	Williams Station Annual DOT/ESD Test	204	NM
5/4/2021	5/6/2021	ORACLE STA	STA	Oracle Station DOT/ESD Test	94	SM
5/4/2021	5/5/2021	FLORIDA STA	1B	Florida Station "B" DOT/ESD Test	53	SM
5/4/2021	5/7/2021	WINDOW ROCK	4A	Window Rock 4A inspection	37	NM
5/6/2021	5/6/2021	WINK	2	Wink 2 inspection	104	SM
5/11/2021	5/11/2021	WENDEN STA	1A	Wenden 1A shutdown checks	110	HX
5/11/2021	5/12/2021	GALLUP	STA	Gallup Station DOT/ESD Test	503	SJ
5/11/2021	5/13/2021	PECOS RIVER STA	3A	Pecos River 3 inspection	32	SM
5/12/2021	5/12/2021	WENDEN STA	2A	Wenden 2A shut down checks	65	HX
5/12/2021	5/12/2021	SAN JUAN PL	1218	Line 1218 maintenance pig MLV 2 to MLV 3 1/2 higher pressures	0	SJ
5/13/2021	5/13/2021	DUTCH FLATS STA	2A	Dutch Flats 2A inspection	33	HX
5/13/2021	5/13/2021	WENDEN STA	STA	Wenden Station DOT/ESD Test	175	HX
5/17/2021	5/21/2021	WASHINGTON RANCH	STA	Washington Ranch Spring BHP Survey No injection or withdrawal	0	SM
5/18/2021	5/19/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
5/18/2021	5/19/2021	SELIGMAN	STA	Seligman "B" Station DOT/ESD Test	170	NM
5/18/2021	5/20/2021	SELIGMAN	1C	Seligman "C" Station DOT/ESD Test	105	NM
5/18/2021	5/20/2021	DAGGETT STA	STA	Daggett Station ESD/DOT Test	50	MOJ
5/18/2021	5/18/2021	TOM MIX STA	2A	Tom Mix 2A inspection	43	SM
5/18/2021	5/20/2021	BELEN	STAA	Belen Station DOT/ESD Test	70	XO
5/18/2021	5/21/2021	EL PASO D	D	El Paso Station "D" DOT/ESD Test	92	SM
5/19/2021	5/19/2021	TOM MIX STA	1A	Tom Mix 1A inspection	43	SM

5/20/2021	5/20/2021	CAPROCK	STA	Caprock Station DOT/ESD Test	40	XO
5/25/2021	5/26/2021	CIMARRON STA	STAALL	Cimarron Station DOT/ESD Test	50	SM
5/26/2021	5/26/2021	CASA GRANDE	2C	Casa Grande 2C shutdown checks	42	SM
5/26/2021	5/28/2021	PECOS RIVER STA	STA	Pecos Station DOT/ESD Test	150	SM
5/27/2021	5/27/2021	CASA GRANDE	STA	Casa Grande Station DOT/ESD Test	210	SM
5/28/2021	5/28/2021	CASA GRANDE	1A	Casa Grande 1A shutdown checks	42	SM
5/28/2021	5/28/2021	CASA GRANDE	1B	Casa Grande 1B shut down checks	104	SM
5/31/2021	6/4/2021	PUCKETT	STA	Puckett Station DOT/ESD Test gas from ITERRELL, IMLTERPK and IYUCBUTE must be routed to Wink thru Line 2000 instead of Waha and will be limited to a total of 98,000 Dthd.	135	PR
6/1/2021	6/2/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
6/1/2021	6/2/2021	BLUEWATER	STA	Blue Water Station DOT/ESD Test	90	XO
6/2/2021	6/2/2021	SAN JUAN PL	1218	Line 1218 maintenance pig MLV 3 1/2 to MLV 3 3/4 higher pressures	0	SJ
6/2/2021	6/2/2021	SAN JUAN PL	1205	Line 1205 maintenance pig Bondad to MLV 3 3/4 higher pressures	0	SJ
6/8/2021	6/11/2021	HUECO STA	STAALL	Hueco Station ESD/DOT Test & Unit shut down checks	70	SM
6/9/2021	6/9/2021	EL PASO D	3D	El Paso 3D inspection	42	SM
6/15/2021	6/16/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
6/15/2021	6/18/2021	WINDOW ROCK	2A	Window Rock 2A inspection	20	NM
6/15/2021	6/18/2021	CORNUDAS STA	A	Cornudas Station A DOT/ESD Test	174	SM
6/16/2021	6/16/2021	DUMAS STA	STA	Dumas Station DOT/ESD Test	50	AN
6/17/2021	6/17/2021	FLORIDA STA	1C	Florida 1C inspection	42	SM
6/22/2021	6/24/2021	AFTON STA	STA	Afton Station DOT/ESD Test	65	SM
6/22/2021	6/22/2021	SAN JUAN	STA	San Juan Station DOT/ESD Test	30	SJ
6/22/2021	6/22/2021	FLAGSTAFF - PL	1208	Line 1208 smart pig MLV 31 1/4 to Williams	140	NM
6/22/2021	6/24/2021	GRESHAM	STA	Gresham Station DOT/ESD Test	66	SM
6/24/2021	6/24/2021	WENDEN STA	2A	Wenden 2A inspection	39	HX
6/29/2021	6/30/2021	CIMARRON STA	1	Cimarron 1A inspection	50	SM
6/29/2021	6/30/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
7/1/2021	7/1/2021	FLAGSTAFF - PL	1208	Line 1208 smart pig MLV 31 1/4 to Williams	140	NM

7/7/2021	7/7/2021	Flag-West-PL	1204	Line 1204 smart pig Flagstaff to Williams	140	NM
7/7/2021	8/6/2021	DILKON	1B	Dilkon 1B maintenance	45	NM
7/13/2021	7/14/2021	Red Mountain	1A	Red Mountain Station DOT/ESD Test	40	SM
7/13/2021	7/14/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
7/13/2021	7/16/2021	MOJAVE STA	2A	Mojave 2A inspection	117	MOJ
7/13/2021	7/15/2021	WHITE ROCK	STA	White Rock Station DOT/ESD Test	259	SJ
7/14/2021	7/15/2021	LINCOLN	STA	Lincoln Station DOT/ESD Test	158	XO
7/17/2021	7/17/2021	Flag-West-PL	1204	Line 1204 smart pig Flagstaff to Williams	140	NM
7/20/2021	7/20/2021	Flag-West-PL	1204	Line 1204 smart pig Williams to Seligman	140	NM
7/26/2021	7/30/2021	AMARILLO	1A	Amarillo 1A inspection	40	AN
7/27/2021	7/28/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
8/3/2021	8/4/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
8/3/2021	8/4/2021	LAGUNA	STAA	Laguna Station DOT/ESD Test	97	XO
8/10/2021	8/10/2021	ODESSA PL	1105	Line 1105 maintenance pig MP 51 to Keystone	0	PR
8/10/2021	8/10/2021	TOM MIX STA	2A	Tom Mix 2A inspection	43	SM
8/10/2021	8/10/2021	EL PASO D	4D	El Paso 4D inspection	42	SM
8/10/2021	8/10/2021	BLANCO A	STA	Blanco Station DOT/ESD Test No flow for 12 hours starting 8:00 AM	400	SJ
8/12/2021	8/12/2021	CORNUDAS STA	1C	Cornudas 1C inspection	80	SM
8/17/2021	8/17/2021	SAN JUAN PL	1212	Line 1212 maintenance pig pressures will be higher Blanco	0	SJ
8/17/2021	8/17/2021	BLUEWATER	1B	Bluewater 1B inspection	20	XO
8/17/2021	8/20/2021	MOJAVE STA	1A	Mojave 1A inspection	117	MOJ
8/24/2021	8/24/2021	FLAGSTAFF - PL	1208	Line 1208 smart pig Seligman to Hackberry	150	NM
8/26/2021	8/26/2021	FLAGSTAFF - PL	1208	Line 1208 smart pig Seligman to Hackberry	150	NM
8/30/2021	9/15/2021	WILLIAMS	STA	Williams Station maintenance	204	NM
8/31/2021	8/31/2021	ODESSA PL	1103	Line 1103 smart pig Pecos to Guadalupe	175	PR
8/31/2021	8/31/2021	BLUEWATER	3B	Bluewater 3B inspection	20	XO
8/31/2021	9/1/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
9/1/2021	9/1/2021	CORNUDAS STA	2C	Cornudas 1C inspection	75	SM
9/2/2021	9/2/2021	ODESSA PL	1103	Line 1103 smart pig Pecos to Guadalupe	175	PR
9/3/2021	10/3/2021	Flag-West-PL	1203	Line 1203 pipeline maintenance MLV 2 to MLV 4	134	MRC
9/7/2021	9/7/2021	SAN JUAN PL	1219	Line 1219 maintenance pig Chaco to White Rock	0	SJ
9/8/2021	9/8/2021	SAN JUAN PL	1202	Line 1202 maintenance pig Blanco to White Rock pressures will be higher	0	SJ
9/8/2021	9/10/2021	WINDOW ROCK	5A	Window Rock 5A inspection	22	NM
9/8/2021	10/8/2021	FLORIDA STA	3A	Florida 3A maintenance	22	SM
9/8/2021	10/29/2021	HUECO STA	2A	Hueco 2A maintenance	80	SM

9/8/2021	12/17/2021	TOPOCK-MOJAVE	1204	Line 1204 Hydro Test Franconia to MLV 13 3/4	250	AN
9/14/2021	9/15/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
9/14/2021	9/17/2021	KEYSTONE	STA	Keystone Station DOT/ESD Test	611	PR
9/14/2021	9/30/2021	GALLUP-N ML MEAS	1204	Line 1204 pipeline maintenance Gallup to Window Rock	TBD	XO
9/14/2021	9/14/2021	PHOENIX	1103	Line 1103 smart pig Casa Grande to Wenden	175	SM
9/15/2021	9/15/2021	SAN JUAN PL	1212	Line 1212 maintenance pig VLV 1 to VLV 3 1/2 pressures will be higher	0	SJ
9/16/2021	9/16/2021	PHOENIX	1103	Line 1103 smart pig Casa Grande to Wenden	175	SM
9/16/2021	9/16/2021	CASA GRANDE	2C	Casa Grande 2C inspection	31	SM
9/17/2021	9/24/2021	WASHINGTON RANCH	STA	Washington Ranch Fall BHP Survey no injection or withdrawal	0	SM
9/21/2021	9/23/2021	WINDOW ROCK	2B	Window Rock 2B inspection	13	NM
9/28/2021	9/29/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
9/29/2021	9/29/2021	ROSWELL	STA	Roswell Station DOT/ESD Test	65	XO
10/5/2021	10/5/2021	PHOENIX	1600	Line 1600 smart pig Casa Grande Station to Wenden	250	PHX
10/5/2021	10/6/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
10/5/2021	10/5/2021	ODESSA PL	1110	Line 1110 smart pig Pecos to Guadalupe	114	SM
10/5/2021	10/7/2021	GUADALUPE STA	STA	Guadalupe Station DOT/ESD Test	160	SM
10/5/2021	11/5/2021	PHOENIX	1203	Line 1203 Hydro Test MLV 4 to MLV 6	134	MRC
10/7/2021	10/7/2021	ALAMO LAKE STA	1A	Alamo Lake 1A inspection	75	HX
10/7/2021	10/7/2021	PHOENIX	1600	Line 1600 smart pig Casa Grande Station to Wenden	250	PHX
10/12/2021	10/12/2021	DUTCH FLATS STA	1A	Dutch Flats 1A shut down checks	33	HX
10/12/2021	10/14/2021	WINK	STA	Wink Station DOT/ESD Test	268	SM
10/12/2021	10/15/2021	WINDOW ROCK	1A	Window Rock 1A inspection	37	NM
10/12/2021	10/12/2021	CASA GRANDE	1C	Casa Grande 2C inspection	31	SM
10/13/2021	10/13/2021	DUTCH FLATS STA	2A	Dutch Flats 2A shut down checks	33	HX
10/13/2021	10/15/2021	PICACHO STA	1,2,3A	Picacho Station DOT/ESD Test informational only	0	PHX
10/14/2021	10/14/2021	DUTCH FLATS STA	STA	Dutch Flats Station DOT/ESD Test	107	HX
10/14/2021	10/14/2021	ODESSA PL	1110	Line 1110 smart pig Pecos River to Guadalupe	140	SM
10/19/2021	10/19/2021	EHRENBERG	1600	Line 1600 smart pig Wenden to Ehrenburg	250	SM
10/19/2021	10/20/2021	CIMARRON STA	1	Cimarron 1A inspection	88	SM

10/19/2021	10/20/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
10/21/2021	10/21/2021	EHRENBERG	1600	Line 1600 smart pig Wenden to Ehrenburg	250	SM
10/27/2021	10/29/2021	PLAINS STA	STAALL	Plain Station DOT/ESD Test deliveries cannot be made to INN30PLA, IW40-043, or IMUSTANG; during this outage, no gas can be received at INN26PLA.	762	AN
11/2/2021	11/3/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
11/2/2021	11/5/2021	WINDOW ROCK	4B	Window Rock 4B inspection	15	NM
11/9/2021	11/9/2021	TOM MIX STA	1A	Tom Mix 1A inspection	43	SM
11/9/2021	11/12/2021	BELEN	2A	Belen 2A inspection	40	XO
11/16/2021	11/17/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
11/16/2021	11/18/2021	HUECO STA	3	Hueco 3A inspection	42	SM
11/16/2021	11/18/2021	LORDSBURG STA	1A	Lordsburg 1A inspection	46	SM
11/16/2021	11/16/2021	BONDAD	1B	Bondad 1B inspection	95	SJ
11/17/2021	11/17/2021	BONDAD	2A	Bondad 2A inspection	95	SJ
11/30/2021	11/30/2021	ODESSA PL	3114	L3114 maintenance pig higher pressures	0	PR
12/1/2021	12/2/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ
12/1/2021	12/1/2021	EL PASO CD PLT	3D	El Paso 3D inspection	42	SM
12/7/2021	12/9/2021	FLORIDA STA	1A	Florida 1A inspection	22	SM
12/7/2021	12/9/2021	CORNUDAS STA	2A	Cornudas 2A Inspection	50	SM
12/7/2021	12/9/2021	HUECO STA	1A	Hueco 1A inspection	42	SM
12/16/2021	12/16/2021	LORDSBURG STA	1C	Lordsburg 1C inspection	42	SM
12/21/2021	12/21/2021	TOM MIX STA	2A	Tom Mix 2A inspection	43	SM
12/22/2021	12/22/2021	FLORIDA STA	1C	Florida 1C inspection	42	SM
12/28/2021	12/29/2021	MOJAVE STA	UNIT	Mojave unit maintenance	117	MOJ