

El Paso Pipeline Maintenance Summary


This document lists major maintenance and construction outages that are being planned on the EPNG pipeline system for the next 12 to 15 months. The purpose of this posting is to make customers aware of **proposed outages** that will affect throughput on the various systems of the pipeline. Dates may change based on changing business conditions or to coordinate with outages on interconnecting pipelines. **Comments regarding alternate dates are welcome.**

This document is not intended to be an official notice. When outages are finalized, they will be posted as Informational Postings, found on the EPNG Pipeline Company Home Page. Refer to those notices for current outages.

This outage schedule will normally be updated weekly or by special edition if warranted. Please refer to the revision date.

El Paso Natural Gas Co. Outage Schedule

All dates are tentative and subject to change. See EBB Maintenance notices for finalized dates and impacts.



Revised: 10/3/2024

Questions? Call John Althoff 719-667-7750

EPNG will post an update for the impact to the system as soon as possible. TBD (To Be Determined)

| Start Date | End Date | Location | Unit | Maintenance Activity | Reduction in MMcf/d | Oregion |
|------------|------------|--------------|------|-------------------------------|---------------------|---------|
| 11/7/2013 | 12/31/2024 | WINDOW ROCK | 3A | Window Rock 3A repair pending | 35 | NM |
| 7/21/2015 | 12/31/2024 | WILLIAMS | 1204 | Williams 4B repair pending | 35 | NM |
| 12/1/2015 | 12/31/2024 | LEUPP | 1A | Leupp 1A repair pending | 25 | NM |
| 8/4/2016 | 12/31/2024 | MONUMENT STA | 1B | Monument 1B repair pending | 20 | SM |
| 9/8/2017 | 12/31/2024 | LEUPP | 9A | Leupp 9A repair pending | 25 | NM |
| 1/1/2018 | 12/31/2024 | CASA GRANDE | 1A | Casa Grande 1A repair pending | 42 | SM |
| 11/6/2018 | 12/31/2024 | WINDOW ROCK | 1B | Window Rock 1B repair pending | 35 | NM |

| | | | | | | |
|------------|------------|---------------|------------------|---|-----|-----|
| 5/27/2021 | 12/31/2025 | PLAINS STA | 15A | Plains 15A repair | 50 | SM |
| 5/28/2021 | 12/31/2024 | PLAINS STA | 8A | Plains 8A repair | 35 | SM |
| 6/14/2022 | 12/31/2024 | FLAGSTAFF | 2A | Flagstaff 2A repair | 115 | NM |
| 7/19/2022 | 11/29/2024 | KEYSTONE | 9A | Keystone 9A repair | 35 | PR |
| 11/30/2022 | 12/31/2024 | FLAGSTAFF | 1A | Flagstaff 1A repair | 115 | NM |
| 6/27/2023 | 12/31/2024 | LEUPP | 2A | Leupp 2A repair pending | 0 | NM |
| 10/30/2023 | 12/31/2024 | LEUPP | 3A | Leupp 3A repair pending | 50 | NM |
| 4/1/2024 | 12/31/2024 | KEYSTONE | 9A | Keystone 9A repair | 35 | PR |
| 4/15/2024 | 12/31/2024 | DIMMITT STA | 3A | Dimmitt 3A maintenance | 50 | AN |
| 5/6/2024 | 10/11/2024 | TOPOCK-MOJAVE | 1200 | Line 1200 Hydrotest Seligman to Hackberry | 150 | NM |
| 5/8/2024 | 10/25/2024 | PLAINS STA | 3A | Plains 3A repair | 50 | SM |
| 5/8/2024 | 10/4/2024 | CAPROCK | 1A | Caprock 1A repair | 75 | XO |
| 7/30/2024 | 10/4/2024 | TUCSON | 1008 | Line 1008 pipeline remediation - MLV 11 to MLV 11.5 - (Informational Only) | 0 | SM |
| 9/6/2024 | 10/6/2024 | PHOENIX | 1203 | Line 1203 pipeline maintenance MLV 5 | 130 | PHX |
| 9/6/2024 | 10/6/2024 | PHOENIX | 1203 | Line 1203 pipeline maintenance MLV 4 to MLV 5.5 | 130 | PHX |
| 9/9/2024 | 10/11/2024 | TUCSON | 1100 | Line 1100 pipeline repair Benson to Vail | 200 | SM |
| 9/9/2024 | 10/11/2024 | TUCSON | 1103 | Line 1103 pipeline repair Benson to Vail | 300 | SM |
| 9/9/2024 | 10/31/2024 | TOPOCK-MOJAVE | 2121 | Line 2121 External Corrosion Dig Assesment - SWG Bullhead City Gate - Customer Affected | 0 | NM |
| 9/10/2024 | 10/11/2024 | TUCSON | 1007 | Line 1007 hydrotest - MLV 17 to MLV 18 - (Informational Only) | 0 | SM |
| 9/12/2024 | 11/10/2024 | TOPOCK-MOJAVE | 1201 | Line 1201 Hydrotest Seligman to Hackberry | 150 | NM |
| 9/12/2024 | 11/10/2024 | TOPOCK-MOJAVE | 1201 | Line 1201 Hydrotest Seligman to Hackberry | 150 | NM |
| 9/16/2024 | 10/18/2024 | SAN JUAN PL | 1201 | Line 1201 Hydrotest MLV 0 to MLV 1 | 150 | SJ |
| 9/16/2024 | 11/8/2024 | LORDSBURG STA | 1A | Lordsburg 1A maintenance | 50 | SM |
| 9/17/2024 | 12/14/2024 | TUCSON | 1100 | Line 1100 pipeline maintenance Dragoon to Vail | 200 | SM |
| 9/24/2024 | 11/22/2024 | CORNUDAS STA | 1100-1103 | Cornudas 2A maintenance | 75 | SM |
| 9/30/2024 | 10/11/2024 | PLAINS STA | 13A | Plains 13A repair | 45 | SM |
| 10/1/2024 | 10/3/2024 | WINDOW ROCK | 2A | Window Rock 2A inspection | 32 | NM |
| 10/1/2024 | 10/3/2024 | WENDEN STA | 2B | Wenden 2B maintenance | 75 | SM |
| 10/1/2024 | 10/3/2024 | WILLIAMS | 1200, 1201, 1208 | Williams 1C inspection | 225 | NM |
| 10/1/2024 | 10/4/2024 | HUECO STA | 1A | Hueco 1A inspection | 75 | SM |
| 10/1/2024 | 10/4/2024 | HUECO STA | 1100-1103 | Hueco Station DOT/ESD Tests | 157 | SM |

| | | | | | | |
|------------|------------|-----------------|-----------|--|-----|-----|
| 10/1/2024 | 10/31/2024 | 301108 | Line 2121 | Line 2121 Hydrotest - No Current Customer Impact - Southwest Gas - Tierra Verde, Sam Joy, and Bull Head City Gate Deliveries on Temporary Gas Supply | 0 | NM |
| 10/1/2024 | 10/31/2024 | LORDSBURG STA | 2A | Lordsburg 2A repair | 205 | SM |
| 10/3/2024 | 10/4/2024 | CIMARRON STA | STA | Cimarron Station maintenance | 103 | SM |
| 10/7/2024 | 10/11/2024 | WENDEN STA | 1A | Wenden 1A (GE) maintenance | 125 | SM |
| 10/8/2024 | 10/10/2024 | TOM MIX STA | 2000 | Tom Mix Station maintenance | 146 | SM |
| 10/8/2024 | 10/9/2024 | CASA GRANDE | 2C | Casa Grande 2C maintenance | 75 | SM |
| 10/8/2024 | 10/8/2024 | PHOENIX | 2171 | Line 2171 cleaning/smart tools - MLV 1 to MLV 2 - (Mesquite Power Plant) | 80 | PHX |
| 10/8/2024 | 10/8/2024 | FLAGSTAFF - PL | 1201 | Line 1201 smart tool Navajo to Dilkon | 168 | NM |
| 10/8/2024 | 10/10/2024 | WINDOW ROCK | 5B | Window Rock 5B inspection | 32 | NM |
| 10/8/2024 | 10/8/2024 | DUTCH FLATS STA | 1104 | Dutch Flats 1A shut down checks | 50 | HX |
| 10/8/2024 | 10/9/2024 | FLORIDA STA | 1C | Florida 1C inspection | 125 | SM |
| 10/8/2024 | 10/11/2024 | DIMITT STA | 1A | Dimmitt 1A maintenance | 38 | AN |
| 10/8/2024 | 10/8/2024 | PHOENIX | 2171 | Line 2171 smart tool - MLV 1 to MLV 2 - (Mesquite Power Plant) | 80 | PHX |
| 10/9/2024 | 10/9/2024 | HACKBERRY STA | 1204,1200 | Hackberry Station inspection | 250 | NM |
| 10/9/2024 | 10/9/2024 | DUTCH FLATS STA | 1104 | Dutch Flats 2A shut down checks | 50 | HX |
| 10/10/2024 | 10/11/2024 | ORACLE STA | 1A | Oracle Station inspection | 200 | SM |
| 10/10/2024 | 10/10/2024 | DUTCH FLATS STA | 1104 | Dutch Flats Station inspection | 128 | HX |
| 10/10/2024 | 10/10/2024 | DUTCH FLATS STA | 1104 | Dutch Flats Station DOT/ESD Tests | 128 | HX |
| 10/10/2024 | 10/11/2024 | LORDSBURG STA | 1C | Lordsburg 1C maintenance | 125 | SM |
| 10/14/2024 | 11/22/2024 | FLAG-WEST-PL | 1204 | Line 1204 pipeline maintenance MLV 31 to MLV 33.375 | 200 | NM |
| 10/14/2024 | 11/22/2024 | FLAG-WEST-PL | 1208 | Line 1208 pipeline maintenance MLV 31.25 to MLV 33 | 150 | NM |
| 10/14/2024 | 10/18/2024 | AMARILLO PL | 1114 | Line 1114 pipeline maintenance Getty Schafer to Dumas | 75 | AN |
| 10/14/2024 | 10/24/2024 | WILLCOX STA | 2A | Willcox 2A maintenance | 130 | SM |

| | | | | | | |
|------------|------------|----------------|---------|--|-----|-----|
| 10/15/2024 | 10/15/2024 | ODESSA PL | 1115 | Line 1115 maintenance tool run Eunice to Goldsmith 802164 - Buckhorn Receipt - WTGGAS/EPNG (IWTGBUCK) BUCKHORN REC - Customer to zero Dth/d during Line 1115 maintenance tool run 302381 - Phillips Goldsmith Receipt - DCP OPER/EPNG (IPHGOLDS) RES FM PHI - Customer to zero Dth/d during Line 1115 maintenance tool run | 220 | PR |
| 10/15/2024 | 10/16/2024 | AFTON STA | 2A | Afton 2A maintenance | 59 | SM |
| 10/16/2024 | 10/17/2024 | LEUPP | 3C | Leupp 3C maintenance | 100 | NM |
| 10/16/2024 | 11/9/2024 | GALLUP-N ML | 1204 | Line 1204 Hydrotest Window Rock to Navajo | 150 | XO |
| 10/15/2024 | 10/16/2024 | ODESSA PL | 1600 | Line 1600 cleaning tool Waha to Gresham | 400 | PR |
| 10/17/2024 | 10/17/2024 | ODESSA PL | 1600 | Line 1600 smart tool Waha to Gresham | 400 | PR |
| 10/22/2024 | 10/22/2024 | CAPROCK | CAPROCK | Caprock 1A inspection | 75 | XO |
| 10/22/2024 | 10/24/2024 | WINDOW ROCK | 2B | Window Rock 2B inspection | 32 | NM |
| 10/22/2024 | 10/24/2024 | LEUPP | 1B | Leupp 1B inspection | 50 | NM |
| 10/22/2024 | 10/25/2024 | PLAINS STA | STA | Plains Station DOT/ESD Tests - Deliveries cannot be made to INN30PLA, IW40-043, or IMUSTANG; during this outage, no gas can be received at INN26PLA. | 762 | AN |
| 10/23/2024 | 10/23/2024 | CAPROCK | CAPROCK | Caprock 2A inspection | 75 | XO |
| 10/23/2024 | 10/23/2024 | EUNICE B | 1B | Eunice 1B maintenance | 391 | SM |
| 10/24/2024 | 10/24/2024 | EUNICE B | 1B | Eunice 1B maintenance | 140 | SM |
| 10/28/2024 | 12/6/2024 | SAN JUAN PL | 1200 | Line 1200 special permit MLV 0 to MLV 1 | 150 | SJ |
| 10/29/2024 | 10/31/2024 | LEUPP | 6A | Leupp 6A inspection | 50 | NM |
| 10/29/2024 | 10/31/2024 | LEUPP | 11A | Leupp 11A maintenance | 15 | NM |
| 10/29/2024 | 10/31/2024 | ODESSA PL | L3140 | WTG Jameson Receipt (ISUNJAME) - Flow Required During Tool Run - 20 Mmcf/d | 50 | PR |
| 10/29/2024 | 10/29/2024 | BLUEWATER | 3B | Bluewater 3B maintenance | 100 | XO |
| 10/29/2024 | 10/29/2024 | EUNICE C | 3C | Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI | 77 | PR |
| 10/31/2024 | 10/31/2024 | ODESSA PL | L3140 | WTG Jameson Receipt (ISUNJAME) - Flow Required During Tool Run - 20 Mmcf/d | 50 | PR |
| 11/4/2024 | 11/4/2024 | DEMING PL | 1103 | Line 1103 cleaning tool Deming to San Simon | 300 | SM |
| 11/5/2024 | 11/7/2024 | MOJAVE STA | 1900 | Mojave 3A inspection | 117 | MOJ |
| 11/5/2024 | 11/7/2024 | WINDOW ROCK | 6B | Window Rock 6B inspection | 31 | NM |
| 11/5/2024 | 11/7/2024 | SAN JUAN PL | 1218 | Line 1218 smart tool Bondad to MLV 1 | 150 | SJ |
| 11/5/2024 | 11/5/2024 | BONDAD | 1A | Bondad 1A inspection | 175 | SJ |
| 11/5/2024 | 11/5/2024 | DEMING PL | 1103 | Line 1103 smart tool Deming to San Simon | 300 | SM |
| 11/6/2024 | 11/6/2024 | BONDAD | 1B | Bondad 1B inspection | 200 | SJ |

| | | | | | | |
|------------|------------|---------------|------|---|-----|-----|
| 11/7/2024 | 11/7/2024 | DEMING PL | 1103 | Line 1103 smart tool Deming to San Simon | 300 | SM |
| 11/8/2024 | 11/8/2024 | DEMING PL | 1103 | Line 1103 smart tool Deming to San Simon | 512 | SM |
| 11/9/2024 | 11/9/2024 | DEMING PL | 1103 | Line 1103 smart tool Deming to San Simon | 512 | SM |
| 11/11/2024 | 1/5/2025 | TOPOCK-MOJAVE | 1208 | Line 1208 Hydrotest Seligman to Hackberry | 150 | NM |
| 11/12/2024 | 11/19/2024 | WINDOW ROCK | 5A | Window Rock 5A inspection | 32 | NM |
| 11/13/2024 | 11/13/2024 | CARLSBAD PIPE | 3191 | Line 3191 cleaning tool Pecos River to South Carlsbad 334819 - East Loving Receipt - (IELOVING) - Customer to zero Dth/d during tool run. 358846 - Pinn Cpd #2 Receipt - (IPINCPD2) - Customer to zero Dth/d during tool run. 50530 - Higby Hole Receipt - (IHIGBYHL) - Customer to zero Dth/d during tool run. 48862 - Bounds #1 and #2 Receipts - (IBOUNDSR) - Customer to zero Dth/d during tool run. 334853 - Crawford Receipt - (ICRAWFRD) - Customer to zero Dth/d during tool run. 314843 - Fsd South Carlsbad Receipt - (IMLSCARL) - Customer to zero Dth/d during tool run. 334823 - Nueva Vista Receipt - (INUVISTA) - Customer to zero Dth/d during tool run. | 375 | SM |
| 11/13/2024 | 11/13/2024 | SAN JUAN PL | 1212 | Line 1212 smart tool MLV 1 to MLV 3.25 | 150 | SJ |
| 11/13/2024 | 11/14/2024 | SAN JUAN PL | 1212 | Line 1212 cleaning tool MLV 1 to MLV 3.25 | 175 | SJ |
| 11/13/2024 | 11/14/2024 | WENDEN STA | STA | Wenden Station maintenance | 150 | SM |
| 11/14/2024 | 12/14/2024 | PHOENIX | 1100 | Line 1100 pipeline maintenance MLV 77 and MLV 79 | 300 | PHX |

| | | | | | | |
|------------|------------|------------------|------|--|-----|-----|
| 11/14/2024 | 11/14/2024 | CARLSBAD PIPE | 3191 | Line 3191 smart tool Pecos River to South Carlsbad 334819 - East Loving Receipt - (IELOVING) - Customer to zero Dth/d during tool run. 358846 - Pinn Cpd #2 Receipt - (IPINCPD2) - Customer to zero Dth/d during tool run. 50530 - Higby Hole Receipt - (IHIGBYHL) - Customer to zero Dth/d during tool run. 48862 - Bounds #1 and #2 Receipts - (IBOUNDSR) - Customer to zero Dth/d during tool run. 334853 - Crawford Receipt - (ICRAWFRD) - Customer to zero Dth/d during tool run. 314843 - Fsd South Carlsbad Receipt - (IMLSCARL) - Customer to zero Dth/d during tool run. 334823 - Nueva Vista Receipt - (INUVISTA) - Customer to zero Dth/d during tool run. | 375 | SM |
| 11/14/2024 | 12/14/2024 | PHOENIX | 1100 | Line 1100 hydrotest Casa Grande to Gila | 300 | PHX |
| 11/19/2024 | 11/21/2024 | SAN SIMON STA | 3A | San Simon 3A inspection | 20 | SM |
| 12/3/2024 | 12/3/2024 | PHOENIX | 1124 | Line 1124 cleaning tool Casa Grande to South Mountain | 163 | PHX |
| 12/3/2024 | 12/3/2024 | EL PASO D | 4D | El Paso 4D inspection | 150 | SM |
| 12/3/2024 | 12/3/2024 | ROSWELL | 3A | Roswell 3A inspection | 65 | XO |
| 12/3/2024 | 12/17/2024 | WINDOW ROCK | 3B | Window Rock 3B inspection | 32 | NM |
| 12/3/2024 | 12/13/2024 | EL PASO C | 1C | El Paso C Station maintenance | 175 | SM |
| 12/4/2024 | 12/4/2024 | PHOENIX | 1124 | Line 1124 smart tool Casa Grande to South Mountain | 163 | PHX |
| 12/5/2024 | 12/5/2024 | PHOENIX | 1124 | Line 1124 smart tool Casa Grande to South Mountain | 163 | PHX |
| 12/10/2024 | 12/10/2024 | TOM MIX STA | 1A | Tom Mix 1A inspection | 43 | SM |
| 12/17/2024 | 12/18/2024 | FLORIDA STA | 1B | Florida 1B inspection | 75 | SM |
| 12/17/2024 | 12/19/2024 | LEUPP | 4B | Leupp 4B inspection | 50 | NM |
| 12/19/2024 | 12/20/2024 | FLORIDA STA | 2A | Florida 2A inspection | 75 | SM |