

El Paso Pipeline Maintenance Summary

This document lists major maintenance and construction shutdowns that are being planned on the EPNG pipeline system for the next 12 to 15 months. The purpose of this posting is to make customers aware of **proposed outages** that will affect throughput on the various systems of the pipeline. Dates may change based on changing business conditions or to coordinate with outages on interconnecting pipelines. **Comments regarding alternate dates are welcome.**

This document is not intended to be an official notice. When shutdowns are finalized, they will be posted as Informational Postings, found on the El Paso Natural Gas Company Home Page. Refer to those notices for current shutdowns.

This Shutdown Schedule will normally be updated weekly or by special edition if warranted. Please refer to the revision date.

El Paso Natural Gas Co. Shutdown Schedule

dates are tentative and subject to change. See EBB notices for finalized dates and impacts.



Revised: 1/18/2019

Questions? Contact Vic Villalva 719-520-4251

****Possible immediate remediation - a placeholder on the schedule for possible outage for immediate remediation based on an ILI (inline inspection, smart pig) assessment report. The outage (remediation) may or may not take place depending on the report findings. If the report states that an immediate remediation must take place, EPNG will post an update for the impact to the system as soon as possible. TBD (To Be Determined)**

SJ= San Juan Basin - NM=North ML - SM=South ML - XO=San Juan Crossover - PR=Permian YU=Yuma - PHX=Phoenix - HX=Havasus Crossover - AN=Anadarko						
Start Date	End Date	Location	Unit	Description	Reduction in MMcf/d	System
11/7/2013	12/31/2019	WINDOW ROCK	3A	Window Rock 3A repair pending	22	NM
11/11/2013	12/31/2019	CAPROCK	1A	Caprock 1A mechanical repair pending	50	XO
1/1/2014	12/31/2019	AFTON STA	2A	Afton 2 mechanical repair pending	65	SM
1/1/2014	12/31/2019	ROSWELL	1A	Roswell 1A repair pending	10	XO
6/10/2014	12/31/2019	AFTON STA	1A	Afton 1 repair pending	65	SM
1/1/2015	2/1/2019	CASA GRANDE	2C	Casa Grande 2C repair pending	65	SM
1/5/2015	12/31/2019	VAIL STA	1,2,3	Vail Station repair pending	18	SM
7/21/2015	12/31/2019	WILLIAMS	4B	Williams 4B repair pending	10	NM
12/1/2015	12/31/2019	LEUPP	1A	Leupp 1A repair pending	7	NM
12/1/2015	12/31/2019	LEUPP	7A	Leupp 7A mechanical repair pending	7	NM

1/1/2016	12/31/2019	EL PASO D STA	2D	El Paso 2D repair pending	0	SM
2/26/2016	9/30/2019	LEUPP	6A	Leupp 6A repair pending	10	NM
8/4/2016	12/31/2019	MONUMENT STA	1B	Monument 1B Repair Pending	20	SM
11/30/2016	12/31/2019	SAN SIMON STA	3A	San Simon 3 repair pending	50	SM
12/16/2016	12/31/2019	WINDOW ROCK	1A	Window Rock 1A repair pending	22	NM
9/8/2017	12/31/2019	LEUPP	9A	Leupp 9A repair pending	10	NM
9/13/2018	3/15/2019	KEYSTONE	8A	Keystone 8A repair	40	PR
10/19/2018	2/8/2019	AMARILLO	2	Amarillo 2 repair	40	AN
10/26/2018	3/22/2019	KEYSTONE	7A	Keystone 7A repair	40	PR
11/2/2018	4/19/2019	KEYSTONE	1A	Keystone 1A repair	40	PR
11/6/2018	12/31/2019	WINDOW ROCK	1B	Window Rock 1B repair pending	37	NM
11/12/2018	2/22/2019	WAHA STA	2	Waha 2 Solar maintenance	40	PR
11/15/2018	2/8/2019	TUCSON	1103	Line 1103 pipeline remediation Tucson to Casa Grande	129	SM
11/26/2018	2/28/2019	AFTON STA	3A	Afton 3 repair	50	SM
12/2/2018	2/8/2019	DIMMITT STA	1	Dimmitt 1 repair	40	AN
12/6/2018	2/8/2019	DIMMITT STA	2	Dimmitt 2A repair	40	AN
12/6/2018	12/31/2019	PLAINS STA	11	Plains 11A repair pending	57	SM
12/6/2018	12/31/2019	PLAINS STA	13	Plains 13A repair pending	110	SM
12/6/2018	12/31/2019	PLAINS STA	14	Plains 14A repair pending	110	SM
12/13/2018	12/31/2019	BLUEWATER	2	Blue Water 2 repair pending	90	XO
12/18/2018	2/1/2019	PHOENIX	1103	Line 1103 pipeline remediation Tucson to Casa Grande	129	PHX
12/27/2018	1/31/2019	NAVAJO	2D	Navajo 2D repair	120	NM
12/28/2018	1/28/2019	MONUMENT STA	4	Monument 4 Repair	20	SM
1/15/2019	2/8/2019	DEMING PL	1004	Line 1004 pipeline remediation MLV 22 1/2 to MLV 24 Monument 90 (DPMEXIL) shut in alternate scheduling location WILLMEX Delivery Point (IMEXWIL) PIN 398669	0	SM
1/25/2019	2/5/2019	TOPOCK-MOJAVE	L1200	Line 1200 pipeline hydro test Hackberry to MLV 45	136	NM
1/29/2019	1/30/2019	LEUPP	4A	Leupp 4A inspection	11	NM
1/29/2019	1/29/2019	CORNUDAS STA	1C	Cornudas 1C inspection	42	SM
1/30/2019	1/30/2019	CORNUDAS STA	2C	Cornudas 2C inspection	42	SM
1/31/2019	2/1/2019	LEUPP	11A	Leupp 11A inspection	10	NM
2/4/2019	2/8/2019	BONDAD	1A	Bondad 1A maintenance	95	SJ
2/5/2019	2/6/2019	LEUPP	8A	Leupp 8A inspection	10	NM
2/5/2019	2/7/2019	MOJAVE STA	1,2,3A	Unit(s) maintenance 1 at a time	39	MOJ

2/5/2019	2/5/2019	FLORIDA STA	1C	Florida 1C inspection	42	SM
2/5/2019	2/8/2019	WINDOW ROCK	6B	Window Rock 6B inspection	37	NM
2/5/2019	2/13/2019	PHOENIX	1203	Line 1203 pipeline remediation MLV 5 to MLV 5 1/2	28	PHX
2/11/2019	2/21/2019	TOPOCK-MOJAVE	L1201	Line 1201 pipeline hydro test Hackberry to MLV 45	452	NM
2/11/2019	2/15/2019	CORNUDAS STA	1A	Cornudas 1A inspection	36	SM
2/12/2019	2/12/2019	TOPOCK-MOJAVE	1104	Line 1104 smart pig Franconia to Topock	27	NM
2/12/2019	2/12/2019	ROSWELL PL	1300	Line 1300 smart pig Caprock to Roswell	243	XO
2/13/2019	2/17/2019	PHOENIX	1600	Line 1600 pipeline remediation Casa Grande to Wenden		SM
2/14/2019	2/14/2019	TOPOCK-MOJAVE	1104	Line 1104 smart pig Franconia to Topock	27	NM
2/18/2019	2/22/2019	LORDSBURG STA	1B	Lordsburg 1B inspection	46	SM
2/19/2019	2/19/2019	BAKERSFIELD AREA	1905	Line 1905 smart pig Daggett to MLV 315B informational only	0	MOJ
2/19/2019	2/22/2019	KEYSTONE	3B	Keystone 3B inspection	37	PR
2/19/2019	2/22/2019	PECOS RIVER STA	2A	Pecos 2A inspection	110	SM
2/21/2019	2/21/2019	BAKERSFIELD AREA	1905	Line 1905 smart pig Daggett to MLV 315B informational only	0	MOJ
2/25/2019	2/28/2019	KEYSTONE	7A	Keystone 7A inspection	40	PR
2/26/2019	2/28/2019	WILLIAMS	3B	Williams 3B maintenance	100	NM
3/1/2019	3/14/2019	TOPOCK-MOJAVE	L1204	Line 1204 pipeline hydro test Hackberry to MLV 45	660	NM
3/4/2019	3/11/2019	LORDSBURG STA	1C	Lordsburg 1C maintenance	50	SM
3/5/2019	3/5/2019	WILLCOX STA	STA	Willcox Station Annual DOT/ESD Test	210	SM
3/5/2019	3/7/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
3/5/2019	3/7/2019	WILLIAMS	5B	Williams 5B maintenance	100	NM
3/5/2019	3/8/2019	CASA GRANDE	1B	Casa Grande 1B Inspection	104	SM
3/5/2019	3/5/2019	LORDSBURG STA	2A	Lordsburg 2A shut down checks	30	SM
3/5/2019	3/6/2019	PHOENIX	2000	Line 2000 smart pig MLV 41 to EOL	170	SM
3/5/2019	3/6/2019	BLACK RIVER	STA	Black River Station Annual DOT/ESD Test & Shutdown checks	95	SM
3/6/2019	3/6/2019	CASTLE DOME STA	STA	Castle Dome Annual DOT/ESD Test no compression available DSWG YUM Yuma Co -Gen ,Yucca Power PLT DAPS YUM	19	YU
3/6/2019	3/6/2019	WILLCOX STA	1A	Willcox 1A shutdown checks	109	SM

3/6/2019	3/6/2019	LORDSBURG STA	1A	Lordsburg 1A shut down checks	30	SM
3/7/2019	3/7/2019	WILLCOX STA	2A	Willcox 2A shut down checks	109	SM
3/7/2019	3/7/2019	LORDSBURG STA	A	Lordsburg Station "A" DOT/ESD Test	65	SM
3/7/2019	3/8/2019	PHOENIX	2000	Line 2000 smart pig MLV 41 to EOL	170	SM
3/11/2019	3/23/2019	DEMING PL	1103	Line 1103 pipeline remediation Afton to Deming	242	SM
3/11/2019	4/12/2019	PHOENIX	1203	Line 1203 pipeline remediation MLV 7 1/2 to MLV 11	28	PHX
3/12/2019	3/12/2019	TOM MIX STA	1A	Tom Mix 1A inspection	43	SM
3/12/2019	3/12/2019	ROSWELL PL	1300	Line 1300 smart pig Caprock to Roswell	243	XO
3/12/2019	3/13/2019	NAVAJO	STA	Navajo Station "D" Annual DOT/ESD Test	120	NM
3/12/2019	3/14/2019	NAVAJO	STA	Navajo Station "C" Annual DOT/ESD Test	120	NM
3/12/2019	3/12/2019	EUNICE C	3C	Eunice 3C maintenance no flow at ITEXNEUN during this maintenance only. Alternate scheduling location IWAREUNI	0	SM
3/12/2019	3/14/2019	ALAMO LAKE STA	2A	Alamo Lake 2A inspection	100	HX
3/12/2019	3/15/2019	LORDSBURG STA	1A	Lordsburg 1A inspection	30	SM
3/13/2019	3/13/2019	ALAMO LAKE STA	STA	Alamo Lake Station DOT/EST Test	150	HX
3/15/2019	3/15/2019	ROSWELL PL	1300	Line 1300 smart pig Caprock to Roswell	110	XO
3/19/2019	3/19/2019	DUTCH FLATS STA	1A	Dutch 1A mechanical inspection	33	HX
3/19/2019	3/19/2019	HACKBERRY STA	1A	Hackberry 1A shut down checks	83	NM
3/19/2019	3/19/2019	PHOENIX	2055	Line 2055 smart pig MLV 1 to EOL		PHX
3/19/2019	3/19/2019	SAN JUAN PL	1218	Line 1218 ILI cleaning pig MLV 3 5/8 to MLV 4 higher pressures	0	SJ
3/19/2019	3/21/2019	CORNUDAS STA	B	Cornudas Station Annual "B" DOT/ESD Test	119	SM
3/20/2019	3/20/2019	TUCSON	1100	L1100 smart Pig San Simon to Benson	63	SM
3/20/2019	3/20/2019	HACKBERRY STA	2A	Hackberry 2A unit shut down checks	83	NM
3/21/2019	3/21/2019	HACKBERRY STA	STA	Hackberry Station Annual DOT/ESD Test	263	NM
3/26/2019	3/27/2019	DILKON	STA	Dilkon Station Annual DOT/ESD Test	78	NM
3/26/2019	3/28/2019	LEUPP	3B	Leupp 3B inspection	20	NM
3/26/2019	3/26/2019	RIO VISTA	STA	Rio Vista Station Annual DOT/ESD Test	150	SJ
3/26/2019	3/27/2019	EL PASO D STA	4D	El Paso 4D inspection	42	SM
3/26/2019	3/28/2019	EL PASO C STA	C	El Paso Station "C" Annual DOT/ESD Test	50	SM
3/26/2019	3/29/2019	KEYSTONE	1B	Keystone 1B inspection	45	PR

3/27/2019	3/27/2019	RIO VISTA	2A	Rio Vista 2A shut down checks	99	SJ
4/2/2019	4/2/2019	BONDAD	STA A	Bondad Station "A" DOT/ESD Test	466	SJ
4/2/2019	4/2/2019	EUNICE B	STA B	Eunice Station B Annual DOT/ESD Test	50	PR
4/2/2019	4/3/2019	BONDAD	STA B	Station "B" DOT/ESD Test	200	SJ
4/3/2019	4/4/2019	LORDSBURG STA	1B	Lordsburg Station B Annual DOT/ESD & Shut down checks	46	SM
4/8/2019	4/15/2019	FLAGSTAFF - PL	1201	L1201 pipeline remediation Navajo to Dilkon	503	NM
4/9/2019	4/9/2019	SAN SIMON STA	STA	San Simon Station Annual DOT/ESD Test	139	SM
4/9/2019	4/11/2019	MOJAVE STA	1,3A	Mojave Unit(s) maintenance	39	MOJ
4/9/2019	4/9/2019	DIMMIT STA	STA	Dimmit Station Annual DOT/ESD Test	65	AN
4/9/2019	4/9/2019	FLORIDA STA	1A	Florida 1A shutdown checks	22	SM
4/9/2019	4/9/2019	TUCSON	1100	Line 1100 smart pig San Simon to Benson	106	SM
4/9/2019	4/9/2019	CASA GRANDE	1B	Casa Grande 1B shut down checks	104	SM
4/9/2019	4/9/2019	CASA GRANDE	1C	Casa Grande 1C shutdown checks	65	SM
4/9/2019	4/9/2019	CARLSBAD PIPE	3191	Line 3191 maintenance pig South Carlsbad to Pecos River flow will be restricted for 5 hrs 35 mmcf rate		SM
4/9/2019	4/11/2019	EUNICE C	2C	Eunice 2C inspection	40	SM
4/9/2019	4/13/2019	WASHINGTON RANCH	STA	Washington Ranch Spring BHP Survey No injection or withdrawal	250	SM
4/10/2019	4/10/2019	SAN SIMON STA	UNIT #1	San Simon 1 shut down check	10	SM
4/10/2019	4/10/2019	ODESSA PL	3133	Line 3133 maintenance pig Sweetie Peck to Goldsmith	0	PR
4/10/2019	4/11/2019	CASA GRANDE	STA	Casa Grande Station Annual DOT/ESD Test	210	SM
4/11/2019	4/11/2019	SAN SIMON STA	UNIT #2	San Simon 2 shutdown checks	10	SM
4/11/2019	4/11/2019	FLORIDA STA	STAA	Florida Station A Annual DOT/ESD Test	65	SM
4/15/2019	4/28/2019	DEMING PL	2000	Line 2000 hydro test Afton to Lordsburg	606	SM
4/16/2019	4/16/2019	SAN JUAN PL	1218	Line 1218 ILI pig MLV 3 5/8 to MLV 4 higher pressures	0	SJ
4/16/2019	4/16/2019	SCHAFFER	STA	Station Annual DOT/ESD Test and Unit shutdown checks	50	AN
4/16/2019	4/17/2019	CIMARRON STA	STA	Cimarron Station Annual DOT/ESD Test	50	SM
4/16/2019	5/4/2019	FLAGSTAFF - PL	1204	Line 1204 pipeline remediation Navajo to Leupp	636	NM
4/16/2019	4/19/2019	SCHAFFER	1A	Schafer 1 inspection	25	AN
4/16/2019	4/16/2019	SAN JUAN PL	1205	Line 1205 maintenance pig Bondad to VIV 1 pressures will be higher	0	SJ
4/16/2019	4/17/2019	FLORIDA STA	1C	Florida C DOT/ESD Test	40	SM
4/16/2019	4/18/2019	EUNICE C	1C	Eunice C1 inspection	40	SM
4/16/2019	5/30/2019	KEYSTONE	1A	Keystone 1A inspection	66	PR
4/16/2019	4/16/2019	SAN JUAN PL	1218	Line 1218 maintenance pig Bondad to VLV 1 pressures will be higher	0	SJ

4/23/2019	4/23/2019	TOPOCK-MOJAVE	1204-1113	Line 1104 smart pig Hackberry to Franconia	155	NM
4/23/2019	4/24/2019	FLAGSTAFF	STA	Flagstaff Station Annual DOT/ESD Test	117	NM
4/23/2019	4/23/2019	PLAINS PL	30125/3026	Line 3026/30125 smart pig Keystone to Eunice Jal 3 (IJALCPLX), Jal Alley(DJALALLY) , Dollarhide (IUTDOLHD), Grobe (ITXGROBE) , Meyers(DTEX JAL) temporary shut in	0	SM
4/23/2019	4/24/2019	DAGGETT STA	STA	Daggett Station Annual ESD/DOT Test	58	MOJ
4/23/2019	4/26/2019	KEYSTONE	9AA	Keystone 9A inspection	37	PR
4/25/2019	4/25/2019	TOPOCK-MOJAVE	1204-1113	Line 1104 smart pig Hackberry to Franconia	155	NM
4/25/2019	4/25/2019	DAGGETT STA	STA	Daggett Station reliability Test MUST RUN	0	MOJ
4/30/2019	4/30/2019	PHOENIX	1100	Line 1100 smart pig MLV Casa Grande to Wenden		PHX
4/30/2019	4/30/2019	WINDOW ROCK	STA B	Window Rock Station B Annual DOT/ESD Test	190	NM
4/30/2019	5/1/2019	WINDOW ROCK	STA A	Window Rock Station A Annual DOT/ESD Test	314	NM
4/30/2019	5/2/2019	WINDOW ROCK	7A	Window Rock 7A Shut down checks	245	NM
4/30/2019	5/3/2019	KEYSTONE	3A	Keystone 3A inspection	37	PR
5/1/2019	5/1/2019	WINDOW ROCK	7A	Window Rock 7A inspection	37	NM
5/1/2019	5/2/2019	CORNUDAS STA	C	Cornudas Station C Annual DOT/ESD Test	83	SM
5/2/2019	5/2/2019	CORNUDAS STA	1C	Cornudas 1C inspection	42	SM
5/3/2019	5/3/2019	CORNUDAS STA	2C	Cornudas 2C inspection	42	SM
5/4/2019	5/4/2019	PHOENIX	1100	Line 1100 smart pig Casa Grande to Wenden	TBD	PHX
5/6/2019	5/19/2019	FLAGSTAFF - PL	2217	Line 2217 pipeline remediation South West Forest Lateral	TBD	NM
5/6/2019	5/31/2019	HUECO STA	2A	Hueco 2A maintenance	80	SM
5/7/2019	5/7/2019	PHOENIX	1100	Line 1100 smart pig Casa Grande to Wenden	TBD	PHX
5/7/2019	5/7/2019	TOPOCK-MOJAVE	1204-1113	Line 1104 smart pig Hackberry to Franconia	155	NM
5/7/2019	5/7/2019	WENDEN STA	2A	Wenden 2A shut down checks	65	HX
5/7/2019	5/9/2019	MOJAVE STA	1A	Mojave 1 inspection	117	MOJ
5/7/2019	5/9/2019	MONUMENT STA	STA	Monument Station Annual DOT/ESD Test	50	PR
5/8/2019	5/8/2019	WENDEN STA	STA	Wenden Station Annual DOT/ESD Test	175	HX
5/9/2019	5/9/2019	PHOENIX	1100	Line 1100 smart pig Casa Grande to Wenden	TBD	PHX
5/9/2019	5/9/2019	ALAMO LAKE STA	1A	Alamo Lake 1A inspection	75	HX

5/14/2019	5/14/2019	Flag-West-PL	1200	Line 1200 cleaning/gauge pig Dilkon to Flagstaff	14	NM
5/14/2019	5/15/2019	SELIGMAN	STA	Seligman Station Annual DOT/ESD Test	170	NM
5/14/2019	5/15/2019	GALLUP	1C	Gallup Station C Annual DOT/ESD Test	433	SJ
5/14/2019	5/14/2019	SAN JUAN PL	1218	Line 1218 maintenance pig MLV 2 to MLV 3 1/2 higher pressures	0	SJ
5/14/2019	5/14/2019	GALLUP	1B	Gallup Station B DOT/ESD Test	75	SJ
5/14/2019	5/14/2019	BLANCO A	STA	Blanco Station DOT/ESD Test	400	SJ
5/14/2019	5/16/2019	MOJAVE STA	1,2,3A	Mojave Unit(S) shut down checks 1 at a time	39	MOJ
5/14/2019	5/17/2019	CORNUDAS STA	STAA	Cornudas Station A Annual DOT/ESD Test	174	SM
5/15/2019	5/17/2019	GRESHAM	STA	Gresham Station Annual DOT/ESD Test	66	SM
5/21/2019	5/24/2019	SCHAFER	2	Schafer 2 inspection	25	AN
5/21/2019	5/21/2019	MOJAVE STA	STA	Mojave Station Annual ESD/DOT Test	375	MOJ
5/21/2019	5/21/2019	PLAINS PL	30125/3026	Line 3026/30125 smart pig Keystone to Eunice Jal 3 (IJALCPLX), Jal Alley(DJALALLY) , Dollarhide (IUTDOLHD), Grobe (ITXGROBE) , Meyers(DTEX JAL) temporary shut in	0	SM
5/21/2019	5/24/2019	PECOS RIVER STA	STA	Pecos Station Annual DOT/ESD Test	150	SM
5/21/2019	5/24/2019	WINDOW ROCK	5B	Window Rock 5B inspection	23	NM
5/21/2019	5/24/2019	PECOS RIVER STA	1A	Pecos 1A inspection	35	SM
5/22/2019	5/22/2019	CAPROCK	STA	Caprock Station Annual DOT/ESD Test	40	XO
5/23/2019	5/23/2019	ROSWELL PL	1300	L1300 smart pig Lincoln to Belen	110	XO
5/24/2019	5/24/2019	PLAINS PL	30125/3026	Line 3026/30125 smart pig Keystone to Eunice Jal 3 (IJALCPLX), Jal Alley(DJALALLY) , Dollarhide (IUTDOLHD), Grobe (ITXGROBE) , Meyers(DTEX JAL) temporary shut in	0	SM
5/28/2019	6/8/2019	DEMING PL	1103	Line 1103 pipeline remediation EL Paso to Afton	275	SM
5/30/2019	5/30/2019	ODESSA PL	3006	Line 3006 maintenance pig Goldsmith to Keystone Field	0	PR
6/3/2019	6/7/2019	PUCKETT	1A	Puckett Station DOT/ESD Test gas from ITERRELL, IMLTERPK and IYUCBUTE must be routed to Wink thru Line 2000 instead of Waha and will be limited to a total of 98,000 Dthd.	135	SM
6/4/2019	6/4/2019	SAN JUAN PL	1205	Line 1205 maintenance pig Bondad to MLV 3 3/4 higher pressures	0	SJ
6/4/2019	6/4/2019	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	PR
6/4/2019	6/5/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
6/4/2019	6/6/2019	BLUEWATER	STA	Blue Water Station Annual DOT/ESD Test	90	XO
6/4/2019	6/6/2019	EUNICE C	STAC	Eunice C Station Annual DOT/ESD Test	240	PR

6/4/2019	6/7/2019	EL PASO D STA	D	El Paso Station D DOT/ESD Test	92	SM
6/4/2019	6/7/2019	WINDOW ROCK	4A	Window Rock 4A inspection	37	NM
6/5/2019	6/5/2019	SAN JUAN PL	1218	Line 1218 maintenance pig MLV 3 1/2 to MLV 3 3/4 higher pressures	0	SJ
6/6/2019	6/6/2019	GALLUP-SAN JUAN X PL	L1301	Line 1300 smart pig Laguna to Bluewater	30	XO
6/10/2019	6/14/2019	DIMMITT STA	2A	Dimmitt 2A inspection	30	AN
6/11/2019	6/11/2019	DUMAS STA	STA	Dumas Station Annual DOT/ESD Test	50	AN
6/11/2019	6/11/2019	Flag-West-PL	1200	Line 1200 smart pig Dilkon to Flagstaff	14	NM
6/11/2019	6/13/2019	MOJAVE STA	2A	Mojave 2A inspection	117	MOJ
6/11/2019	6/14/2019	HUECO STA	STAALL	Hueco Station Annual ESD/DOT Test & Unit shut down checks	70	SM
6/14/2019	6/14/2019	Flag-West-PL	1200	Line 1200 smart pig Dilkon to Flagstaff	14	NM
6/14/2019	6/14/2019	Flag-West-PL	1200	Line 1200 cleaning/gauge pig Dilkon to Flagstaff	7	NM
6/18/2019	6/18/2019	GALLUP-SAN JUAN X PL	L1301	Line 1301 smart pig Laguna to Bluewater	30	XO
6/18/2019	6/18/2019	Flag-West-PL	1200	Line 1200 smart pig Dilkon to Flagstaff	7	NM
6/20/2019	6/20/2019	GALLUP-SAN JUAN X MEAS	L1301	Line 1301 smart pig Laguna to Bluewater	30	XO
6/20/2019	6/20/2019	Flag-West-PL	1200	Line 1200 smart pig MLV 31 to Seligman	7	NM
6/21/2019	6/21/2019	GALLUP-SAN JUAN X MEAS	L1301	Line 1301 smart pig Laguna to Bluewater	30	XO
6/25/2019	6/27/2019	AFTON STA	STA	Afton Station Annual DOT/ESD Test	65	SM
6/25/2019	6/25/2019	SAN JUAN	STA	San Juan Station DOT/ESD Test	30	SJ
6/25/2019	6/28/2019	KEYSTONE	5A	Keystone 5A inspection	40	PR
7/9/2019	7/9/2019	SAN JUAN PL	1212	Line 1212 maintenance pig pressures will be higher Blanco	0	SJ
7/9/2019	7/9/2019	Flag-West-PL	1204	Line 1204 smart pig Leupp to Flagstaff	47	NM
7/9/2019	7/10/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
7/9/2019	7/11/2019	WHITE ROCK	STA	White Rock Station DOT/ESD Test	259	SJ
7/9/2019	7/12/2019	WINDOW ROCK	5A	Window Rock 5A inspection	22	NM
7/10/2019	7/10/2019	TOM MIX STA	1A	Tom Mix 1A inspection	43	SM
7/10/2019	7/10/2019	SAN JUAN PL	1212	Line 1212 maintenance pig VLV 1 to VLV 3 1/2 pressures will be higher	0	SJ
7/10/2019	7/10/2019	ODESSA PL	1105	Line 1105 maintenance pig Benedum Junction to MP 51 IBOBCAT will go to zero during run pressures will be higher	0	PR
7/11/2019	7/11/2019	ODESSA PL	1105	Line 1105 maintenance pig MP 51 to Keystone	0	PR
7/11/2019	7/11/2019	Flag-West-PL	1204	Line 1204 smart pig Leupp to Flagstaff	47	NM
7/16/2019	7/18/2019	MOJAVE STA	3A	Mojave Unit 3A inspection	117	MOJ
7/17/2019	7/18/2019	ODESSA PL	3082	Line 3082 maintenance pig Goldsmith to Keystone Field	0	PR
7/17/2019	7/17/2019	LINCOLN	STA	Lincoln Station Annual DOT/ESD Test	70	XO

7/23/2019	7/23/2019	Flag-West-PL	1204	Line 1200 smart pig MLV 31 to Williams	30	NM
7/23/2019	7/24/2019	LEUPP	2A	Leupp 2A inspection	8	NM
7/23/2019	7/23/2019	SAN JUAN PL	1205	Line 1205 ILI Cleaning Bondad to MLV 3 3/4 higher pressures	70	SJ
7/23/2019	7/26/2019	KEYSTONE	12A	Keystone 12A inspection	40	PR
8/1/2019	8/2/2019	BELEN	STA	Belen Station Annual DOT/ESD Test	70	XO
8/5/2019	8/5/2019	Flag-West-PL	1201	Line 1201 smart pig Dilkon to Flagstaff	161	NM
8/5/2019	8/25/2019	DEMING PL	1004	RCT L1004 MP 76+5141 to 76+5256	0	SM
8/6/2019	8/7/2019	WILLCOX STA	2A	Willcox 2A inspection	109	SM
8/6/2019	8/8/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
8/6/2019	8/9/2019	Flag-West-PL	1201	Line 1201 smart pig Dilkon to Flagstaff	161	NM
8/6/2019	8/6/2019	SAN JUAN PL	1219	Line 1219 maintenance pig Chaco to White Rock	0	SJ
8/6/2019	8/9/2019	KEYSTONE	6A	Keystone 6A inspection	33	PR
8/7/2019	8/7/2019	SAN JUAN PL	1202	Line 1202 maintenance pig Blanco to White Rock pressures will be higher	0	SJ
8/8/2019	8/8/2019	Flag-West-PL	1201	Line 1201 smart pig Dilkon to Flagstaff	161	NM
8/8/2019	8/9/2019	LAGUNA	STA	Laguna Station Annual DOT/ESD Test	97	XO
8/13/2019	8/14/2019	LEUPP	5B	Leupp 5B inspection	20	NM
8/15/2019	8/15/2019	SAN JUAN PL	1205	Line 1205 ILI tool Bondad to MLV 3 3/4 higher pressures	70	SJ
8/20/2019	8/20/2019	Flag-West-PL	1204	Line 1200 smart pig MLV 31 to Williams	30	NM
8/20/2019	8/21/2019	LEUPP	10A	Leupp 10A inspection	10	NM
8/20/2019	8/23/2019	WINDOW ROCK	2B	Window Rock 2B inspection	13	NM
8/23/2019	8/23/2019	Flag-West-PL	1204	Line 1200 smart pig MLV 31 to Williams	30	NM
8/27/2019	8/27/2019	TOM MIX STA	1A	Tom Mix 1 shut down checks	43	SM
8/27/2019	8/28/2019	LEUPP	2B	Leupp 2B inspection	10	NM
8/27/2019	8/29/2019	PECOS RIVER STA	3A	Pecos River 3 inspection	32	SM
8/28/2019	8/28/2019	CASA GRANDE	1C	Casa Grande 1C inspection	114	SM
9/4/2019	9/5/2019	LEUPP	3A	Leupp 3A inspection	2	NM
9/5/2019	9/12/2019	WASHINGTON RANCH	STA	Washington Ranch Fall BHP Survey no injection or withdrawal	250	SM
9/6/2019	9/6/2019	ODESSA PL	1115	Line 1115 maintenance pig Goldsmith to L1102	0	PR
9/10/2019	9/12/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
9/10/2019	9/10/2019	ALAMO LAKE STA	1A	Alamo Lake 1A inspection	75	HX
9/10/2019	9/10/2019	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	PR
9/10/2019	9/13/2019	CORNUDAS STA	2A	Cornudas 2A inspection	80	SM
9/10/2019	9/13/2019	WINDOW ROCK	4B	Window Rock 4B inspection	15	NM

9/17/2019	9/17/2019	CIMARRON STA	1	Cimarron 1 inspection	88	SM
9/17/2019	9/18/2019	LEUPP	5A	Leupp 5A inspection	2	NM
9/17/2019	9/20/2019	KEYSTONE	STA	Keystone Station Annual DOT/ESD Test	611	PR
9/17/2019	9/17/2019	ODESSA PL	3028	Line 3028 maintenance pig Goldsmith to Keystone Field	0	PR
9/17/2019	9/17/2019	ODESSA PL	3161	Line 3161 maintenance pig Mobil Coyanosa to Waha	0	PR
9/17/2019	9/19/2019	HACKBERRY STA	1A	Hackberry 1 inspection	66	NM
9/19/2019	9/19/2019	ODESSA PL	3146	Line 3146 maintenance pig Puckett to Line 1105	0	PR
9/23/2019	9/27/2019	SELIGMAN	STAC	Seligman C Station maintenance		NM
9/24/2019	9/25/2019	LEUPP	1B	Leupp 1B inspection	10	NM
9/24/2019	9/24/2019	TUCSON	2000	L2000 smart pig Cimarron to Tom Mix		SM
9/24/2019	9/24/2019	EL PASO D STA	4D	El Paso 4D inspection	42	SM
9/26/2019	9/27/2019	ODESSA PL	3173	Line 3153 maintenance pig Terrell to Puckett	0	PR
9/30/2019	10/27/2019	BAKERSFIELD AREA	1905	Line 1104 smart pig Franconia to Alamo Lake	TBD	NM
10/1/2019	10/3/2019	KEYSTONE	8A	Keystone 8A inspection	35	PR
10/1/2019	10/4/2019	WINDOW ROCK	2A	Window Rock 2A inspection	22	NM
10/2/2019	10/2/2019	ROSWELL	STA	Roswell Station Annual DOT/ESD Test	65	XO
10/2/2019	10/2/2019	BLACK RIVER	1	Black River 1 inspection	119	SM
10/8/2019	10/10/2019	PICACHO STA	1,2,3A	Picacho Station Annual DOT/ESD Test	0	PHX
10/8/2019	10/10/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
10/8/2019	10/11/2019	WINDOW ROCK	6A	Window Rock 6A inspection	37	NM
10/8/2019	10/11/2019	GUADALUPE STA	STA	Guadalupe Station DOT/ESD Test	160	SM
10/15/2019	10/18/2019	KEYSTONE	2A	Keystone 2A inspection	44	PR
10/15/2019	10/15/2019	WINK	STA	Wink Station Annual DOT/ESD Test	268	SM
10/15/2019	10/15/2019	DAGGETT STA	STA	Daggett Station reliability test must run	0	MOJ
10/16/2019	10/16/2019	DUTCH FLATS STA	2A	Dutch Flats 2A shut down checks	33	HX
10/16/2019	10/16/2019	ODESSA PL	1103	Line 1103 smart pig Guadalupe to Cornudas	0	PR
10/16/2019	10/16/2019	BONDAD	2A	Bondad 2A inspection	95	SJ
10/17/2019	10/17/2019	DUTCH FLATS STA	STA	Dutch Flats Station Annual DOT/ESD Test	107	HX
10/17/2019	10/17/2019	BONDAD	1B	Bondad 1B inspection	95	SJ
10/21/2019	10/25/2019	BONDAD	1A	Bondad 1A inspection	95	SJ
10/22/2019	10/25/2019	KEYSTONE	2B	Keystone 2B inspection	70	PR
10/31/2019	10/31/2019	ODESSA PL	2000	Line 2000 maintenance pig Black River to Guadalupe	0	PR
11/1/2019	11/1/2019	ODESSA PL	3173	Line 3173 maintenance pig Puckett to Waha	0	PR
11/4/2019	11/4/2019	ODESSA PL	3160	Line 3160 maintenance pig Mobil Coyanosa to Waha	0	PR

11/5/2019	11/7/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
11/5/2019	11/5/2019	WENDEN STA	2A	Wenden 2A inspection	39	HX
11/5/2019	11/7/2019	FLORIDA STA	2A	Florida 2A inspection	22	SM
11/5/2019	11/17/2019	EHRENBERG	1100	Line 1100 pipeline replacement	TBD	SM
11/6/2019	11/6/2019	TOM MIX STA	1A	Tom Mix 1A inspection	43	SM
11/12/2019	11/13/2019	ORACLE STA	1	Oracle 1 inspection	105	SM
11/12/2019	11/13/2019	WILLIAMS	3B	Williams 3B inspection	25	NM
11/19/2019	11/19/2019	LORDSBURG STA	1C	Lordsburg 1C inspection	42	SM
12/3/2019	12/4/2019	BOWIE STA	1	Bowie 1 inspection	38	SM
12/3/2019	12/5/2019	MOJAVE STA	1,2,3A	Mojave Unit(s) maintenance	39	MOJ
12/3/2019	12/5/2019	FLORIDA STA	1A	Florida 1A inspection	22	SM
12/10/2019	12/11/2019	TOM MIX STA	2A	Tom Mix 2 inspection	43	SM
12/10/2019	12/10/2019	DAGGETT STA	STA	Daggett Station reliability Test MUST RUN	0	MOJ
12/10/2019	12/10/2019	EUNICE C	3C	Eunice 3C mechanical Inspection no flow at ITEXNEUN (377034) during this maintenance only. Alternate scheduling location IWAREUNI	0	SM
12/10/2019	12/12/2019	KEYSTONE	10A	Keystone 10A inspection	40	PR
12/12/2019	12/12/2019	ODESSA PL	3114	L3114 maintenance pig higher pressures	0	PR
12/17/2019	12/17/2019	DUTCH FLATS STA	2A	Dutch Flats 2A inspection	33	HX
12/17/2019	12/17/2019	CORNUDAS STA	1C	Cornudas 1C inspection	42	SM
12/18/2019	12/18/2019	CORNUDAS STA	2C	Cornudas 2C inspection	42	SM
12/27/2019	12/27/2019	ODESSA PL	3114	Line 3105/3104 maintenance pig to Sweetie Peck Junction	0	PR
12/27/2019	12/27/2019	ODESSA PL	3137	Line 3137 maintenance pig Benedum to Sweetie Peck higher pressures	0	PR