


# El Paso Natural Gas Company, L.L.C.'s (El Paso)

## Proposed Maintenance and Construction Outage Impact Summary

This document lists proposed outages for major maintenance and construction that are being planned on El Paso's system for the next 12 to 15 months. The purpose of this posting is to inform customers of proposed outages that will affect throughput on El Paso's system. All dates are tentative and subject to change. Consistent with prudent operations, dates may change based on a number of factors including, but not limited to, weather, contractor or material availability, changing business conditions, minimizing adverse impact to shippers, or to coordinate with outages on interconnecting pipelines. Comments regarding alternate dates are welcome. Generally, this proposed outage schedule will be updated weekly and may be updated more often, if warranted. Please refer to the revision date to differentiate the schedules.

This document is not intended to be an official notice of the outage. When outages are scheduled, they will be included in the monthly maintenance report and posted on El Paso's Electronic Bulletin Board (EBB) under Planned Service Outage as well as a Critical Notice, both located in the Notices section of the Informational Postings tab on EPNG's EBB. Shippers should refer to this report for current outages. El Paso's EBB Home Page will also have information and links to access the information.

This schedule does not include outages associated with a declared Force Majeure event. A Force Majeure event will be communicated through a Critical Notice in the Notice section of the Informational Postings tab on El Paso's EBB in addition to updated information in the monthly maintenance notice mentioned above.



Revised: 3/26/2026

Questions? Call John Althoff 719-667-7750

| Start Date | End Date   | Location     | Unit | Maintenance Activity          | Reduction in MMcf/d | Oregion |
|------------|------------|--------------|------|-------------------------------|---------------------|---------|
| 11/7/2013  | 12/31/2026 | WINDOW ROCK  | 3A   | Window Rock 3A repair pending | 35                  | NM      |
| 7/21/2015  | 12/31/2026 | WILLIAMS     | 4B   | Williams 4B repair pending    | 35                  | NM      |
| 12/1/2015  | 12/31/2026 | LEUPP        | 1A   | Leupp 1A repair pending       | 25                  | NM      |
| 8/4/2016   | 12/31/2026 | MONUMENT STA | 1B   | Monument 1B repair pending    | 20                  | PR      |
| 9/8/2017   | 12/31/2026 | LEUPP        | 9A   | Leupp 9A repair pending       | 25                  | NM      |
| 1/1/2018   | 12/31/2026 | CASA GRANDE  | 1A   | Casa Grande 1A repair pending | 42                  | SM      |

|           |            |                 |      |                                                                                  |     |     |
|-----------|------------|-----------------|------|----------------------------------------------------------------------------------|-----|-----|
| 11/6/2018 | 12/31/2026 | WINDOW ROCK     | 1B   | Window Rock 1B repair pending                                                    | 35  | NM  |
| 7/7/2025  | 3/31/2026  | DIMMITT         | 2A   | Dimmitt 2A maintenance                                                           | 20  | AN  |
| 3/9/2026  | 4/12/2026  | PHOENIX         | 1103 | Line 1103 pipeline remediation Casa Grande to Wenden                             | 300 | PHX |
| 3/9/2026  | 4/12/2026  | EHRENBERG       | 1103 | Line 1103 pipeline remediation Gila to Wenden                                    | 400 | SM  |
| 3/10/2026 | 3/27/2026  | ODESSA PL       | 3028 | Line 3028 pipeline remediation                                                   | 150 | PR  |
| 3/11/2026 | 5/15/2026  | CARLSBAD PIPE   | 1100 | Line 1100 pipeline remediation Pecos River to Guadalupe - MLV 9 to MLV 12        | 121 | PR  |
| 3/22/2026 | 3/27/2026  | PECOS RIVER STA | 2A   | Pecos River 2A maintenance                                                       | 75  | SM  |
| 3/24/2026 | 3/26/2026  | LEUPP           | 1201 | Leupp 1B inspection                                                              | 50  | NM  |
| 3/24/2026 | 3/26/2026  | LORDSBURG STA   | STA  | Lordsburg A Station DOT/ESD Tests                                                | 175 | SM  |
| 3/24/2026 | 3/26/2026  | LEUPP           | 1201 | Leupp 1B maintenance                                                             | 50  | NM  |
| 3/24/2026 | 3/27/2026  | EUNICE C        | STA  | Eunice C Station DOT/ESD Tests                                                   | 240 | PR  |
| 3/24/2026 | 3/26/2026  | LORDSBURG STA   | 1A   | Lordsburg 1A DOT/ESD Tests                                                       | 75  | SM  |
| 3/24/2026 | 3/26/2026  | LORDSBURG STA   | 2A   | Lordsburg 2A DOT/ESD Tests                                                       | 75  | SM  |
| 3/24/2026 | 3/27/2026  | EL PASO D       | STA  | El Paso D Station DOT/ESD Tests                                                  | 450 | SM  |
| 3/24/2026 | 3/28/2026  | EL PASO         | 1100 | Line 1100 pipeline maintenance El Paso Area                                      | 490 | SM  |
| 3/26/2026 | 3/26/2026  | VAIL STA        | 2A   | Vail 2A DOT/ESD Tests                                                            | 75  | SM  |
| 3/26/2026 | 3/26/2026  | TUCSON          | 1100 | Line 1100 smart tool Benson to Vail                                              | 400 | SM  |
| 3/27/2026 | 3/27/2026  | TUCSON          | 1100 | Line 1100 smart tool Benson to Vail                                              | 400 | SM  |
| 3/30/2026 | 3/30/2026  | HACKBERRY STA   | 1A   | Hackberry 1A DOT/ESD Tests                                                       | 83  | NM  |
| 3/31/2026 | 4/2/2026   | LEUPP           | STA  | Leupp C&D Stations DOT/ESD Tests                                                 | 108 | NM  |
| 3/31/2026 | 4/2/2026   | LEUPP           | STA  | Leupp Station DOT/ESD Tests                                                      | 108 | NM  |
| 3/31/2026 | 3/31/2026  | HACKBERRY STA   | 2A   | Hackberry 2A DOT/ESD Tests                                                       | 83  | NM  |
| 4/1/2026  | 4/1/2026   | HACKBERRY STA   | STA  | Hackberry Station DOT/ESD Tests                                                  | 263 | NM  |
| 4/1/2026  | 6/30/2026  | KEYSTONE        | 2B   | Keystone 2B maintenance                                                          | 50  | PR  |
| 4/6/2026  | 4/14/2026  | PHOENIX         | 1007 | Line 1007 pipeline maintenance - Rustler's Roost                                 | 50  | PHX |
| 4/6/2026  | 4/17/2026  | FLAG-WEST-PL    | 2208 | Line 2208 pipeline maintenance - No current capacity impact - Informational Only | 0   | NM  |
| 4/6/2026  | 4/9/2026   | HACKBERRY STA   | 2A   | Hackberry 2A maintenance                                                         | 150 | NM  |
| 4/7/2026  | 4/10/2026  | SAN SIMON STA   | STA  | San Simon Station DOT/ESD Tests                                                  | 275 | SM  |
| 4/7/2026  | 4/7/2026   | BONDAD          | 2A   | Bondad 2A DOT/ESD Tests                                                          | 75  | SJ  |
| 4/7/2026  | 4/7/2026   | BONDAD          | 1A   | Bondad 1A DOT/ESD Tests                                                          | 75  | SJ  |
| 4/7/2026  | 4/7/2026   | BONDAD          | 1B   | Bondad B Station DOT/ESD Tests                                                   | 150 | SJ  |

|           |           |                    |      |                                                                                                                                                                                                       |     |    |
|-----------|-----------|--------------------|------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|----|
| 4/7/2026  | 4/7/2026  | BONDAD             | STA  | Bondad B Station DOT/ESD Tests                                                                                                                                                                        | 727 | SJ |
| 4/7/2026  | 4/7/2026  | BONDAD             | STA  | Bondad A Station DOT/ESD Tests                                                                                                                                                                        | 727 | SJ |
| 4/7/2026  | 4/8/2026  | EUNICE C           | STA  | Eunice B Station DOT/ESD Tests                                                                                                                                                                        | 100 | PR |
| 4/7/2026  | 4/9/2026  | WAHA               | STA  | Waha Station DOT/ESD Tests                                                                                                                                                                            | 436 | SM |
| 4/7/2026  | 4/11/2026 | EL PASO            | 1103 | Line 1103 pipeline maintenance El Paso                                                                                                                                                                | 667 | SM |
| 4/7/2026  | 4/9/2026  | DIMMITT            | STA  | Dimmitt Station DOT/ESD Tests                                                                                                                                                                         | 150 | AN |
| 4/8/2026  | 4/8/2026  | SAN SIMON<br>STA   | 3A   | San Simon 3A DOT/ESD Tests                                                                                                                                                                            | 50  | SM |
| 4/8/2026  | 4/8/2026  | SAN SIMON<br>STA   | 1A   | San Simon 1A DOT/ESD Tests                                                                                                                                                                            | 50  | SM |
| 4/8/2026  | 4/9/2026  | CASTLE DOME<br>STA | STA  | Castle Dome Annual DOT/ESD Test no compression available<br>DSWG YUM Yuma Co -Gen ,Yucca Power PLT DAPS YUM                                                                                           | 50  | YU |
| 4/9/2026  | 4/9/2026  | SAN SIMON<br>STA   | 2A   | San Simon 2A DOT/ESD Tests                                                                                                                                                                            | 50  | SM |
| 4/14/2026 | 4/15/2026 | WILLCOX STA        | 1A   | Willcox 2A inspection                                                                                                                                                                                 | 130 | SM |
| 4/14/2026 | 4/16/2026 | SAN SIMON<br>STA   | 2A   | San Simon 2A maintenance                                                                                                                                                                              | 75  | SM |
| 4/14/2026 | 4/14/2026 | FLAG-WEST-PL       | 1200 | Line 1200 cleaning tool Flagstaff to Seligman                                                                                                                                                         | 250 | NM |
| 4/14/2026 | 4/16/2026 | NAVAJO             | STA  | Navajo Station D Station DOT/ESD Tests                                                                                                                                                                | 120 | NM |
| 4/14/2026 | 4/16/2026 | NAVAJO             | STA  | Navajo Station C Station DOT/ESD Tests                                                                                                                                                                | 120 | NM |
| 4/14/2026 | 4/17/2026 | WINDOW<br>ROCK     | 4B   | Window Rock 4B inspection                                                                                                                                                                             | 32  | NM |
| 4/14/2026 | 4/15/2026 | LORDSBURG<br>STA   | 1B   | Lordsburg B Station DOT/ESD Tests                                                                                                                                                                     | 65  | SM |
| 4/14/2026 | 4/15/2026 | CASA GRANDE        | 2000 | Line 2000 smart tool Casa Grande to Ehrenberg Re-Run -<br>North Baja Delivery - (INORBAJA) - Customer limited to<br>CADIZSOU Line 1903 volume during Line 2000 Casa Grande<br>to Ehrenberg smart tool | 442 | SM |
| 4/14/2026 | 4/17/2026 | BLACK RIVER        | STA  | Black River Station DOT/ESD Tests                                                                                                                                                                     | 175 | SM |
| 4/15/2026 | 4/15/2026 | FLAG-WEST-PL       | 1200 | Line 1200 smart tool Flagstaff to Seligman                                                                                                                                                            | 250 | NM |
| 4/16/2026 | 4/29/2026 | TUCSON             | 1007 | Line 1007 hydrotest - MLV 4.75 to MLV 7 - (Informational Only)<br>- No Current Capacity Impact                                                                                                        | 0   | SM |
| 4/16/2026 | 4/17/2026 | WILLCOX STA        | 1A   | Willcox 1A inspection                                                                                                                                                                                 | 130 | SM |
| 4/17/2026 | 4/17/2026 | FLAG-WEST-PL       | 1200 | Line 1200 smart tool Flagstaff to Seligman                                                                                                                                                            | 250 | NM |
| 4/20/2026 | 4/29/2026 | TOM MIX STA        | 1A   | Tom Mix 1A maintenance                                                                                                                                                                                | 43  | SM |
| 4/21/2026 | 4/23/2026 | GALLUP-N ML        | 1201 | Line 1201 smart tool Valve City to Navajo                                                                                                                                                             | 150 | XO |
| 4/27/2026 | 7/2/2026  | SAN SIMON<br>STA   | 1A   | San Simon 1A maintenance                                                                                                                                                                              | 75  | SM |
| 4/28/2026 | 4/30/2026 | FLAGSTAFF          | STA  | Flagstaff Station DOT/ESD Tests                                                                                                                                                                       | 117 | NM |

|           |            |                  |      |                                                                                                                                                                                                                                                                      |     |     |
|-----------|------------|------------------|------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----|
| 5/4/2026  | 5/22/2026  | FLAGSTAFF - PL   | 1200 | Line 1200 pipeline remediation Navajo to Dilkon                                                                                                                                                                                                                      | 150 | NM  |
| 5/4/2026  | 5/25/2026  | GALLUP-N ML      | 1200 | Line 1200 pipeline remediation Window Rock to Navajo                                                                                                                                                                                                                 | 150 | XO  |
| 5/4/2026  | 5/25/2026  | GALLUP-N ML      | 1200 | Line 1200 pipeline remediation Window Rock to Navajo                                                                                                                                                                                                                 | 150 | XO  |
| 5/4/2026  | 5/25/2026  | GALLUP-N ML      | 1200 | Line 1200 pipeline remediation Window Rock to Navajo                                                                                                                                                                                                                 | 150 | XO  |
| 5/5/2026  | 5/6/2026   | FLAG-WEST-PL     | 1203 | Line 1203 pipeline maintenance - MLV 1 to MLV 2                                                                                                                                                                                                                      | 139 | NM  |
| 5/5/2026  | 12/31/2026 | MONUMENT STA     | STA  | Monument Station DOT/ESD Tests                                                                                                                                                                                                                                       | 50  | PR  |
| 5/5/2026  | 5/6/2026   | CAPROCK          | STA  | Caprock Station DOT/ESD Tests                                                                                                                                                                                                                                        | 150 | XO  |
| 5/5/2026  | 5/7/2026   | ODESSA PL        | 1115 | Line 1115 smart tool Plains to Goldsmith<br><br>Buckhorn Receipt - Customer reduced to zero Dth/d during Line 1115 smart tool Plains to Goldsmith<br><br>Phillips Goldsmith Receipt - Customer reduced to zero Dth/d during Line 1115 smart tool Plains to Goldsmith | 220 | PR  |
| 5/5/2026  | 5/7/2026   | BLANCO A         | STA  | Blanco Station DOT/ESD Test - (IMOITRKA) - Valverde Receipt - Customer limited to zero flow during maintenance                                                                                                                                                       | 481 | SJ  |
| 5/5/2026  | 5/8/2026   | WENDEN STA       | STA  | Wenden Station DOT/ESD Tests                                                                                                                                                                                                                                         | 150 | HX  |
| 5/5/2026  | 5/7/2026   | MOJAVE STA       | 1A   | Mojave 1A maintenance                                                                                                                                                                                                                                                | 117 | MOJ |
| 5/6/2026  | 5/6/2026   | SAN JUAN         | STA  | San Juan River Station DOT/ESD Tests                                                                                                                                                                                                                                 | 30  | SJ  |
| 5/11/2026 | 5/15/2026  | WASHINGTON RANCH | STA  | Washington Ranch Spring BHP Survey - No injection or withdrawal available                                                                                                                                                                                            | 250 | SM  |
| 5/12/2026 | 5/14/2026  | DAGGETT STA      | STA  | Daggett Station DOT/ESD Tests                                                                                                                                                                                                                                        | 260 | MOJ |
| 5/12/2026 | 5/14/2026  | SELIGMAN         | 1C   | Seligman C Station DOT/ESD Tests                                                                                                                                                                                                                                     | 175 | NM  |
| 5/12/2026 | 5/14/2026  | SELIGMAN         | 1B   | Seligman B Station DOT/ESD Tests                                                                                                                                                                                                                                     | 100 | NM  |
| 5/12/2026 | 5/12/2026  | SAN JUAN PL      | 1218 | Line 1218 cleaning tool MLV 3.625 to Blanco                                                                                                                                                                                                                          | 300 | SJ  |
| 5/12/2026 | 5/14/2026  | FLORIDA STA      | STA  | Florida A Station DOT/ESD Tests                                                                                                                                                                                                                                      | 225 | SM  |
| 5/12/2026 | 5/14/2026  | BELEN            | STA  | Belen Station DOT/ESD Tests                                                                                                                                                                                                                                          | 150 | XO  |
| 5/12/2026 | 5/14/2026  | FLORIDA STA      | 2A   | Florida 2A ESD DOT Tests                                                                                                                                                                                                                                             | 22  | SM  |
| 5/12/2026 | 5/14/2026  | FLORIDA STA      | 1A   | Florida 1A DOT/ESD Tests                                                                                                                                                                                                                                             | 22  | SM  |
| 5/12/2026 | 5/14/2026  | BELEN            | 1A   | Belen 1A maintenance                                                                                                                                                                                                                                                 | 150 | XO  |
| 5/12/2026 | 5/14/2026  | FLORIDA STA      | 3A   | Florida 3A DOT/ESD Tests                                                                                                                                                                                                                                             | 22  | SM  |

|           |           |                  |      |                                                                                                       |     |     |
|-----------|-----------|------------------|------|-------------------------------------------------------------------------------------------------------|-----|-----|
| 5/12/2026 | 5/15/2026 | WASHINGTON RANCH | STA  | Washington Ranch DOT/ESD Tests                                                                        | 250 | SM  |
| 5/12/2026 | 5/14/2026 | FLORIDA STA      | 2A   | Florida 2A maintenance                                                                                | 50  | SM  |
| 5/12/2026 | 5/12/2026 | SAN JUAN PL      | 1218 | Line 1218 smart tool MLV 3.625 to Blanco                                                              | 300 | SJ  |
| 5/12/2026 | 5/16/2026 | EL PASO          | 1100 | Line 1100 pipeline maintenance El Paso                                                                | 490 | SM  |
| 5/13/2026 | 5/13/2026 | WINDOW ROCK      | STA  | Window Rock B Station DOT/ESD Tests                                                                   | 450 | NM  |
| 5/14/2026 | 5/14/2026 | WINDOW ROCK      | STA  | Window Rock Station A Station DOT/ESD Tests                                                           | 450 | NM  |
| 5/14/2026 | 5/14/2026 | WINDOW ROCK      | 7A   | Window Rock 7A DOT/ESD Tests                                                                          | 150 | NM  |
| 5/15/2026 | 8/14/2026 | CARLSBAD PIPE    | 1100 | Line 1100 pipeline remediation Pecos River to Guadalupe - MLV 6.75 to MLV 9                           | 121 | PR  |
| 5/18/2026 | 5/24/2026 | PHOENIX          | 2223 | Line 2223 Direct Assessment                                                                           | 0   | PHX |
| 5/19/2026 | 5/22/2026 | GUADALUPE STA    | STA  | Guadalupe Station maintenance                                                                         | 290 | SM  |
| 5/19/2026 | 5/21/2026 | SCHAFER          | STA  | Getty Schafer Station DOT/ESD Tests                                                                   | 50  | AN  |
| 5/19/2026 | 5/20/2026 | FLORIDA STA      | 1B   | Florida B Station DOT/ESD Tests                                                                       | 53  | SM  |
| 5/19/2026 | 5/23/2026 | EL PASO          | 2000 | Line 2000 pipeline maintenance El Paso to Afton                                                       | 610 | SM  |
| 5/19/2026 | 5/23/2026 | EL PASO          | 2000 | Line 2000 pipeline maintenance El Paso to Afton                                                       | 610 | SM  |
| 5/19/2026 | 5/25/2026 | PHOENIX          | 2223 | Line 2223 pipeline maintenance - MLV 2 to MLV 3 - No current capacity impact - Informational only     | 0   | PHX |
| 5/20/2026 | 5/21/2026 | PHOENIX          | STA  | Casa Grande C Station maintenance                                                                     | 120 | PHX |
| 5/20/2026 | 5/20/2026 | CASA GRANDE      | 2C   | Casa Grande 2C DOT/ESD Tests                                                                          | 120 | SM  |
| 5/20/2026 | 5/20/2026 | CASA GRANDE      | 1C   | Casa Grande 1C DOT/ESD Tests                                                                          | 120 | SM  |
| 5/21/2026 | 5/21/2026 | CASA GRANDE      | STA  | Casa Grande Station DOT/ESD Tests - (Capacity Reductions to CG LP, CG HP and CASA C)                  | 120 | SM  |
| 5/22/2026 | 5/22/2026 | CASA GRANDE      | 1A   | Casa Grande 1A DOT/ESD Tests                                                                          | 42  | SM  |
| 5/22/2026 | 5/22/2026 | CASA GRANDE      | 1B   | Casa Grande 1B DOT/ESD Tests                                                                          | 104 | SM  |
| 5/22/2026 | 5/22/2026 | CASA GRANDE      | 2A   | Casa Grande Unit 2A DOT/ESD Tests                                                                     | 42  | SM  |
| 5/25/2026 | 6/7/2026  | FLAGSTAFF - PL   | 1201 | Line 1201 pipeline remediation Navajo to Dilkon                                                       | 150 | NM  |
| 5/26/2026 | 5/28/2026 | LINCOLN          | STA  | Lincoln Station DOT/ESD Tests                                                                         | 158 | XO  |
| 5/26/2026 | 5/28/2026 | CORNUDAS STA     | STA  | Cornudas B Station DOT/ESD Tests                                                                      | 119 | SM  |
| 5/27/2026 | 5/27/2026 | FLAGSTAFF - PL   | 1204 | Line 1204 cleaning tool Leupp to Flagstaff                                                            | 173 | NM  |
| 5/28/2026 | 5/28/2026 | FLAGSTAFF - PL   | 1204 | Line 1204 smart tool Leupp to Flagstaff                                                               | 173 | NM  |
| 5/29/2026 | 5/29/2026 | FLAGSTAFF - PL   | 1204 | Line 1204 smart tool Leupp to Flagstaff                                                               | 173 | NM  |
| 6/1/2026  | 6/14/2026 | PHOENIX          | 1203 | Line 1203 pipeline maintenance Maricopa to Prescott - No current capacity impact - Informational only | 0   | PHX |

|           |           |                   |      |                                                                                                                            |     |     |
|-----------|-----------|-------------------|------|----------------------------------------------------------------------------------------------------------------------------|-----|-----|
| 6/1/2026  | 6/14/2026 | PHOENIX           | 2214 | Line 2214 direct assessment                                                                                                | 0   | PHX |
| 6/1/2026  | 6/21/2026 | PHOENIX           | 2214 | Line 2214 pipeline maintenance MLV 2 to Ocotillo Power Plant<br>- No current capacity impact - Informational only          | 0   | PHX |
| 6/2/2026  | 6/4/2026  | LEUPP             | 3B   | Leupp 3B inspection                                                                                                        | 50  | NM  |
| 6/2/2026  | 6/2/2026  | FLAG-WEST-PL      | 1200 | Line 1200 pipeline remediation Seligman to Hackberry                                                                       | 150 | NM  |
| 6/2/2026  | 6/4/2026  | WINDOW<br>ROCK    | 4A   | Window Rock 4A inspection                                                                                                  | 32  | NM  |
| 6/2/2026  | 6/4/2026  | LEUPP             | 7A   | Leupp 7A inspection                                                                                                        | 50  | NM  |
| 6/2/2026  | 6/2/2026  | TOPOCK-<br>MOJAVE | 1200 | Line 1200 cleaning tool Seligman to Hackberry                                                                              | 150 | NM  |
| 6/2/2026  | 6/4/2026  | PUCKETT           | STA  | Puckett Station DOT/ESD Tests                                                                                              | 135 | PR  |
| 6/2/2026  | 6/15/2026 | EL PASO           | 1100 | Line 1100 pipeline remediation Afton to Florida - MLV 28.75 to<br>MLV 30 - No current capacity impact - Informational Only | 0   | SM  |
| 6/3/2026  | 6/3/2026  | FLAG-WEST-PL      | 1200 | Line 1200 smart tool Seligman to Hackberry                                                                                 | 150 | NM  |
| 6/3/2026  | 6/3/2026  | TOPOCK-<br>MOJAVE | 1200 | Line 1200 smart tool Seligman to Hackberry                                                                                 | 150 | NM  |
| 6/5/2026  | 6/5/2026  | FLAG-WEST-PL      | 1200 | Line 1200 smart tool Seligman to Hackberry                                                                                 | 150 | NM  |
| 6/5/2026  | 6/5/2026  | TOPOCK-<br>MOJAVE | 1200 | Line 1200 smart tool Seligman to Hackberry                                                                                 | 150 | NM  |
| 6/8/2026  | 6/12/2026 | WINDOW<br>ROCK    | 4A   | Window Rock 4A maintenance                                                                                                 | 45  | NM  |
| 6/8/2026  | 6/14/2026 | PHOENIX           | 2222 | Line 2222 pipeline maintenance MLV 4 to Chandler - No<br>current capacity impact - Informational only                      | 0   | PHX |
| 6/9/2026  | 6/11/2026 | AMARILLO          | STA  | Amarillo Station DOT/ESD Tests                                                                                             | 80  | AN  |
| 6/9/2026  | 6/12/2026 | DILKON            | 1B   | Dilkon 1B maintenance                                                                                                      | 175 | NM  |
| 6/15/2026 | 7/12/2026 | FLAGSTAFF -<br>PL | 1200 | Line 1200 pipeline remediation Dilkon to Flagstaff                                                                         | 150 | NM  |
| 6/15/2026 | 7/12/2026 | FLAGSTAFF -<br>PL | 1200 | Line 1200 pipeline remediation Dilkon to Flagstaff - MLV 23 to<br>MLV 25                                                   | 150 | NM  |
| 6/15/2026 | 7/12/2026 | FLAGSTAFF -<br>PL | 1200 | Line 1200 pipeline remediation Dilkon to Flagstaff - MLV 25 to<br>MLV 25.5                                                 | 150 | NM  |
| 6/15/2026 | 7/12/2026 | FLAGSTAFF -<br>PL | 1200 | Line 1200 pipeline remediation Dilkon to Flagstaff - MLV 25.5<br>to MLV 27                                                 | 150 | NM  |
| 6/15/2026 | 6/26/2026 | KEYSTONE          | 12A  | Keystone 12A inspection                                                                                                    | 40  | PR  |
| 6/16/2026 | 6/16/2026 | PHOENIX           | 1007 | Line 1007 smart tool I-10 to MLV 26.75                                                                                     | 50  | PHX |
| 6/16/2026 | 6/22/2026 | PHOENIX           | 1600 | Line 1600 pipeline remediation Casa Grande to Wenden                                                                       | 600 | PHX |
| 6/16/2026 | 8/28/2026 | TUCSON            | 2105 | Line 2105 hydrotest MLV 1 to EOL                                                                                           | 150 | SM  |
| 6/16/2026 | 6/25/2026 | EL PASO           | 1600 | Line 1600 pipeline remediation El Paso to Florida                                                                          | 600 | SM  |
| 6/16/2026 | 7/2/2026  | DEMING PL         | 1100 | Line 1100 pipeline remediation Florida to Deming - MLV 32.5<br>to MLV 35                                                   | 200 | SM  |

|           |           |                |      |                                                                                                                                                                                                  |     |     |
|-----------|-----------|----------------|------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----|
| 6/17/2026 | 6/17/2026 | PHOENIX        | 1007 | Line 1007 smart tool I-10 to MLV 26.75                                                                                                                                                           | 50  | PHX |
| 6/22/2026 | 6/22/2026 | AFTON STA      | 3A   | Afton 3A maintenance                                                                                                                                                                             | 75  | SM  |
| 6/26/2026 | 7/17/2026 | PHOENIX        | 1103 | Line 1103 hydrotest Casa Grande                                                                                                                                                                  | 500 | PHX |
| 6/30/2026 | 7/2/2026  | EL PASO        | 1100 | Line 1100 pipeline remediation Afton to Deming - MLV 30 to MLV 32.5 - No current capacity impact - Informational Only                                                                            | 0   | SM  |
| 6/30/2026 | 7/31/2026 | LEUPP          | 1204 | Leupp C and D Station maintenance                                                                                                                                                                | 250 | NM  |
| 7/7/2026  | 7/7/2026  | WHITE ROCK     | 2A   | White Rock 2A DOT/ESD Tests                                                                                                                                                                      | 80  | SJ  |
| 7/7/2026  | 7/9/2026  | WHITE ROCK     | STA  | White Rock Station DOT/ESD Tests                                                                                                                                                                 | 259 | SJ  |
| 7/7/2026  | 11/2/2026 | TOPOCK-MOJAVE  | 1204 | Line 1204 pipeline maintenance Seligman to Hackberry                                                                                                                                             | 200 | NM  |
| 7/7/2026  | 7/7/2026  | AMARILLO PL    | 2131 | Line 2131 ILI Inspections - SPS Plant X Delivery (DPLTXDIS) - 16 Mmcfd Flow Rate Required for ILI inspections                                                                                    | 16  | AN  |
| 7/14/2026 | 9/4/2026  | WILLIAMS       | 1C   | Williams C Station maintenance                                                                                                                                                                   | 400 | NM  |
| 7/14/2026 | 7/16/2026 | RED MOUNTAIN   | STA  | Red Mountain Station DOT/ESD Tests                                                                                                                                                               | 165 | SM  |
| 7/14/2026 | 7/16/2026 | DUMAS          | STA  | Dumas Station DOT/ESD Tests                                                                                                                                                                      | 140 | AN  |
| 7/20/2026 | 8/18/2026 | PHOENIX        | 1100 | Line 1100 hydrotest Casa Grande                                                                                                                                                                  | 400 | PHX |
| 7/21/2026 | 7/24/2026 | CARLSBAD PIPE  | 1100 | Line 1100 smart tool Pecos River to Guadalupe                                                                                                                                                    | 121 | SM  |
| 7/21/2026 | 8/4/2026  | PHOENIX        | 2214 | Line 2214 pipeline maintenance MLV 0 to MLV 2 - No current capacity impact - Informational only                                                                                                  | 0   | PHX |
| 7/21/2026 | 7/23/2026 | SAN JUAN PL    | 1205 | Line 1218 smart tool Bondad to Blanco                                                                                                                                                            | 87  | SJ  |
| 7/21/2026 | 7/24/2026 | AFTON STA      | STA  | Afton Station DOT/ESD Tests                                                                                                                                                                      | 150 | SM  |
| 7/22/2026 | 7/23/2026 | LAGUNA         | STA  | Laguna Station DOT/ESD Tests                                                                                                                                                                     | 97  | XO  |
| 7/27/2026 | 8/7/2026  | TOM MIX STA    | 1A   | Tom Mix 1A maintenance                                                                                                                                                                           | 43  | SM  |
| 7/28/2026 | 7/28/2026 | FLAG-WEST-PL   | 1203 | Line 1203 cleaning tool Ashfork to North Phoenix                                                                                                                                                 | 54  | NM  |
| 7/28/2026 | 7/28/2026 | PHOENIX        | 1203 | Line 1203 cleaning tool Flagstaff to Phoenix                                                                                                                                                     | 55  | PHX |
| 7/28/2026 | 8/10/2026 | FLAGSTAFF - PL | 1204 | Line 1204 pipeline remediation Navajo to Leupp                                                                                                                                                   | 150 | NM  |
| 7/30/2026 | 7/30/2026 | FLAG-WEST-PL   | 1203 | Line 1204 smart tool Ash Fork to North Phoenix                                                                                                                                                   | 54  | NM  |
| 7/30/2026 | 7/30/2026 | PHOENIX        | 1203 | Line 1203 smart tool North Phoenix to Chandler                                                                                                                                                   | 55  | PHX |
| 8/1/2026  | 8/1/2026  | FLAG-WEST-PL   | 1203 | Line 1203 smart tool Ash Fork to North Phoenix                                                                                                                                                   | 54  | NM  |
| 8/1/2026  | 8/1/2026  | PHOENIX        | 1203 | Line 1203 smart tool North Phoenix to Chandler                                                                                                                                                   | 55  | PHX |
| 8/3/2026  | 8/23/2026 | ODESSA PL      | 3140 | Line 3140 pipeline remediation - Jameson Receipt, Conoco Sterling Receipt, Deadwood Receipt and GCX Sterling Delivery - Limited to zero Dth/d net capacity during Line 3140 pipeline remediation | 200 | PR  |
| 8/4/2026  | 8/5/2026  | WILLIAMS       | STA  | Williams C Station maintenance                                                                                                                                                                   | 400 | NM  |
| 8/4/2026  | 9/28/2026 | TUCSON         | 1100 | Line 1100 pipeline maintenance Benson to Vail                                                                                                                                                    | 400 | SM  |

|           |            |                  |      |                                                                                                                                                                            |     |     |
|-----------|------------|------------------|------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----|
| 8/4/2026  | 8/14/2026  | WILLIAMS         | STA  | Williams B Station maintenance                                                                                                                                             | 275 | NM  |
| 8/4/2026  | 8/14/2026  | WILLIAMS         | 1204 | Williams B Station maintenance                                                                                                                                             | 200 | NM  |
| 8/4/2026  | 8/21/2026  | WILLIAMS         | 3B   | Williams 5B maintenance                                                                                                                                                    | 55  | NM  |
| 8/10/2026 | 8/10/2026  | GALLUP-N ML      | 1201 | Line 1201 pipeline remediation Valve City to Navajo                                                                                                                        | 150 | XO  |
| 8/10/2026 | 9/4/2026   | GALLUP-N ML      | 1201 | Line 1201 pipeline remediation Valve City to Navajo                                                                                                                        | 150 | XO  |
| 8/10/2026 | 9/4/2026   | GALLUP-N ML      | 1201 | Line 1201 pipeline remediation Valve City to Navajo                                                                                                                        | 150 | XO  |
| 8/11/2026 | 8/13/2026  | WILLIAMS         | STA  | Williams C Station maintenance                                                                                                                                             | 400 | NM  |
| 8/11/2026 | 8/13/2026  | AMARILLO PL      | 1192 | Line 1192 ILI Inspections - Flow Required at Nichols Power Plant Delivery (DNICHOLS) for ILI Inspections                                                                   | 0   | AN  |
| 8/17/2026 | 8/28/2026  | TOM MIX STA      | 2A   | Tom Mix 2A maintenance                                                                                                                                                     | 43  | SM  |
| 8/17/2026 | 9/13/2026  | FLAGSTAFF - PL   | 2217 | Line 2217 pipeline remediation Southwest Forest - Southwest Forest Delivery (DCITZSWF) - Customer limited to zero Dth/d net capacity during Line 2217 pipeline remediation | 30  | NM  |
| 8/18/2026 | 8/20/2026  | WINDOW ROCK      | 1A   | Window Rock 1A inspection                                                                                                                                                  | 45  | NM  |
| 8/18/2026 | 8/27/2026  | ROSWELL          | 1A   | Roswell 1A maintenance                                                                                                                                                     | 65  | XO  |
| 8/24/2026 | 12/6/2026  | EHRENBERG        | 1103 | Line 1103 pipeline maintenance Wenden to Ehrenberg                                                                                                                         | 500 | SM  |
| 8/25/2026 | 8/28/2026  | GRESHAM          | STA  | Gresham Station DOT/ESD Tests                                                                                                                                              | 175 | SM  |
| 8/25/2026 | 8/28/2026  | ROSWELL          | STA  | Roswell Station DOT/ESD Tests                                                                                                                                              | 188 | XO  |
| 8/31/2026 | 9/27/2026  | DEMING PL        | 1103 | Line 1103 pipeline repair Afton to Deming - MLV 35 to MLV 36.75                                                                                                            | 500 | SM  |
| 9/2/2026  | 9/2/2026   | BONDAD           | 1B   | Bondad 1B inspection                                                                                                                                                       | 150 | SJ  |
| 9/8/2026  | 9/11/2026  | PECOS RIVER STA  | STA  | Pecos River Station DOT/ESD Tests                                                                                                                                          | 250 | SM  |
| 9/8/2026  | 9/10/2026  | LEUPP            | 4A   | Leupp 4A inspection                                                                                                                                                        | 15  | NM  |
| 9/8/2026  | 9/11/2026  | CORNUDAS STA     | STA  | Cornudas A Station DOT/ESD Tests                                                                                                                                           | 272 | SM  |
| 9/15/2026 | 9/16/2026  | BLUEWATER        | STA  | Bluewater Station DOT/ESD Tests                                                                                                                                            | 220 | XO  |
| 9/15/2026 | 9/16/2026  | MOJAVE STA       | 1A   | Mojave 1A inspection                                                                                                                                                       | 117 | MOJ |
| 9/15/2026 | 9/18/2026  | KEYSTONE         | STA  | Keystone Station DOT/ESD Tests                                                                                                                                             | 591 | PR  |
| 9/17/2026 | 9/18/2026  | MOJAVE STA       | 2A   | Mojave 2A inspection                                                                                                                                                       | 117 | MOJ |
| 9/18/2026 | 9/25/2026  | WASHINGTON RANCH | STA  | Washington Ranch Fall BHP Survey - No injection or withdrawal available                                                                                                    | 250 | SM  |
| 9/29/2026 | 11/24/2026 | TUCSON           | 1103 | Line 1103 pipeline maintenance Benson to Vail                                                                                                                              | 500 | SM  |
| 9/29/2026 | 10/1/2026  | WINDOW ROCK      | 2A   | Window Rock 2A inspection                                                                                                                                                  | 32  | NM  |
| 9/29/2026 | 10/2/2026  | HUECO STA        | STA  | Hueco Station DOT/ESD Tests                                                                                                                                                | 157 | SM  |
| 9/29/2026 | 11/10/2026 | CAPROCK          | 2A   | Caprock 2A maintenance                                                                                                                                                     | 75  | XO  |
| 9/29/2026 | 11/20/2026 | CORNUDAS STA     | 3A   | Cornudas 3A maintenance                                                                                                                                                    | 75  | SM  |
| 9/29/2026 | 9/30/2026  | DUTCH FLATS STA  | 1A   | Dutch Flats 1A inspection                                                                                                                                                  | 50  | HX  |



|            |            |                   |           |                                                                                                                                                      |     |     |
|------------|------------|-------------------|-----------|------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----|
| 9/30/2026  | 12/31/2026 | SAN SIMON STA     | STA       | San Simon Station maintenance                                                                                                                        | 175 | SM  |
| 9/30/2026  | 10/1/2026  | DUTCH FLATS STA   | 2A        | Dutch Flats 2A inspection                                                                                                                            | 33  | HX  |
| 10/6/2026  | 10/13/2026 | EHRENBERG         | ALL       | Wenden Station Valve 9140 maintenance                                                                                                                | 300 | SM  |
| 10/6/2026  | 10/6/2026  | TUCSON            | 1100      | Line 1100 cleaning tool San Simon to Benson                                                                                                          | 400 | SM  |
| 10/6/2026  | 10/6/2026  | DUTCH FLATS STA   | 1A        | Dutch Flats 1A DOT/ESD Tests                                                                                                                         | 50  | HX  |
| 10/7/2026  | 10/7/2026  | TUCSON            | 1100      | Line 1100 smart tool San Simon to Benson                                                                                                             | 400 | SM  |
| 10/7/2026  | 10/7/2026  | DUTCH FLATS STA   | 2A        | Dutch Flats 2A DOT/ESD Tests                                                                                                                         | 50  | HX  |
| 10/8/2026  | 10/8/2026  | TUCSON            | 1100      | Line 1100 pipeline remediation San Simon to Benson                                                                                                   | 400 | SM  |
| 10/12/2026 | 11/10/2026 | TUCSON            | 1103      | Line 1103 pipeline maintenance Benson to Vail                                                                                                        | 500 | SM  |
| 10/12/2026 | 11/13/2026 | TUCSON            | 1103      | Line 1103 pipeline maintenance Benson to Vail                                                                                                        | 500 | SM  |
| 10/13/2026 | 10/15/2026 | WINK              | STA       | Wink Station DOT/ESD Tests                                                                                                                           | 135 | SM  |
| 10/13/2026 | 10/15/2026 | MOJAVE STA        | STA       | Mojave Station maintenance (One Unit at a Time)                                                                                                      | 117 | MOJ |
| 10/20/2026 | 10/20/2026 | DUTCH FLATS       | STA       | Dutch Flats Station DOT/ESD Tests                                                                                                                    | 128 | HX  |
| 10/20/2026 | 10/23/2026 | PLAINS STA        | STA       | Plains Station DOT/ESD Tests - Deliveries cannot be made to INN30PLA, IW40-043, or IMUSTANG; during this outage, no gas can be received at INN26PLA. | 762 | AN  |
| 10/20/2026 | 11/3/2026  | GALLUP-SAN JUAN X | 1300      | Line 1300 pipeline maintenance Laguna to Bluewater                                                                                                   | 615 | XO  |
| 10/20/2026 | 10/20/2026 | TOPOCK-MOJAVE     | 1204/1113 | Line 1204/1113 cleaning tool Hackberry to Topock                                                                                                     | 150 | NM  |
| 10/22/2026 | 10/22/2026 | TOPOCK-MOJAVE     | 1204/1113 | Line 1204/1113 smart tool Hackberry to Topock                                                                                                        | 150 | NM  |
| 11/3/2026  | 12/18/2026 | CORNUDAS STA      | 3A        | Cornudas 3A maintenance                                                                                                                              | 75  | SM  |
| 11/10/2026 | 11/12/2026 | LEUPP             | 8A        | Leupp 8A inspection                                                                                                                                  | 10  | NM  |
| 11/17/2026 | 11/19/2026 | LEUPP             | 5A        | Leupp 5A inspection                                                                                                                                  | 15  | NM  |
| 12/1/2026  | 12/3/2026  | WILLIAMS          | 5B        | Williams 5B maintenance                                                                                                                              | 50  | NM  |
| 12/21/2026 | 12/22/2026 | TOM MIX STA       | 1A        | Tom Mix 1A inspection                                                                                                                                | 43  | SM  |
| 12/22/2026 | 12/24/2026 | LEUPP             | 11A       | Leupp 11A inspection                                                                                                                                 | 50  | NM  |