

# El Paso Natural Gas Company, L.L.C.'s (El Paso)

## Proposed Maintenance and Construction Outage Impact Summary

This document lists proposed outages for major maintenance and construction that are being planned on El Paso's system for the next 12 to 15 months. The purpose of this posting is to inform customers of proposed outages that will affect throughput on El Paso's system. All dates are tentative and subject to change. Consistent with prudent operations, dates may change based on a number of factors including, but not limited to, weather, contractor or material availability, changing business conditions, minimizing adverse impact to shippers, or to coordinate with outages on interconnecting pipelines. Comments regarding alternate dates are welcome. Generally, this proposed outage schedule will be updated weekly and may be updated more often, if warranted. Please refer to the revision date to differentiate the schedules.

This document is not intended to be an official notice of the outage. When outages are scheduled, they will be included in the monthly maintenance report and posted on El Paso's Electronic Bulletin Board (EBB) under Planned Service Outage as well as a Critical Notice, both located in the Notices section of the Informational Postings tab on EPNG's EBB. Shippers should refer to this report for current outages. El Paso's EBB Home Page will also have information and links to access the information.

This schedule does not include outages associated with a declared Force Majeure event. A Force Majeure event will be communicated through a Critical Notice in the Notice section of the Informational Postings tab on El Paso's EBB in addition to updated information in the monthly maintenance notice mentioned above.



Revised: 8/7/2026

Questions? Call John Althoff 719-667-7750

| Start Date | End Date   | Location        | Unit | Maintenance Activity          | Reduction in MMcf/d | Oregion |
|------------|------------|-----------------|------|-------------------------------|---------------------|---------|
| 11/7/2013  | 12/31/2026 | WINDOW ROCK     | 3A   | Window Rock 3A repair pending | 35                  | NM      |
| 7/21/2015  | 12/31/2026 | WILLIAMS        | 4B   | Williams 4B repair pending    | 35                  | NM      |
| 12/1/2015  | 12/31/2026 | LEUPP           | 1A   | Leupp 1A repair pending       | 25                  | NM      |
| 8/4/2016   | 12/31/2026 | MONUMENT STA PL | 1B   | Monument 1B repair pending    | 20                  | PR      |
| 9/8/2017   | 12/31/2026 | LEUPP           | 9A   | Leupp 9A repair pending       | 25                  | NM      |
| 1/1/2018   | 12/31/2026 | CASA GRANDE     | 1A   | Casa Grande 1A repair pending | 42                  | SM      |

|           |            |                  |      |                                                                                                                                                           |     |     |
|-----------|------------|------------------|------|-----------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----|
| 11/6/2018 | 12/31/2026 | WINDOW ROCK      | 1B   | Window Rock 1B repair pending                                                                                                                             | 35  | NM  |
| 5/15/2026 | 8/14/2026  | CARLSBAD PIPE    | 1100 | Line 1100 pipeline remediation Pecos River to Guadalupe - MLV 6.75 to MLV 9                                                                               | 121 | PR  |
| 7/14/2026 | 9/4/2026   | WILLIAMS         | 1C   | Williams C Station maintenance                                                                                                                            | 400 | NM  |
| 7/20/2026 | 8/18/2026  | PHOENIX          | 1100 | Line 1100 hydrotest Tucson to Casa Grande                                                                                                                 | 38  | PHX |
| 7/27/2026 | 8/7/2026   | TOM MIX STA      | 1A   | Tom Mix 1A maintenance                                                                                                                                    | 43  | SM  |
| 7/27/2026 | 8/21/2026  | GALLUP-N ML MEAS | 1201 | Line 1201 pipeline remediation Valve City to Navajo                                                                                                       | 150 | XO  |
| 7/27/2026 | 8/28/2026  | GALLUP-N ML MEAS | 1201 | Line 1201 pipeline remediation Valve City to Navajo                                                                                                       | 150 | XO  |
| 7/27/2026 | 9/4/2026   | GALLUP-N ML MEAS | 1201 | Line 1201 pipeline remediation Valve City to Navajo                                                                                                       | 150 | XO  |
| 7/28/2026 | 8/10/2026  | FLAGSTAFF - PL   | 1204 | Line 1204 pipeline remediation Navajo to Leupp                                                                                                            | 150 | NM  |
| 7/28/2026 | 8/10/2026  | FLAGSTAFF - PL   | 1204 | Line 1204 pipeline remediation Navajo to Leupp                                                                                                            | 150 | NM  |
| 7/28/2026 | 8/10/2026  | FLAGSTAFF - PL   | 1204 | Line 1204 pipeline remediation Navajo to Leupp                                                                                                            | 150 | NM  |
| 8/10/2026 | 8/14/2026  | CORNUDAS STA     | 1A   | Cornudas 1A maintenance                                                                                                                                   | 75  | SM  |
| 8/10/2026 | 8/17/2026  | Flag-West-PL     | 1200 | Line 1200 pipeline maintenance Flagstaff to MLV 30.75                                                                                                     | 100 | NM  |
| 8/10/2026 | 8/21/2026  | TWIN BUTTES      | 2143 | Line 2143 pipeline remediation MLV 1 to MLV 2 - No current capacity impact - Informational Only                                                           | 0   | SM  |
| 8/11/2026 | 8/11/2026  | WILLCOX STA      | STA  | Willcox Station maintenance                                                                                                                               | 124 | SM  |
| 8/11/2026 | 8/13/2026  | AMARILLO PL      | 1192 | Line 1192 ILI Inspections - Flow Required at Nichols Power Plant Delivery (DNICHOLS) for ILI Inspections                                                  | 0   | AN  |
| 8/11/2026 | 8/14/2026  | LEUPP            | 1204 | Leupp C and D Station maintenance                                                                                                                         | 250 | NM  |
| 8/17/2026 | 8/28/2026  | TOM MIX STA      | 2A   | Tom Mix 2A maintenance                                                                                                                                    | 43  | SM  |
| 8/17/2026 | 9/13/2026  | FLAGSTAFF - PL   | 2217 | Line 2217 pipeline remediation Southwest Forest - Southwest Forest Delivery (DCITZSWF) - Informational Only - Lower pressures possible during this outage | 0   | NM  |
| 8/18/2026 | 8/20/2026  | CORNUDAS STA     | 3A   | Cornudas 3A maintenance                                                                                                                                   | 75  | SM  |
| 8/18/2026 | 8/20/2026  | DUMAS EAST PL    | STA  | Dumas Station DOT/ESD Tests                                                                                                                               | 140 | AN  |
| 8/18/2026 | 10/3/2026  | CORNUDAS STA     | 3A   | Cornudas 3A maintenance                                                                                                                                   | 75  | SM  |
| 8/24/2026 | 8/27/2026  | CARLSBAD PIPE    | 1100 | Line 1100 smart tool Pecos River to Guadalupe                                                                                                             | 121 | PR  |
| 8/24/2026 | 8/28/2026  | LORDSBURG STA    | 1B   | Lordsburg 1B maintenance                                                                                                                                  | 100 | SM  |

|           |            |                        |      |                                                                                  |     |     |
|-----------|------------|------------------------|------|----------------------------------------------------------------------------------|-----|-----|
| 8/25/2026 | 8/26/2026  | CORNUDAS STA           | 1C   | Cornudas 1C maintenance                                                          | 100 | SM  |
| 8/25/2026 | 8/28/2026  | GRESHAM                | STA  | Gresham Station DOT/ESD Tests                                                    | 175 | SM  |
| 8/25/2026 | 8/28/2026  | ROSWELL                | STA  | Roswell Station DOT/ESD Tests                                                    | 188 | XO  |
| 8/27/2026 | 8/28/2026  | CORNUDAS STA           | 2C   | Cornudas 2C maintenance                                                          | 100 | SM  |
| 8/31/2026 | 9/27/2026  | DEMING PL              | 1103 | Line 1103 pipeline repair Afton to Deming - MLV 35 to MLV 36.75                  | 248 | SM  |
| 9/1/2026  | 9/21/2026  | ODESSA PL              | 3140 | Line 3140 pipeline remediation - No current capacity impact - Informational Only | 0   | PR  |
| 9/2/2026  | 9/2/2026   | BONDAD                 | 1B   | Bondad 1B inspection                                                             | 150 | SJ  |
| 9/8/2026  | 9/11/2026  | PECOS RIVER STA        | STA  | Pecos River Station DOT/ESD Tests                                                | 250 | SM  |
| 9/8/2026  | 9/10/2026  | LEUPP                  | 4A   | Leupp 4A inspection                                                              | 15  | NM  |
| 9/8/2026  | 9/11/2026  | CORNUDAS STA           | STA  | Cornudas A Station DOT/ESD Tests                                                 | 272 | SM  |
| 9/14/2026 | 12/11/2026 | TUCSON                 | 2006 | Line 2006 pipeline maintenance MLV 0.625 to MLV 7                                | 15  | SM  |
| 9/15/2026 | 9/18/2026  | BLUEWATER              | STA  | Bluewater Station DOT/ESD Tests                                                  | 220 | XO  |
| 9/15/2026 | 9/16/2026  | MOJAVE STA             | 1A   | Mojave 1A inspection                                                             | 117 | MOJ |
| 9/15/2026 | 9/18/2026  | KEYSTONE               | STA  | Keystone Station DOT/ESD Tests                                                   | 591 | PR  |
| 9/17/2026 | 9/18/2026  | MOJAVE STA             | 2A   | Mojave 2A inspection                                                             | 117 | MOJ |
| 9/18/2026 | 9/25/2026  | WASHINGTON RANCH       | STA  | Washington Ranch Fall BHP Survey - No injection or withdrawal available          | 250 | SM  |
| 9/29/2026 | 9/29/2026  | WILLIAMS               | STA  | Williams C Station maintenance                                                   | 400 | NM  |
| 9/29/2026 | 10/1/2026  | WINDOW ROCK            | 2A   | Window Rock 2A inspection                                                        | 32  | NM  |
| 9/29/2026 | 9/29/2026  | GALLUP-SAN JUAN X MEAS | 1301 | Line 1301 smart tool MLV 28 to MLV 33                                            | 150 | XO  |
| 9/29/2026 | 10/2/2026  | HUECO STA              | STA  | Hueco Station DOT/ESD Tests                                                      | 157 | SM  |
| 9/29/2026 | 9/30/2026  | DUTCH FLATS STA        | 1A   | Dutch Flats 1A inspection                                                        | 50  | HX  |
| 9/30/2026 | 9/30/2026  | GALLUP-SAN JUAN X MEAS | 1301 | Line 1301 smart tool MLV 28 to MLV 33                                            | 150 | XO  |
| 9/30/2026 | 10/1/2026  | DUTCH FLATS STA        | 2A   | Dutch Flats 2A inspection                                                        | 33  | HX  |
| 10/6/2026 | 10/6/2026  | TUCSON                 | 1100 | Line 1100 cleaning tool San Simon to Benson                                      | 400 | SM  |
| 10/6/2026 | 10/8/2026  | LEUPP                  | 7A   | Leupp 7A inspection                                                              | 50  | NM  |
| 10/6/2026 | 10/6/2026  | DUTCH FLATS STA        | 1A   | Dutch Flats 1A DOT/ESD Tests                                                     | 50  | HX  |
| 10/6/2026 | 10/19/2026 | ODESSA PL              | 1600 | Line 1600 pipeline remediation Waha to Gresham                                   | 300 | PR  |
| 10/7/2026 | 10/7/2026  | TUCSON                 | 1100 | Line 1100 smart tool San Simon to Benson                                         | 400 | SM  |
| 10/7/2026 | 10/7/2026  | DUTCH FLATS STA        | 2A   | Dutch Flats 2A DOT/ESD Tests                                                     | 50  | HX  |

|            |            |                        |           |                                                                                                                                                      |     |     |
|------------|------------|------------------------|-----------|------------------------------------------------------------------------------------------------------------------------------------------------------|-----|-----|
| 10/8/2026  | 10/8/2026  | TUCSON                 | 1100      | Line 1100 smart tool San Simon to Benson                                                                                                             | 400 | SM  |
| 10/13/2026 | 10/15/2026 | ORACLE STA             | STA       | Oracle Station inspection                                                                                                                            | 94  | SM  |
| 10/13/2026 | 10/15/2026 | WINK                   | STA       | Wink Station DOT/ESD Tests                                                                                                                           | 135 | SM  |
| 10/13/2026 | 10/16/2026 | WILLIAMS               | 1204      | Williams B Station maintenance                                                                                                                       | 200 | NM  |
| 10/13/2026 | 10/21/2026 | WILLIAMS               | 3B        | Williams 5B maintenance                                                                                                                              | 55  | NM  |
| 10/13/2026 | 10/15/2026 | MOJAVE STA             | STA       | Mojave Station maintenance (One Unit at a Time)                                                                                                      | 117 | MOJ |
| 10/20/2026 | 10/20/2026 | DUTCH FLATS STA        | STA       | Dutch Flats Station DOT/ESD Tests                                                                                                                    | 128 | HX  |
| 10/20/2026 | 10/23/2026 | PLAINS STA PL          | STA       | Plains Station DOT/ESD Tests - Deliveries cannot be made to INN30PLA, IW40-043, or IMUSTANG; during this outage, no gas can be received at INN26PLA. | 762 | AN  |
| 10/20/2026 | 11/3/2026  | GALLUP-SAN JUAN X MEAS | 1300      | Line 1300 pipeline maintenance Laguna to Bluewater                                                                                                   | 615 | XO  |
| 10/20/2026 | 10/20/2026 | TOPOCK-MOJAVE          | 1204/1113 | Line 1204/1113 cleaning tool Hackberry to Topock                                                                                                     | 150 | NM  |
| 10/21/2026 | 10/21/2026 | ODESSA PL              | 3125      | Line 3125 maintenance tool - 100 Mmc/d flow rate requested from Midkiff Receipt - (IMIDKIFF)                                                         | 0   | PR  |
| 10/22/2026 | 10/22/2026 | TOPOCK-MOJAVE          | 1204/1113 | Line 1204/1113 smart tool Hackberry to Topock                                                                                                        | 150 | NM  |
| 11/2/2026  | 11/13/2026 | AMARILLO PL            | STA       | Big Blue Receipt and Delivery - (IBIGBLUE) - Customer limited to zero Dth/d net capacity during meter station maintenance                            | 163 | AN  |
| 11/3/2026  | 11/5/2026  | WILLIAMS               | 5B        | Williams 5B maintenance                                                                                                                              | 50  | NM  |
| 11/3/2026  | 12/18/2026 | CORNUDAS STA           | 3A        | Cornudas 3A maintenance                                                                                                                              | 75  | SM  |
| 11/10/2026 | 11/12/2026 | LEUPP                  | 8A        | Leupp 8A inspection                                                                                                                                  | 10  | NM  |
| 11/10/2026 | 11/24/2026 | EHRENBURG              | 1103      | Line 1103 pipeline maintenance Wenden to Ehrenberg                                                                                                   | 500 | SM  |
| 11/17/2026 | 11/19/2026 | LEUPP                  | 5A        | Leupp 5A inspection                                                                                                                                  | 15  | NM  |
| 12/1/2026  | 12/15/2026 | EHRENBURG              | 1103      | Line 1103 pipeline maintenance Wenden to Ehrenberg                                                                                                   | 500 | SM  |
| 12/21/2026 | 12/22/2026 | TOM MIX STA            | 1A        | Tom Mix 1A inspection                                                                                                                                | 43  | SM  |
| 12/22/2026 | 12/24/2026 | LEUPP                  | 11A       | Leupp 11A inspection                                                                                                                                 | 50  | NM  |