

TGP - Outage Impact Report
Seven Day Forecast (updated 09/17/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

TGP - Outage Impact Report Seven Day Forecast (updated 09/17/26)									Primary impact restrictions may be necessary
									Major impact restrictions may be necessary
									Minor impact restrictions may be necessary depending on flow conditions
									Little to no impact, though minor outages may cause incremental reductions
Station / Seg	Est Nominal Operating Capacity (Thousand Dth)	Monday (9/21)	Tuesday (9/22)	Wednesday (9/23)	Thursday (9/24)	Friday (9/25)	Saturday (9/26)	Sunday (9/27)	Primary Outage(s) that may Impact Throughput
Est. Operational Capacity (Operational Impact) - Thousand Dth									
Station 409A (Alamo) (segment 492 FH)	274	125 (149)	125 (149)	125 (149)	125 (149)	125 (149)	215 (59)	215 (59)	MLV 409-1 to MLV 406-1: Spike Test (M) (9/20/2026 - 11/11/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (9/21/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (9/22/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (9/23/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - EMAT (M) (9/25/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - MFL-C (M) (9/24/2026)
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	564	564	564	
Station 1 (segment 101 BH)	399	300 (99)	300 (99)	300 (99)	300 (99)	300 (99)	300 (99)	300 (99)	Sta 1: Station Power Protection System (9/22/2026)
Station 9 (segment 109 BH)	1,027	1,027	1,027	1,027	1,027	1,027	1,027	1,027	MLV 1-1D to MLV 5-1: Spike Test (M) (9/21/2026 - 11/2/2026)
Station 17 (segment 117 FH)	1,122	1085 (37)	1085 (37)	1085 (37)	1085 (37)	1,122	1,122	1,122	MLV 17-1D to MLV 20-1A: Pig Run - Chemical Cleaning (9/21/2026) MLV 17-1D to MLV 20-1A: Pig Run - EMAT (9/24/2026) MLV 17-1D to MLV 20-1A: Pig Run - GAUGE PLATE (9/22/2026) MLV 17-1D to MLV 20-1A: Pig Run - MFL-C (9/23/2026)
Station 25 (segment 125 FH)	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	
Station 47 (segment 143 FH)	1,343	1,343	1,343	1,343	1,343	1,343	1,343	1,343	
Station 63 (segment 163 FH)	1,242	1030 (212)	1030 (212)	1030 (212)	1030 (212)	1030 (212)	1030 (212)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 82-2C to MLV 83-2: Anomaly Remediation (9/21/2026 - 9/26/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	734	734	734	
Station 834 (segment 834 BH)	683	670 (13)	670 (13)	670 (13)	670 (13)	670 (13)	683	683	Sta 834: Unit 4A - Replace Lubrication System (9/21/2026 - 9/25/2026)
Station 534 South of Pool (segment 530 BH)	1,550	985 (565)	985 (565)	985 (565)	985 (565)	985 (565)	985 (565)	985 (565)	MLV 533-2 to MLV 534-2: Pipe Replacement (M) (6/4/2026 - 9/27/2026)
Station 860 (segment 548 BH)	1,593	1545 (48)	1545 (48)	1545 (48)	1545 (48)	1545 (48)	1577 (16)	1577 (16)	Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 9/30/2026) Sta 542: Unit 4A - Cylinder Replacement (9/21/2026 - 9/25/2026) Sta 546: Unit 7A - Metal in Oil (7/14/2025 - 9/30/2026) Sta 555: Unit 4A - Engine Maintenance (9/21/2026 - 9/24/2026)
Station 860 North (Segment 860 BH)	1,874	1495 (379)	1495 (379)	1846 (28)	1846 (28)	1846 (28)	1846 (28)	1846 (28)	Sta 563: Unit 1A - Emergent Repair (8/28/2026 - 9/22/2026) Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026) Sta 860: Unit 1B - Replace Turbocharger (9/21/2026 - 9/25/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2407 (278)	2407 (278)	2407 (278)	2407 (278)	2407 (278)	2407 (278)	2407 (278)	MLV 109-5 to MLV 109-5A: Pipe Replacement (9/14/2026 - 10/12/2026) MLV 109-5A to MLV 110-5: Pipe Replacement (9/14/2026 - 10/12/2026) MLV 110-2 to MLV 114-2: CAO - Force Majeure (M) (7/14/2026 - 12/31/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 93-4 to MLV 94-4: Anomaly Remediation (M) (9/21/2026 - 9/28/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 10/10/2026) Sta 871: Unit 1A - Bearing (9/12/2026 - 9/30/2026)
Station 114 (segment 114 BH)	907	907	907	907	907	907	907	907	
Station 204 (Segment 204 BH)	1,828	1715 (113)	1715 (113)	1715 (113)	1715 (113)	1825 (3)	1825 (3)	1825 (3)	MLV 214-2 to MLV 215-2: PHMSA Immediate (9/16/2026 - 10/6/2026) Sta 204: Unit 5A - Piston (9/21/2026 - 9/24/2026) Sta 209 Cambridge: Unit 12A - Eutectic Device (9/21/2026 - 9/24/2026)
Station 245 (segment 245 FH)	986	970 (16)	970 (16)	970 (16)	970 (16)	970 (16)	970 (16)	970 (16)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026)
MLV 256 West (segment 249 FH)	1,203	660 (543)	660 (543)	660 (543)	1,203	1,203	1,203	1,203	MLV 258-2 to MLV 259-2: Emergent Repair (9/9/2026 - 9/23/2026)
Station 261 Discharge East (segment 261 FH)	888	715 (173)	715 (173)	715 (173)	555 (333)	555 (333)	715 (173)	715 (173)	Sta 264 Charlton: Annual ESD Test (9/24/2026 - 9/25/2026) Sta 264 Charlton: Unit 1C - Engine Maintenance (8/24/2026 - 10/16/2026)
Station 307 (segment 307 BH)	1,153	1010 (143)	1010 (143)	1,153	1,153	1,153	1,153	1,153	Sta 310: Unit 1A - Water Washes and Borescope (9/21/2026 - 9/22/2026)
Station 313 Discharge (segment 399 FH)	797	797	797	797	797	797	797	797	
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	1,823	1,823	1,823	
Station 321 (segment 321 FH)	2,102	1830 (272)	1830 (272)	1830 (272)	1830 (272)	2,102	2,102	2,102	Sta 323: Station Outage (9/21/2026 - 9/24/2026)
MLV 324 (segment 324 FH)	1,767	1,767	1,767	1,767	1,767	1,767	1,767	1,767	

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

TGP - Outage Impact Report October 2026 (updated 09/17/26)							-Primary impact restrictions may be necessary
							-Major impact restrictions may be necessary
							-Minor impact restrictions may be necessary depending on flow conditions
							-Little to no impact, though minor outages may cause incremental reductions
Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (9/28 - 10/4)	Week 2 (10/5 - 10/11)	Week 3 (10/12 - 10/18)	Week 4 (10/19 - 10/25)	Week 5 (10/26 - 11/1)	Primary Outage(s)
Est. Operational Capacity (Operational Impact) - Thousand Dth							
Station 409A (Alamo) (segment 492 FH)	274	215 (59)	215 (59)	215 (59)	215 (59)	215 (59)	MLV 409-1 to MLV 406-1: Spike Test (M) (9/20/2026 - 11/11/2026)
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	564	
Station 1 (segment 101 BH)	399	300 (99)	300 (99)	300 (99)	300 (99)	300 (99)	
Station 9 (segment 109 BH)	1,027	1,027	1,027	1,027	125 (902)	946 (81)	MLV 1-1D to MLV 5-1: Spike Test (M) (9/21/2026 - 11/2/2026) MLV 9-2S to MLV 1-2: Pig Runs - Cleaning / Maintenance (M) (10/22/2026) MLV 9-3 to MLV 5-3: Pig Run - Maintenance (M) (10/21/2026)
Station 17 (segment 117 FH)	1,122	1,122	985 (137)	980 (142)	1100 (22)	1,122	MLV 17-2D to MLV 20-2A: Pig Run - Chemical Cleaning (10/19/2026 - 10/20/2026) MLV 17-2D to MLV 20-2A: Pig Run - GAUGE (10/21/2026) MLV 17-2D to MLV 20-2A: Pig Run - MFL-A (10/22/2026) MLV 32-2D TO MLV 40-2S: Pig Runs - Maintenance (10/8/2026) MLV 32-3D to MLV 40-3S: Pig Runs - Maintenance (10/13/2026) Sta 25: Annual ESD Test (10/13/2026)
Station 25 (segment 125 FH)	1,078	1,078	1,078	1,078	1,078	1,078	
Station 47 (segment 143 FH)	1,343	1025 (318)	1025 (318)	1290 (53)	1300 (43)	1,343	MLV 58-2 to MLV 59-2: Anomaly Remediation (10/10/2026 - 10/20/2026) Sta 47: Scrubber/Filter/Separator Cleaning/Inspection/Changeout (9/28/2026 - 10/2/2026) Sta 47: Station Transformer Maintenance (10/6/2026) Sta 47: Unit 1D - 16K hour Overhaul (10/5/2026 - 10/15/2026)
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1030 (212)	1030 (212)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 73-1 to MLV 74-1: Anomaly Remediation (10/12/2026 - 10/23/2026) MLV 82-1 to MLV 87-1: Pig Run - AFD/Cal/IMU (10/8/2026) MLV 82-1 to MLV 87-1: Pig Run - Cleaning / Gauge (10/6/2026) MLV 82-1 to MLV 87-1: Pig Run - EMAT (10/13/2026) MLV 84-3 to MLV 85-3: Anomaly Remedition (9/28/2026 - 10/3/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	734	
Station 834 (segment 834 BH)	683	683	683	670 (13)	670 (13)	683	Sta 834: Unit 1A - Replace Insulation Blanket (10/12/2026 - 10/13/2026) Sta 834: Unit 2A - Replace Insulation Blanket (10/14/2026 - 10/15/2026) Sta 834: Unit 3A - Replace Insulation Blanket (10/16/2026 - 10/17/2026) Sta 834: Unit 4A - Replace Insulation Blanket (10/19/2026 - 10/20/2026)
Station 534 South of Pool (segment 530 BH)	1,550	1,550	1440 (110)	1175 (375)	1,550	1,550	Sta 529: Unit 1A - Solar Inspection (10/12/2026 - 10/15/2026) Sta. 527 Port Sulphur: Building C - Medium Voltage Electrical Testing (10/5/2026 - 10/9/2026)
Station 534 (segment 534 BH)	1,909	1,909	1,909	1770 (139)	1,909	1,909	Sta 538: Boost Pump Vibration Upgrade (10/12/2026 - 10/15/2026)
Station 860 (segment 548 BH)	1,593	1577 (16)	1,593	1,593	1181 (412)	1,593	Sta 542 Dekalb: Annual ESD Test (10/20/2026 - 10/22/2026) Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 9/30/2026) Sta 546: Unit 7A - Metal in Oil (7/14/2025 - 9/30/2026)
Station 860 North (Segment 860 BH)	1,874	1846 (28)	1846 (28)	1475 (399)	1475 (399)	1475 (399)	MLV 560-2 to MLV 563-2: Pipe Replacements (M) (10/15/2026 - 10/26/2026) Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2407 (278)	2043 (642)	1972 (713)	2428 (257)	1822 (863)	MLV 103-3 to MLV 105-3: Crossover Upgrade (10/10/2026 - 10/17/2026) MLV 104-3 to MLV 106-3S: HDD at Kentucky River (10/10/2026 - 10/17/2026) MLV 109-3A to MLV 110-3: Pipe Replacement (10/14/2026 - 10/30/2026) MLV 109-5 to MLV 109-5A: Pipe Replacement (9/14/2026 - 10/12/2026) MLV 109-5A to MLV 110-5: Pipe Replacement (9/14/2026 - 10/12/2026) MLV 110-2 to MLV 114-2: CAO - Force Majeure (M) (7/14/2026 - 12/31/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 867-2 to MLV 868-2: Anomaly Remediation (10/19/2026 - 10/24/2026) MLV 870-2 to MLV 870-2R: Anomaly Remediation (10/12/2026 - 10/17/2026) MLV 93-4 to MLV 94-4: Anomaly Remediation (M) (9/21/2026 - 9/28/2026) MLV 97-3 to MLV 106-3: Pig Run - Cleaning / Gauge (10/27/2026) MLV 97-3 to MLV 106-3: Pig Run - MFL-S (10/29/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 10/10/2026) Sta 871: Unit 1A - Bearing (9/12/2026 - 9/30/2026) Sta 875: Unit 1A- 8K Solar Turbine Inspection (10/27/2026 - 10/29/2026) Sta 96: Unit 2D Replace Compressor Valves (10/12/2026 - 10/15/2026)
Station 114 (segment 114 BH)	907	907	853 (54)	907	907	907	Sta 118A Tyler Mountain: Annual ESD Test (10/5/2026 - 10/6/2026)

TGP - Outage Impact Report October 2026 (updated 09/17/26)							-Primary impact restrictions may be necessary
							-Major impact restrictions may be necessary
							-Minor impact restrictions may be necessary depending on flow conditions
							-Little to no impact, though minor outages may cause incremental reductions
Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (9/28 - 10/4)	Week 2 (10/5 - 10/11)	Week 3 (10/12 - 10/18)	Week 4 (10/19 - 10/25)	Week 5 (10/26 - 11/1)	Primary Outage(s)
		Est. Operational Capacity (Operational Impact) - Thousand Dth					
Station 204 (Segment 204 BH)	1,828	1415 (413)	1750 (78)	1745 (83)	1745 (83)	1690 (138)	MLV 209-2 to MLV 214-2: Pig Run - Chem Cleaning (10/26/2026) MLV 209-2 to MLV 214-2: Pig Run - Chem Cleaning (10/27/2026) MLV 209-2 to MLV 214-2: Pig Run - Chem Cleaning (10/28/2026) MLV 209-2 to MLV 214-2: Pig Run - Chem Cleaning (10/29/2026) MLV 209-2 to MLV 214-2: Pig Run - Chem Cleaning (10/30/2026) MLV 214-1 to MLV 219-1: Pig Run - Cal/IMU (10/20/2026) MLV 214-1 to MLV 219-1: Pig Run - Gauge/Cleaning (10/15/2026) MLV 214-1 to MLV 219-1: Pig Run - MFL-C (10/22/2026) MLV 214-2 to MLV 215-2: PHMSA Immediate (9/16/2026 - 10/6/2026) Sta 204: Scrubber Filter Change (10/1/2026 - 10/3/2026) Sta 209 Cambridge: Scrubber Filter (9/28/2026 - 9/30/2026) Sta 209 Cambridge: Unit 11A - Eutectic Device (9/28/2026 - 9/30/2026) Sta. 200: Unit 1B - Replace Turbochargers (10/4/2026 - 10/30/2026)
Station 233 (segment 233 FH)	459	355 (104)	459	459	459	459	MLV 233-2 to MLV 235-2: Pig Run (9/30/2026)
Station 245 (segment 245 FH)	986	970 (16)	970 (16)	970 (16)	970 (16)	760 (226)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026) Sta 245-1 to MLV 249-1: Pig Run - EMAT (10/28/2026) Sta 245-1 to MLV 249-1: Pig Run - MFL-C - Rerun (10/27/2026)
MLV 256 West (segment 249 FH)	1,203	642 (561)	1,203	1,203	1,203	1,203	Sta 249-2 to MLV 254-2: Pig Run - Hardspot Rerun (9/30/2026)
Station 261 Discharge East (segment 261 FH)	888	500 (388)	715 (173)	555 (333)	888	888	Sta 261 Agawam: Annual ESD test (M) (9/28/2026 - 10/2/2026) Sta 264 Charlton: Unit 1C - Engine Maintenance (8/24/2026 - 10/16/2026) Sta 264: Oil System (10/12/2026 - 10/16/2026)
Station 307 (segment 307 BH)	1,153	1,153	1,153	765 (388)	765 (388)	765 (388)	MLV 302-2 to MLV 303-2: Anomaly Remediation (10/16/2026 - 10/27/2026) Sta 303A: Unit 1A - Water Wash (10/19/2026 - 10/22/2026)
Station 313 Discharge (segment 399 FH)	797	207 (590)	207 (590)	207 (590)	797	797	MLV 313A-403 to MLV 313A-404: Anomaly Remediation (9/29/2026 - 10/15/2026)
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	1,823	
MLV 324 (segment 324 FH)	1,767	1450 (317)	1,767	1,767	1550 (217)	1,767	MLV 325-1 to MLV 329-1: Pig runs - Cleaning/Gauge (M) (10/19/2026) MLV 325-1 to MLV 329-1: Pig runs - EMAT (M) (10/20/2026) Sta 325: Station Outage (9/29/2026 - 10/1/2026)
Cranston Lateral South (segment 281 FH)	187	187	187	125 (62)	187	187	Sta 265: Unit 1A - Replace Lube Oil Fan (10/12/2026)
Station 405 HC Line (segment 299 FH)	794	794	794	670 (124)	794	794	Sta 405A: Unit 1A - 4k Waterwash (10/13/2026) ; Sta 405A: Unit 1A - 8K Solar Turbine Inspection (10/14/2026)
Station 224 (segment 224 FH)	388	388	200 (188)	388	388	388	MLV 229-2 to MLV 232-2: Pig runs - Maintenance (M) (10/6/2026)
This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses. Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report. The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.							

TGP - Outage Impact Report November 2026 (updated 09/17/26)						-Primary impact restrictions may be necessary
						-Major impact restrictions may be necessary
						-Minor impact restrictions may be necessary depending on flow conditions
						-Little to no impact, though minor outages may cause incremental reductions
Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (11/2 - 11/8)	Week 2 (11/9 - 11/15)	Week 3 (11/16 - 11/22)	Week 4 (11/23 - 11/29)	Primary Outage(s)
		Est. Operational Capacity (Operational Impact) - Thousand Dth				
Station 409A (Alamo) (segment 492 FH)	297	260 (37)	260 (37)	297	297	MLV 409-1 to MLV 406-1: Spike Test (M) (9/20/2026 - 11/11/2026)
Station 409 (Donna Line) (segment 490 FH)	587	587	587	587	587	
MLV 406 (segment 406 BH)	479	479	479	479	479	
Station 1 (segment 101 BH)	438	438	399 (39)	226 (212)	438	MLV 400-1 to MLV 409-1: Pig Run - Maintenance Cleaning (M) (11/10/2026) MLV 400-2 to MLV 409-2: Pig Run - Maintenance Cleaning (M) (11/17/2026)
Station 9 (segment 109 BH)	1,066	985 (81)	880 (186)	1,066	1,066	MLV 1-1D to MLV 5-1: Spike Test (M) (9/21/2026 - 11/2/2026) MLV 1-1D to MLV 9-1S: Pig Run - Maintenance / Cleaning (M) (11/10/2026)
Station 17 (segment 117 FH)	1,138	1,138	1,138	1,138	1,138	
Station 25 (segment 125 FH)	1,095	1,095	1,095	1,095	1,095	
Station 40 South (segment 132 FH)	1,294	1,294	1,294	915 (379)	1,294	Sta 32: Annual ESD Test (11/17/2026 - 11/18/2026)
Station 47 (segment 143 FH)	1,428	1350 (78)	1350 (78)	1,428	1,428	MLV 61-3 to MLV 62-3: Pipe Replacements (11/2/2026 - 11/13/2026)
Station 63 (segment 163 FH)	1,192	871 (321)	1067 (125)	1067 (125)	1067 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 71-3D to MLV 74-3: Pig Runs - Cleaning / Gauge (11/3/2026) MLV 71-3D to MLV 74-3: Pig Runs - TDW MDS (11/5/2026)
Station 823 (segment 823 BH)	758	210 (548)	758	758	758	Sta 827 to Sta 823: Pig Run - Maintenance (M) (11/5/2026) Sta 834 to Sta 827: Maintenance Pig (M) (11/5/2026)
Station 860 (segment 548 BH)	1,665	1660 (5)	1450 (215)	1,665	1,665	Sta 550 Hamilton: Annual ESD Test (11/9/2026) Sta 550: Unit 1B - Junction Box Rewire & Unit Valves (11/2/2026 - 11/13/2026)
Station 860 North (Segment 860 BH)	2,059	2031 (28)	2031 (28)	2031 (28)	2031 (28)	Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026) Sta 860: Unit 1C - 4K/Turbine Waterwash/Boroscope (11/2/2026 - 11/3/2026) Sta 860: Unit 2C - 4K/Turbine Waterwash/Boroscope (11/3/2026 - 11/4/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,594	1951 (643)	2327 (267)	2327 (267)	2327 (267)	MLV 110-2 to MLV 114-2: CAO - Force Majeure (M) (7/14/2026 - 12/31/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 97-3 to MLV 106-3: Pig Run - EMAT (11/5/2026) MLV 97-3 to MLV 106-3: Pig Run - MFL-C (11/3/2026)
Station 114 (segment 114 BH)	946	858 (88)	946	946	946	Sta 118A: Solar Turbine Inspection (11/2/2026 - 11/4/2026)
Station 204 (Segment 204 BH)	1,888	1765 (123)	1405 (483)	1425 (463)	1,888	MLV 204-4 to MLV 209-4: Pig Run - Cal/IMU (11/12/2026) MLV 204-4 to MLV 209-4: Pig Run - Efficiency (11/11/2026) MLV 204-4 to MLV 209-4: Pig Run - EMAT (11/19/2026) MLV 204-4 to MLV 209-4: Pig Run - Gauge (11/10/2026) MLV 204-4 to MLV 209-4: Pig Run - MFL-C (11/17/2026) MLV 209-2 to MLV 214-2: Pig Run - CAL/IMU (11/3/2026) MLV 209-2 to MLV 214-2: Pig Run - EMAT (11/5/2026)
Station 245 (segment 245 FH)	1,043	1,043	1,043	1,043	1,043	
Station 261 Discharge East (segment 261 FH)	1,034	1,034	1,034	1,034	1,034	
Station 307 (segment 307 BH)	1,203	1020 (183)	1,203	1,203	1,203	Sta 219: Annual ESD Test & Scrubber Maintenance (11/3/2026 - 11/6/2026)

- Primary impact restrictions may be necessary
- Major impact restrictions may be necessary
- Minor impact restrictions may be necessary depending on flow conditions
- Little to no impact, though minor outages may cause incremental reductions

Primary Outage(s)

MLV 319-1 to MLV 320-1: Hot Tap (11/5/2026)

- Primary impact restrictions may be necessary
- Major impact restrictions may be necessary
- Minor impact restrictions may be necessary depending on flow conditions
- Little to no impact, though minor outages may cause incremental reductions

Primary Outage(s)

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses. Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report. The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.