



April 25, 2019

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, DC 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Sierrita Gas Pipeline LLC;
Docket No. CP13-73-000;
Quarterly Post-Construction Status Report

Commissioners:

Sierrita Gas Pipeline LLC ("Sierrita") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP13-73-000, a quarterly post-construction status report related to Sierrita's Pipeline Project ("Project").

Description of Proceeding

On February 7, 2013, Sierrita submitted its application ("Application"), pursuant to Section 7(c) of the Natural Gas Act ("NGA"), requesting a certificate of public convenience and necessity authorizing the construction and operation of the Sierrita Pipeline Project located in Pima County, Arizona. Concurrently, Sierrita filed an application in Docket No. CP13-74-000, pursuant to Section 3 of the NGA, seeking a new presidential permit authorizing the export of natural gas at a new international border crossing associated with the Sierrita Pipeline. On June 6, 2014, the Commission issued an Order Issuing Certificate ("Order") granting Sierrita's requested certificate.¹ Sierrita placed the project facilities into service on October 31, 2014.

Submittal of Status Report

In accordance with the Project's Upland Erosion Control, Revegetation, and Maintenance Plan reporting requirements, Sierrita is herein filing a quarterly status report describing its post-construction maintenance/reclamation efforts for the period of January 1, 2019 to March 31, 2019.

¹ See *Sierrita Gas Pipeline, LLC*, 147 FERC ¶ 61,192 (2014).

Filing Information

Sierrita is e-Filing this letter with attachments with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000. Sierrita is also providing copies of this filing to the OEP.

Respectfully submitted,

SIERRITA GAS PIPELINE LLC

By /s/
Francisco Tarin
Director, Regulatory

Attachments

cc: Mr. David M. Hanobic
Mr. Kevin Bowman

**CP13-73-000 Sierrita Pipeline Project Quarterly Report
January 1, 2019 through March 31, 2019**

Sierrita Pipeline Project

Restoration Activities

During this reporting period, no restoration activities were undertaken or required.

Cultural Monitoring

No cultural resource monitoring activities were conducted on the ROW during the reporting period.

Weed Control

During this reporting period, spring weed monitoring and control activities were completed. The spring weed monitoring report will be available during the second quarter; select photographs of the weed monitoring areas within the ROW are provided below.

Landowner Concerns

No landowner concerns were identified during the reporting period.

Right-of-Way Repairs

No right of way repairs were conducted during the reporting period.

Up Coming Activities

Minor subsidence repairs are scheduled to be completed at approximately Milepost 31. In addition, Sierrita anticipates completing all required tree plantings in 9 of the 16 wash crossings during the second quarter of 2019 as required by the U.S. Fish and Wildlife Service in order to meet their success criteria. Finally, Sierrita notes that its Annual Post-Construction Vegetation Monitoring Report (Year Four) was completed and filed with FERC on April 18, 2019. The results of that report will be presented at its annual stakeholders meeting scheduled to be held on April 30, 2019 at the Kinder Morgan Tucson area field office.¹

¹ Current committed attendees include Pima County, United States Fish & Wildlife Service and the Altar Valley Alliance.

**CP13-73-000 Sierrita Pipeline Project Quarterly Report
January 1, 2019 through March 31, 2019**



Milepost 6.3, view northeast.



Milepost 8, view northeast.

**CP13-73-000 Sierrita Pipeline Project Quarterly Report
January 1, 2019 through March 31, 2019**



Milepost 14.6, view west.



Milepost 25.7, view south.

**CP13-73-000 Sierrita Pipeline Project Quarterly Report
January 1, 2019 through March 31, 2019**



Milepost 36, view north.



Milepost 38.2, view northeast.

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing documents to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 25th day of April 2019.

/s/

Francisco Tarin

P.O. Box 1087
Colorado Springs, Colorado 80944
(719) 667-7517