



July 29, 2020

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, DC 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Sierrita Gas Pipeline LLC;
Docket No. CP18-37-000;
Sierrita Compressor Expansion Project;
Quarterly Post-Construction Report

Commissioners:

Sierrita Gas Pipeline LLC ("Sierrita") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-37-000, its quarterly post-construction status report related to the Sierrita Compressor Expansion Project.

Description of Proceeding

On December 21, 2017, Sierrita submitted its application, pursuant to Section 7(c) of the Natural Gas Act requesting a certificate of public convenience and necessity for authorization to construct, install, and operate a new compressor ("Sierrita Compressor Station") to be located in Pima County, Arizona. The project is referred to as the "Sierrita Compressor Expansion Project."

Submittal of Status Report

In accordance with the Project's Upland Erosion Control, Revegetation, and Maintenance Plan reporting requirements, Sierrita is herein filing a quarterly status report describing its post-construction maintenance/reclamation efforts for the period of April 1, 2020 to June 30, 2020.

Filing Information

Sierrita is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Federal Energy
Regulatory Commission

-2-

July 29, 2020

Respectfully submitted,

SIERRITA GAS PIPELINE LLC

By _____/s/_____
Francisco Tarin
Director, Regulatory

Enclosures

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing document to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 29th day of July, 2020.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517

CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
April 1, 2020 through June 30, 2020

Activities During the Reporting Period

On June 9, 2020, Sierrita filed the post-construction noise survey with the FERC. The survey was conducted on May 27, 2020 with the Sierrita Compressor Station operated at full horsepower (full load) capacity. The survey indicated that the sound level attributable to the Sierrita Compressor Station at the nearby NSAs is notably lower than 55 dBA (Ldn).

The contractor completed site clean-up and removal of materials and equipment, finalized the security fence installation, completed gravel installation as necessary, addressed final punch list items and demobilized from the site.

Restoration Activities

No restoration activities were conducted during the reporting period.

Weed Control

No weed control activities were conducted during this period.

Landowner Concerns

No landowner concerns were identified during the reporting period.

Right-of-Way Repairs

No right-of-way repairs were conducted during the reporting period.

Upcoming Activities

Pursuant to Paragraph (B)(3) of the Order under environmental condition no. 13, Sierrita is required to conduct a post-construction test of the water well identified within 100 feet of the construction work area. Since the City of Tucson Water Department only performs specific water well tests during the year, Sierrita initiated discussions with the City of Tucson Water Department on July 23rd regarding the timing on the next upcoming test of its well.

**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
April 1, 2020 through June 30, 2020**

Location:
Compressor
Station

**Direction of
Photo:** East

Description:
North security
fence.



Location:
Compressor
Station

**Direction of
Photo:** West

Description:
North Security
fence.



**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
April 1, 2020 through June 30, 2020**

Location: ROW

**Direction of
Photo:** South

Description:
Compressor
building and
seeded ROW.



Location: ROW

**Direction of
Photo:** North

Description:
Restoration on
ROW.



CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
April 1, 2020 through June 30, 2020

Location:
Compressor
Station

**Direction of
Photo:**
Northwest

Description:
Auxiliary and
compressor
building with final
gravel installed.



Location:
Compressor
Station

**Direction of
Photo:** North

Description:
View along west
security fence.



CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
April 1, 2020 through June 30, 2020

Location:
Compressor
Station

**Direction of
Photo:** Northeast

Description:
Cooler and final
gravel
installation.



Location:
Compressor
Station

**Direction of
Photo:**
Southeast

Description:
Compressor
building and final
gravel
installation.



**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
April 1, 2020 through June 30, 2020**

Location:
Compressor
Station

**Direction of
Photo:** South

Description:
Final gravel
installation.



Location: Mainline
Valve 2

**Direction of
Photo:** South

Description: View
down center of
restoration area.
Vehicle traffic is on
TRICO's ROW.
TRICO's temporary
power pole still on
site.



CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
April 1, 2020 through June 30, 2020

Location:
Mainline Valve 2

Direction of Photo: North

Description:
View north from project area toward the access road.



Location:
Mainline Valve 2

Direction of Photo: South

Description:
View from northwest corner of project area.

