



October 19, 2020

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, DC 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Sierrita Gas Pipeline LLC;
Docket No. CP18-37-000;
Sierrita Compressor Expansion Project;
Quarterly Post-Construction Report

Commissioners:

Sierrita Gas Pipeline LLC ("Sierrita") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-37-000, its quarterly post-construction status report related to the Sierrita Compressor Expansion Project.

Description of Proceeding

On December 21, 2017, Sierrita submitted its application, pursuant to Section 7(c) of the Natural Gas Act requesting a certificate of public convenience and necessity for authorization to construct, install, and operate a new compressor ("Sierrita Compressor Station") to be located in Pima County, Arizona. The project is referred to as the "Sierrita Compressor Expansion Project."

Submittal of Status Report

Consistent with the Project's Upland Erosion Control, Revegetation, and Maintenance Plan reporting requirements, Sierrita is herein filing a quarterly status report describing its post-construction maintenance/reclamation efforts for the period of July 1, 2020 to September 30, 2020.

Filing Information

Sierrita is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing document to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 19th day of October, 2020.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517

CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
July 1, 2020 through September 30, 2020

Activities During the Reporting Period

Sierrita has been working with the City of Tucson Water Department to schedule a water test for the water well located within 100 feet of the construction area in compliance with Environmental Condition No. 13. The City of Tucson Water Department has offered to collect a sample and conduct the required testing.

Restoration Activities

No restoration activities were conducted during the reporting period.

Weed Control

No weed control activities were conducted during the reporting period.

Landowner Concerns

No landowner concerns were identified during the reporting period.

Right-of-Way Repairs

No right of way repairs were conducted during the reporting period.

Upcoming Activities

Sierrita plans to provide the post-construction water test results from the City of Tucson Water Department during the next reporting period.

**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
July 1, 2020 through September 30, 2020**

Location:
Compressor
Station

**Direction of
Photo:** North

Description:
Compressor
station from south
fence.

Date: 10/8/2020



Location:
Compressor
Station

**Direction of
Photo:** East

Description:
Compressor
station from west
fence.

Date: 10/8/2020



**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
July 1, 2020 through September 30, 2020**

Location: ROW

**Direction of
Photo:** North

Description:
ROW from fence
line at
compressor
station.

Date: 10/8/2020



Location: ROW

**Direction of
Photo:** West

Description:
Variance area.

Date: 10/8/2020



**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
July 1, 2020 through September 30, 2020**

Location: ROW

Direction of Photo: South

Description:
ROW toward compressor station.

Date: 10/8/2020



Location: ROW

Direction of Photo: North

Description:
Tie-in area.

Date: 10/8/2020



**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
July 1, 2020 through September 30, 2020**

<p>Location: MLV 2</p> <p>Direction of Photo: South</p> <p>Description: Reclamation at MLV 2.</p> <p>Date: 10/8/2020</p>	
<p>Location: MLV 2</p> <p>Direction of Photo: North</p> <p>Description: View from south side of MLV 2 work area.</p> <p>Date: 10/8/2020</p>	