



January 22, 2021

Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, DC 20426

Attention: Ms. Kimberly D. Bose, Secretary

Re: Sierrita Gas Pipeline LLC;
Docket No. CP18-37-000;
Sierrita Compressor Expansion Project;
Quarterly Post-Construction Report

Commissioners:

Sierrita Gas Pipeline LLC ("Sierrita") is hereby filing with the Federal Energy Regulatory Commission ("Commission") in Docket No. CP18-37-000, its quarterly post-construction status report related to the Sierrita Compressor Expansion Project.

Description of Proceeding

On December 21, 2017, Sierrita submitted its application, pursuant to Section 7(c) of the Natural Gas Act requesting a certificate of public convenience and necessity for authorization to construct, install, and operate a new compressor ("Sierrita Compressor Station") to be located in Pima County, Arizona. The project is referred to as the "Sierrita Compressor Expansion Project."

Submittal of Status Report

Consistent with the Project's Upland Erosion Control, Revegetation, and Maintenance Plan reporting requirements, Sierrita is herein filing a quarterly status report describing its post-construction maintenance/reclamation efforts for the period of October 1, 2021 to December 31, 2021.

Filing Information

Sierrita is e-Filing this letter and report with the Commission's Secretary in accordance with the Commission's Order No. 703, *Filing Via the Internet*, guidelines issued on November 15, 2007 in Docket No. RM07-16-000.

Certificate of Service

I hereby certify that I have this day caused a copy of the foregoing document to be served upon each person designated on the official service list compiled by the Commission's Secretary in this proceeding in accordance with the requirements of Section 385.2010 of the Federal Energy Regulatory Commission's Rules of Practice and Procedure.

Dated at Colorado Springs, Colorado as of this 22nd day of January, 2021.

/s/

Francisco Tarin

Two North Nevada Avenue
Colorado Springs, Colorado 80903
(719) 667-7517

CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
October 1, 2020 through December 31, 2020

Activities During the Reporting Period

Sierrita worked with the City of Tucson Water Department on conducting a post-construction water test for the water well located within 100 feet of the construction area. The City of Tucson Water Department collected the water sample and performed the testing on October 29, 2020. On December 16, 2020, the City of Tucson Water Quality Lab reported to Sierrita that their testing demonstrated that no irregularities were present in the water samples that were collected on October 29, 2020. These results confirm that Sierrita's compressor station construction activities did not affect the water well.

Restoration Activities

No restoration activities were conducted during the reporting period.

Weed Control

No weed control activities were conducted during the reporting period.

Landowner Concerns

No landowner concerns were identified during the reporting period.

Right-of-Way Repairs

No right of way repairs were conducted during the reporting period.

Upcoming Activities

No planned upcoming activities.

CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
October 1, 2020 through December 31, 2020

Location:
Compressor
Station

**Direction of
Photo:**
Southwest

Description:
Northeast
Corner

Date:
12/31/2020



Location:
Compressor
Station



**Direction of
Photo:** North

Description:
South fence line
center

Date:
12/31/2020



**CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
October 1, 2020 through December 31, 2020**

<p>Location: ROW</p> <p>Direction of Photo: North</p> <p>Description: North fence line at ROW start</p> <p>Date: 12/31/2020</p>	
<p>Location: ROW</p> <p>Direction of Photo: South</p> <p>Description: Tie-in center</p> <p>Date: 12/31/2020</p>	

CP18-37-000 Sierrita Compressor Expansion Project
Quarterly Report
October 1, 2020 through December 31, 2020

Location:
MLV2

Direction of Photo: South

Description:
Center work area

Date:
12/31/2020



Location:
MLV2

Direction of Photo: North

Description:
Center south end

Date:
12/31/2020

