| | | Sev | | age Impact Ro | | Primary impact restrictions may be necessary -Major impact restrictions may be necessary -Minor impact restrictions may be necessary depending on flow conditions | | | |
|--|--|--------------------|------------------|------------------|-------------------|---|--------------------|------------------|--|
| | | | | 1 | | I | 1 | 1 | -Little to no impact, though minor outages may cause incremental reductions |
| Station # / Lateral (FH)=forward haul (BH)=backward haul | Est Nominal Design Capacity (Thousand Dth) | Saturday (2/16) | Sunday (2/17) | Monday (2/18) | Tuesday (2/19) | Wednesday (2/20) | Thursday (2/21) | Friday (2/22) | Primary Outage(s) that may Impact Throughput |
| | | | Est. Op | erational Capac | ity (Operational | Impact) - Thousa | and Dth | | |
| Station 409 (Donna Line) (segment 490 FH) | 601 | 601 | 601 | 601 | 601 | 601 | 601 | 601 | |
| Station 1 (segment 101 BH) | 255 | 255 | 255 | 255 | 255 | 255 | 255 | 255 | |
| Station 9 (segment 109 BH) | 1,049 | 1,049 | 1,049 | 1,049 | 1,049 | 1,049 | 1,049 | 1,049 | |
| Sta. 823 (segment 823 BH) | 702 | 650 (52) | 650 (52) | 702 | 702 | 702 | 702 | 702 | Sta 504: Unit 2B: Controls upgrade & convert to simple cycle (11/1/2018 - 2/17/2019) |
| Station 860 (segment 548 BH) | 1,633 | 1,633 | 1,633 | 1,633 | 1,633 | 1,633 | 1,633 | 1,633 | |
| Station 110 (segment 187 BH) (south thru Kentucky) | 2,736 | 2680 (56) | 2680 (56) | 2680 (56) | 2680 (56) | 2680 (56) | 2680 (56) | 2680 (56) | Sta 871: Unit 3A: Compressor Valve Maintenance (2/4/2019 - 2/23/2019) |
| Station 114 (segment 114 BH) | 941 | 941 | 941 | 941 | 941 | 941 | 941 | 941 | MLVS 122: Broad Run Cornwell Meter: Emergent Repair (M) (8/8/2017 - 3/31/2019) |
| Station 204 (Segment 204 BH) | 1,908 | 1,908 | 1,908 | 1865 (43) | 1865 (43) | 1865 (43) | 1865 (43) | 1865 (43) | Sta 209: Unit 6A: Carbon Removal (2/18/2019 - 2/22/2019) |
| Station 245 (segment 245 FH) | 1,066 | 1,066 | 1,066 | 1,066 | 1,066 | 1,066 | 1,066 | 1,066 | |
| Station 261 Discharge (segment 261 FH) | 992 | 992 | 992 | 992 | 992 | 992 | 992 | 992 | |
| Station 307 (segment 307 BH) | 1,201 | 1,201 | 1,201 | 1160 (41) | 1160 (41) | 1160 (41) | 1160 (41) | 1160 (41) | Sta 307: Unit 6A: Main Bearing Inspection (2/18/2019 - 3/1/2019) |
| Station 315 (segment 315 BH) | 1,980 | 1,980 | 1,980 | 1,980 | 1,980 | 1,980 | 1,980 | 1,980 | |
| Sta. 325 (segment 324 FH) | 1,715 | 1,715 | 1,715 | 1,715 | 1,715 | 1,715 | 1,715 | 1,715 | |
| Sta. 405 HC Line (segment 299 FH) | 823 | 823 | 823 | 823 | 823 | 823 | 823 | 823 | |
| Sta. 229 (segment 224 FH) | 402 | 402 | 402 | 402 | 402 | 402 | 402 | 402 | |

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.

Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates within this forecasted on this report.

The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

| | | outage Capacit bruary 2019 (u | | | | -Primary impact restrictions may be necessary -Major impact restrictions may be necessary -Minor impact restrictions may be necessary depending on flow conditions -Little to no impact, though minor outages may cause incremental reductions |
|--|--|------------------------------------|---|--|------------------------------------|--|
| Station # / Lateral | Est Nominal Design Capacity (Thousand Dth) | Week 1 (2/4 - 2/10) Est. Ope | Week 2 (2/11 - 2/17) erational Capacity (Op | Week 3 (2/18 - 2/24) perational Impact) - Thou | Week 4 (2/25 - 3/3) sand Dth | Primary Outage(s) |
| Station 409 (Donna Line) (segment 490 FH) | 601 | | | | 601 | |
| Station 1 (segment 101 BH) | 255 | | | | 255 | |
| Station 9 (segment 109 BH) | 1,049 | | | | 1,049 | |
| Station 860 (segment 548 BH) | 1,633 | | | | 1,633 | |
| Station 110 (segment 187 BH) (south thru Kentucky) | 2,736 | | | | 2,736 | |
| Station 114 (segment 114 BH) | 941 | | | | 941 | MLVS 122: Broad Run Cornwell Meter: Emergent Repair (M) (8/8/2017 - 3/31/2019) |
| Station 204 (Segment 204 BH) | 1,908 | | | | 1,908 | |
| Station 245 (segment 245 FH) | 1,066 | | | | 1,066 | |
| Station 261 Discharge (segment 261 FH) | 992 | | | | 992 | |
| Station 307 (segment 307 BH) | 1,201 | | | | 1160 (41) | Sta 307: Unit 6A: Main Bearing Inspection (2/18/2019 - 3/1/2019) |
| Station 315 (segment 315 BH) | 1,980 | | | | 1,980 | |
| Sta. 325 (segment 324 FH) | 1,715 | | | | 1,715 | |
| Sta. 405 HC Line (segment 299 FH) | 823 | | | | 823 | |
| Station 229 (segment 224 FH) | 402 | | | | 402 | |

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.

Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates within this forecasted on this report.

The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

| | C | Outage Capaci March 2019 (u | ty Impact Repo | ort 9) | | -Primary impact restrictions may be necessary -Major impact restrictions may be necessary -Minor impact restrictions may be necessary depending on flow conditions |
|--|--|--------------------------------|-------------------------|--------------------------|-------------------------|--|
| Station # / Lateral | Est Nominal Design Capacity (Thousand Dth) | Week 1 (3/4 - 3/10) | Week 2 (3/11 - 3/17) | Week 3 (3/18 - 3/24) | Week 4 (3/25 - 3/31) | -Little to no impact, though minor outages may cause incremental reductions Primary Outage(s) |
| Station 409 (Donna Line) (segment 490 FH) | 601 | Est. Op 601 | erational Capacity (Op | erational Impact) - Thou | 601 | |
| Station 1 (segment 101 BH) | 255 | 255 | 255 | 255 | 255 | |
| Station 9 (segment 109 BH) | 1,049 | 1,049 | 1,049 | 1,049 | 1,049 | |
| MLV 822 (segment 820 BH) | 1,052 | 1,052 | 1,052 | 1,052 | 1,052 | Sta 823 to STA 820-1: Maintenance Pig (M) (3/12/2019 - 3/12/2019) |
| Sta 847 (segment 847 FH) | 655 | 655 | 245 (410) | 245 (410) | 245 (410) | MLV 856-1 TO MLV 860-1: Pig Runs - Cleaning/Gauge 3/14/19 & 3/19/19 & 3/21/19, MFL/AFD 3/26/19, Hardspot/EMAT 3/28/19 (3/14/2019 - 3/28/2019) |
| Station 546 (segment 542 BH) | 1,596 | 1435 (161) | 1435 (161) | 1435 (161) | 1435 (161) | MLV 534-2 TO MLV 538-2: Make Piggable (M) (3/4/2019 - 4/29/2019) |
| Station 860 (segment 548 BH) | 1,633 | 1,633 | 1,633 | 1,633 | 1,633 | |
| Station 110 (segment 187 BH) (south thru Kentucky) | 2,736 | 2,736 | 2,736 | 2690 (46) | 2550 (186) | MLV 87-2D TO MLV 96-2S: Remediaton (3/25/2019 - 4/20/2019) MLV 110-2 TO MLV 106-2D: Pig run - Cleaning 3/18/19, Gauge 3/19/19, MFL 3/21/19, Hardspot 3/26/19 (3/18/2019 - 3/26/2019) |
| Station 114 (segment 114 BH) | 941 | 941 | 941 | 941 | 941 | MLVS 122: Broad Run Cornwell Meter: Emergent Repair (M) (8/8/2017 - 3/31/2019) |
| Station 204 (Segment 204 BH) | 1,908 | 1,908 | 1,908 | 1,908 | 1,908 | |
| Station 245 (segment 245 FH) | 1,066 | 1030 (36) | 1,066 | 1,066 | 1,066 | Sta 241: Unit 3A: Engine Maintenance (3/4/2019 - 3/7/2019) |
| Station 261 Discharge (segment 261 FH) | 992 | 992 | 992 | 992 | 992 | |
| Station 307 (segment 307 BH) | 1,201 | 1,201 | 1,201 | 1,201 | 1,201 | |
| Station 315 (segment 315 BH) | 1,980 | 1,980 | 1,980 | 1,980 | 1,980 | |
| Sta. 325 (segment 324 FH) | 1,715 | 1,715 | 1,715 | 1,715 | 1,715 | |
| Sta. 405 HC Line (segment 299 FH) | 823 | 823 | 823 | 823 | 823 | |
| Station 229 (segment 224 FH) | 402 | 402 | 402 | 402 | 402 | |

| | C | Outage Capaci April 2019 (up | ty Impact Repo | ort)) | | -Primary impact restrictions may be necessary -Major impact restrictions may be necessary -Minor impact restrictions may be necessary depending on flow conditions -Little to no impact, though minor outages may cause incremental reductions |
|--|--|---------------------------------|------------------------|--|-------------------------|--|
| Station # / Lateral | Est Nominal Design Capacity (Thousand Dth) | Week 1 (4/1 - 4/7) | Week 2 (4/8 - 4/14) | Week 3 (4/15 - 4/21) perational Impact) - Thor | Week 4 (4/22 - 4/28) | Primary Outage(s) |
| Station 409A (Alamo) (segment 492 FH) | 238 | 150 (88) | 150 (88) | 150 (88) | 238 | Sta 409A: Station Outage (M) (4/1/2019 - 4/21/2019) |
| Station 409 (Donna Line) (segment 490 FH) | 562 | 562 | 562 | 562 | 562 | |
| Station 1 (segment 101 BH) | 238 | 238 | 238 | 238 | 238 | |
| Station 9 (segment 109 BH) | 999 | 999 | 999 | 999 | 999 | |
| MLV 843 (segment 834 BH) | 692 | 692 | 692 | 435 (257) | 435 (257) | MLV 827-1 TO MLV 834-1: Pig run - Cleaning 4/15/19 - 4/18/19, Caliper 4/24/19, MFL 4/25/19 (4/15/2019 - 4/25/2019) |
| Sta 847 (segment 847 FH) | 618 | 618 | 618 | 205 (413) | 205 (413) | MLV 847-1 TO MLV 851-1: Pig Run - Cleaning 4/16/19, Gauge 4/23/19, MFL Combo 4/25/19, Hardspot/EMAT 4/30/19 (4/16/2019 - 4/30/2019) |
| Station 546 (segment 542 BH) | 1,508 | 1435 (73) | 1435 (73) | 1435 (73) | 1435 (73) | MLV 534-2 TO MLV 538-2: Make Piggable (M) (3/4/2019 - 4/29/2019) |
| Station 860 (segment 548 BH) | 1,537 | 1,537 | 1,537 | 1455 (82) | 1455 (82) | MLV 555-2 TO MLV 559-2: Pig run - Cleaning 4/17/19, Gauge 4/18/19, MFL Combo 4/23/19 (4/17/2019 - 4/23/2019) |
| Station 110 (segment 187 BH) (south thru Kentucky) | 2,659 | 2490 (169) | 2490 (169) | 2550 (109) | 2,659 | MLV 87-2D TO MLV 96-2S: Remediaton (3/25/2019 - 4/20/2019) MLV 106-1S TO MLV 96-1D: Pig run - Cleaning 4/2/19, MFL 4/4/19, Hardspot 4/9/19 (4/2/2019 - 4/9/2019) |
| Station 114 (segment 114 BH) | 919 | 919 | 919 | 919 | 445 (474) | MLV 118-1 to MLV 121-1A: Remediation (4/22/2019 - 4/27/2019) |
| Station 204 (Segment 204 BH) | 1,838 | 1735 (103) | 1735 (103) | 1,838 | 1,838 | MLV 214-2 TO MLV 209-2: Pig Runs - Cleaning 4/3/19, Gauge 4/4/19, AFD 4/9/19 (4/3/2019 - 4/10/2019) MLV 219-3 to MLV 214-3: Pig Run - Cleaning/Gauge 4/4/19, ILI 4/9/19, Hardspot 4/11/19 (4/4/2019 - 4/11/2019) |
| Station 245 (segment 245 FH) | 1,014 | 1,014 | 1,014 | 800 (214) | 800 (214) | Sta 245: Unit 1C: Borescope and Water Wash (4/15/2019 - 4/18/2019) Sta 249: ESD Piping Modification & Filter Separator Maintenance (4/15/2019 - 4/23/2019) |
| Station 254 (segment 256 FH) | 1,195 | 1,195 | 1,195 | 1,195 | 960 (235) | Sta 254: Filter Separator Maintenance (4/24/2019 - 4/27/2019) |
| Station 261 Discharge (segment 261 FH) | 896 | 896 | 896 | 896 | 896 | |
| Station 307 (segment 307 BH) | 1,150 | 1,150 | 1,150 | 1,150 | 1,150 | MLV 219-2 TO MLV 307-1: Remediaton (M) (4/8/2019 - 5/27/2019) |
| Station 315 (segment 315 BH) | 1,927 | 1,927 | 1,927 | 1,927 | 1,927 | |
| Sta. 325 (segment 324 FH) | 1,606 | 1,606 | 1,606 | 1,606 | 1,606 | |
| Sta. 405 HC Line (segment 299 FH) | 803 | 803 | 803 | 803 | 803 | |
| Station 229 (segment 224 FH) | 388 | 388 | 388 | 388 | 388 | |