

**TGP - Outage Impact Report
Seven Day Forecast (updated 06/04/26)**

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station / Seg	Est Nominal Operating Capacity (Thousand Dth)	Monday (6/8)	Tuesday (6/9)	Wednesday (6/10)	Thursday (6/11)	Friday (6/12)	Saturday (6/13)	Sunday (6/14)	Primary Outage(s) that may Impact Throughput
		Est. Operational Capacity (Operational Impact) - Thousand Dth							
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	564	564	564	
Station 1 (segment 101 BH)	399	399	399	399	399	399	399	399	
Station 9 (segment 109 BH)	1,027	904 (123)	904 (123)	945 (82)	945 (82)	945 (82)	945 (82)	945 (82)	MLV 4-1 to MLV 5-1: Emergent Repair (6/10/2026 - 7/1/2026) MLV 8-1BR to MLV 8-1: Emergent Repair (6/4/2026 - 6/9/2026)
Station 17 (segment 117 FH)	1,122	1104 (18)	1104 (18)	1104 (18)	1104 (18)	1104 (18)	1104 (18)	1104 (18)	MLV 19-2 TO MLV 20-2A: Pipe Replacement (M) (4/28/2026 - 6/19/2026)
Station 25 (segment 125 FH)	1,078	1,078	1,078	1,078	1,078	1,078	1,078	1,078	
Station 47 (segment 143 FH)	1,343	1330 (13)	1300 (43)	1330 (13)	1330 (13)	1330 (13)	1330 (13)	1330 (13)	MLV 40-3D to MLV 47-3S: Pig Run - Maintenance Cleaning (6/9/2026) MLV 55-1 to MLV 56-1: PHMSA Immediate (5/11/2026 - 7/31/2026)
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1117 (125)	1117 (125)	1117 (125)	1117 (125)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	734	734	734	
Station 834 (segment 834 BH)	683	220 (463)	510 (173)	220 (463)	220 (463)	220 (463)	220 (463)	220 (463)	Sta 827 (Alexandria): Annual ESD and Maintenance (6/8/2026 - 6/11/2026) Sta 827 to Sta 823: Pig Run - Maintenance (M) (6/8/2026) Sta 834 to Sta 827: Pig Run - Cleaning / Gauge 6/10/26 to 6/14/26 (M) (6/10/2026 - 6/14/2026) Sta 834: Unit 7A - Turbocharger/Overhaul (6/1/2026 - 6/11/2026)
Station 527 (segment 527 BH)	2,395	2340 (55)	2340 (55)	2340 (55)	2340 (55)	2340 (55)	2340 (55)	2340 (55)	Sta 527: Unit 1C - High Vibration (2/4/2026 - 7/3/2026)
Station 534 South of Pool (segment 530 BH)	1,550	1370 (180)	1528 (22)	1528 (22)	1528 (22)	1528 (22)	1528 (22)	1528 (22)	Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026) Sta 534: Annual ESD Test (6/8/2026) Sta 534: Unit 6A - Piston Liner & Unloader Replacements (6/30/2025 - 7/10/2026) Sta 534: Unit 7A - Oil Pump (6/9/2026 - 6/10/2026)
MLV 548 (segment 542 BH)	1,647	1435 (212)	1435 (212)	1435 (212)	1435 (212)	1435 (212)	1435 (212)	1435 (212)	Sta 542: Unit 1A - Emergent Repair (1/1/2026 - 6/18/2026) Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/14/2026) Sta 542: Unit 3A - Emergent Repair (3/26/2026 - 6/28/2026) Sta 546: Unit 7A - Metal in Oil (7/14/2025 - 6/19/2026)
Station 860 (segment 548 BH)	1,593	1580 (13)	1580 (13)	1580 (13)	1580 (13)	1580 (13)	1580 (13)	1580 (13)	Sta 555: Unit 5A - Foundation Regrout (1/20/2026 - 6/19/2026)
Station 860 North (Segment 860 BH)	1,874	1540 (334)	1540 (334)	1540 (334)	1540 (334)	1540 (334)	1540 (334)	1540 (334)	Sta 563 Joelton: Unit 2A - Solar Turbine Exchange (6/8/2026 - 6/17/2026) Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	1748 (937)	1748 (937)	1748 (937)	1748 (937)	2225 (460)	2415 (270)	2415 (270)	MLV 109-3: Crossover to Ln 5 Valve Replacements (5/28/2026 - 6/11/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 87-3 to MLV 96-3: Pig Run - Cal (6/9/2026) Sta 110 Morehead: Annual ESD Test & Substation Inspection (6/8/2026 - 6/12/2026) Sta 871: Unit 3A - Engine Crankshaft Inspection (8/22/2025 - 6/16/2026) Sta. 106: C Building - Install Water Trech System (6/8/2026 - 6/12/2026)
Station 114 (segment 114 BH)	907	907	907	907	812 (95)	907	907	907	Sta 119A: Unit 1A - Oil Cooler (6/11/2026)
Station 204 (Segment 204 BH)	1,828	1270 (558)	1270 (558)	1270 (558)	1270 (558)	1270 (558)	1,828	1,828	MLV 204-4 to MLV 206-4: Replace MLV 205-4 (M) (5/27/2026 - 6/12/2026) MLV 205-4 to MLV 207-4: Replace MLV 206-4 (M) (5/27/2026 - 6/12/2026) MLV 206-4 to MLV 208-4: Replace MLV 207-4 (M) (5/27/2026 - 6/12/2026) MLV 207-4 to MLV 209-4: Replace MLV 208-4 (M) (5/27/2026 - 6/12/2026)
Station 245 (segment 245 FH)	986	830 (156)	830 (156)	830 (156)	830 (156)	830 (156)	830 (156)	830 (156)	Sta 241: Unit 2B - Oil System (6/9/2026 - 6/11/2026) Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026) Sta 249: Unit 2B - 25k Overhaul (6/1/2026 - 6/26/2026)
Station 261 Discharge East (segment 261 FH)	888	500 (388)	500 (388)	500 (388)	500 (388)	500 (388)	888	888	Sta 261 Agawam: Unit Suction Valve Replacement (M) (6/8/2026 - 6/12/2026)
Station 307 (segment 307 BH)	1,153	1,153	1,153	770 (383)	770 (383)	770 (383)	770 (383)	770 (383)	MLV 306-2 to MLV 307-2: Anomaly Remediation (6/10/2026 - 6/15/2026) Sta 307: Unit 3A - Turbocharger swap (6/8/2026 - 6/12/2026)
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	1,823	1,823	1,823	
MLV 324 (segment 324 FH)	1,767	1,767	1,767	1,767	1,767	1,767	1,767	1,767	
MLV 329 (segment 324 FH)	846	846	500 (346)	500 (346)	500 (346)	846	846	846	MLV 325-1 to MLV 329-1: Pig runs - Call/IMU (M) (6/10/2026) MLV 325-1 to MLV 329-1: Pig runs - Cleaning/Gauge (M) (6/9/2026) MLV 325-1 to MLV 329-1: Pig runs - MFL-C (M) (6/11/2026)
Station 405 HC Line (segment 299 FH)	794	794	794	794	794	794	794	794	

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

**TGP - Outage Impact Report
June 2026 (updated 06/04/26)**

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1	Week 2	Week 3	Week 4	Primary Outage(s)
		(6/1 - 6/7)	(6/8 - 6/14)	(6/15 - 6/21)	(6/22 - 6/28)	
Est. Operational Capacity (Operational Impact) - Thousand Dth						
Station 409A (Alamo) (segment 492 FH)	274			274	125 (149)	MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (6/23/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (6/24/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - EMAT (M) (6/26/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - MFL-C (M) (6/25/2026)
Station 409 (Donna Line) (segment 490 FH)	564			564	564	
Station 1 (segment 101 BH)	399			399	399	
Station 9 (segment 109 BH)	1,027			945 (82)	945 (82)	MLV 4-1 to MLV 5-1: Emergent Repair (6/10/2026 - 7/1/2026)
Station 17 (segment 117 FH)	1,122			1080 (42)	1000 (122)	MLV 17-3DL to MLV 18-3A: Anomaly Remediation (6/15/2026 - 6/22/2026) MLV 19-2 TO MLV 20-2A: Pipe Replacement (M) (4/28/2026 - 6/19/2026) MLV 19-3 TO MLV 20-3A: Pipe Replacement (M) (6/22/2026 - 7/23/2026)
Station 25 (segment 125 FH)	1,078			1,078	1055 (23)	MLV 26-1 Relocation: Highway 59 Widening (6/22/2026 - 7/10/2026)
Station 47 (segment 143 FH)	1,343			1330 (13)	1330 (13)	MLV 55-1 to MLV 56-1: PHMSA Immediate (5/11/2026 - 7/31/2026)
Station 63 (segment 163 FH)	1,242			1117 (125)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026)
Station 823 (segment 823 BH)	734			734	734	
Station 834 (segment 834 BH)	683			220 (463)	590 (93)	Sta 834 to Sta 827: Pig Run - BH Ultimate MFLA Combo 6/16/26 (M) (6/16/2026) Sta 834 to Sta 827: Pig Run - Cleaning / Gauge 6/15/26 (M) (6/15/2026) Sta 834: Scrubber Filter Changeout (6/24/2026 - 6/26/2026) Sta 834: Station Outage (6/24/2026 - 6/25/2026)
Station 527 (segment 527 BH)	2,395			2340 (55)	2340 (55)	Sta 527: Unit 1C - High Vibration (2/4/2026 - 7/3/2026)
Station 534 South of Pool (segment 530 BH)	1,550			1528 (22)	1528 (22)	Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026) Sta 534: Unit 6A - Piston Liner & Unloader Replacements (6/30/2025 - 7/10/2026)
MLV 548 (segment 542 BH)	1,647			1215 (432)	1635 (12)	MLV 539-2 to MLV 540-2: Anomaly Remediation (6/18/2026 - 6/20/2026) Sta 542: Unit 1A - Emergent Repair (1/1/2026 - 6/18/2026) Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/14/2026) Sta 542: Unit 3A - Emergent Repair (3/26/2026 - 6/28/2026) Sta 546: Unit 7A - Metal in Oil (7/14/2025 - 6/19/2026)
Station 860 (segment 548 BH)	1,593			1580 (13)	1580 (13)	Sta 555: Unit 5A - Foundation Regrout (1/20/2026 - 6/19/2026) Sta. 555: Unit 4A - Engine Maintenance (6/22/2026 - 6/27/2026) Sta. 555: Unit 6A - Engine Maintenance (6/15/2026 - 6/18/2026)
Station 860 North (Segment 860 BH)	1,874			1530 (344)	1846 (28)	Sta 563 Joelton: Scrubber Filter Changeout (6/15/2026 - 6/17/2026) Sta 563 Joelton: Unit 2A - Solar Turbine Exchange (6/8/2026 - 6/17/2026) Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685			1895 (790)	1930 (755)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 87-3 to MLV 96-3: Pig Run - EMAT (6/16/2026) MLV 87-3 to MLV 96-3: Pig Run - MDS (6/23/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 9/30/2026) Sta 871 Campbellsville: Annual ESD Test (6/23/2026) Sta 871: Unit 3A - Engine Crankshaft Inspection (8/22/2025 - 6/16/2026)
Station 114 (segment 114 BH)	907			907	907	
Station 204 (Segment 204 BH)	1,828			1545 (283)	1,828	Sta 200 Greenup: Annual ESD Test (6/16/2026 - 6/19/2026) Sta 200: Unit 1B - Crankcase Inspection (6/16/2026 - 6/19/2026)
Station 219 to Station 224 (Segment 219 FH)	539			140 (399)	539	MLV 219-1D to MLV 224-1: Pig Run - Maintenance (6/16/2026)

TGP - Outage Impact Report June 2026 (updated 06/04/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (6/1 - 6/7)	Week 2 (6/8 - 6/14)	Week 3 (6/15 - 6/21)	Week 4 (6/22 - 6/28)	Primary Outage(s)
		Est. Operational Capacity (Operational Impact) - Thousand Dth				
Station 245 (segment 245 FH)	986			735 (251)	830 (156)	Sta 241: Annual ESD Test (6/16/2026) Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026) Sta 249: Unit 2B - 25k Overhaul (6/1/2026 - 6/26/2026)
Station 261 Discharge East (segment 261 FH)	888			888	888	
Station 307 (segment 307 BH)	1,153			770 (383)	1,153	MLV 306-2 to MLV 307-2: Anomaly Remediation (6/10/2026 - 6/15/2026)
Station 315 (segment 315 BH)	1,823			1,823	1,823	
MLV 324 (segment 324 FH)	1,767			1,767	1450 (317)	Sta 325: Station Outage (6/24/2026 - 6/25/2026)
Cranston Lateral South (segment 281 FH)	187			187	150 (37)	MLV 265E-101.1 to MLV 265E-104: PIG RUNS - Cal/IMU (M) (6/23/2026) ; MLV 265E-101.1 to MLV 265E-104: PIG RUNS - Gauge/Cleaning tool (M) (6/22/2026) ; MLV 265E-101.1 to MLV 265E-104: PIG RUNS - MFL-A (M) (6/24/2026)
Station 405 HC Line (segment 299 FH)	794			794	794	

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

TGP - Outage Impact Report July 2026 (updated 06/04/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (6/29 - 7/5)	Week 2 (7/6 - 7/12)	Week 3 (7/13 - 7/19)	Week 4 (7/20 - 7/26)	Week 5 (7/27 - 8/2)	Primary Outage(s)
		Est. Operational Capacity (Operational Impact) - Thousand Dth					
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	564	
Station 1 (segment 101 BH)	399	399	399	399	399	399	
Station 9 (segment 109 BH)	1,027	945 (82)	1,027	640 (387)	640 (387)	640 (387)	MLV 11-1A to MLV 11-1: Anomaly Remediation (7/27/2026 - 8/14/2026) MLV 1-2D to MLV 5-2: Pig Run - Cleaning Gauge (7/13/2026) MLV 1-2D to MLV 5-2: Pig Run - Cleaning Gauge (7/14/2026) MLV 1-2D to MLV 5-2: Pig Run - Cleaning Gauge (7/15/2026) MLV 1-2D to MLV 5-2: Pig Run - Cleaning Gauge (7/16/2026) MLV 1-2D to MLV 5-2: Pig Run - Cleaning Gauge (7/17/2026) MLV 1-2D to MLV 5-2: Pig Run - TDW MDS (7/21/2026) MLV 13-1 to MLV 12-1: Anomaly Remediation (7/27/2026 - 8/13/2026) MLV 4-1 to MLV 5-1: Emergent Repair (6/10/2026 - 7/1/2026) MLV 9-1D to MLV 10-1: Anomaly Remediation (7/27/2026 - 8/14/2026)
Station 17 (segment 117 FH)	1,122	1000 (122)	1000 (122)	1000 (122)	1000 (122)	1100 (22)	MLV 19-1 TO MLV 20-1A: Pipe Replacement (M) (7/25/2026 - 9/2/2026) MLV 19-3 TO MLV 20-3A: Pipe Replacement (M) (6/22/2026 - 7/23/2026)
Station 25 (segment 125 FH)	1,078	1055 (23)	1055 (23)	1070 (8)	955 (123)	1070 (8)	MLV 25-2 to MLV 26-2: Pipe Replacement (7/11/2026 - 7/29/2026) MLV 26-1 Relocation: Highway 59 Widening (6/22/2026 - 7/10/2026) MLV 26-2 Relocation: Highway 59 Widening (7/11/2026 - 7/29/2026) Sta 25: Annual ESD Test (7/21/2026)
Station 47 (segment 143 FH)	1,343	1330 (13)	1115 (228)	960 (383)	1330 (13)	1330 (13)	MLV 40-1D to MLV 47-1S: Pig Run - Maintenance (7/14/2026) MLV 40-4D to MLV 47-4S: Pig Run - Maintenance (7/9/2026) MLV 55-1 to MLV 56-1: PHMSA Immediate (5/11/2026 - 7/31/2026) Sta. 47: Station Transformer Maintenance (7/13/2026 - 7/14/2026)
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1117 (125)	901 (341)	901 (341)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 77-3 to MLV 77-3A: Pipe Replacements (7/20/2026 - 7/27/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	734	
Station 823 Muskrat Line (segment 509 BH)	231	130 (101)	231	231	231	231	Sta 823 to MLV 516: Pig Run - Maintenance (M) (6/30/2026)
MLV 516 Muskrat Line (segment 516 FH)	241	241	100 (141)	241	241	241	Sta 523 to MLV 516: Pig Run - Chemical Cleaning / Gauge 7/6/26 to 7/10/26 (M) (7/6/2026 - 7/10/2026) Sta 523 to MLV 516: Pig Run - MFL-A 7/11/26 (M) (7/11/2026)
Station 527 (segment 527 BH)	2,395	2340 (55)	2,395	2,395	2,395	2,395	Sta 527: Unit 1C - High Vibration (2/4/2026 - 7/3/2026)
Station 534 South of Pool (segment 530 BH)	1,550	1528 (22)	1528 (22)	1528 (22)	1528 (22)	1528 (22)	Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026) Sta 534: Unit 6A - Piston Liner & Unloader Replacements (6/30/2025 - 7/10/2026)
MLV 548 (segment 542 BH)	1,647	1640 (7)	1640 (7)	1640 (7)	1640 (7)	1640 (7)	Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/14/2026)
Station 860 (segment 548 BH)	1,593	1,593	1,593	1585 (8)	1430 (163)	1,593	MLV 557-3 to MLV 559-3: Pig Runs - Cal / IMU & MFL-A 6/4/26 (7/16/2026) MLV 557-3 to MLV 559-3: Pig Runs - Cleaning / Gauge 6/2/26 (7/14/2026) Sta 555: Scrubber/Filter/Separator Clean, Inspect & Filter Change (7/21/2026 - 7/22/2026)
Station 860 North (Segment 860 BH)	1,874	1846 (28)	1846 (28)	1846 (28)	1846 (28)	1846 (28)	Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2534 (151)	2358 (327)	2040 (645)	2150 (535)	2150 (535)	MLV 104-1 to MLV 105-1: Anomaly Remediation (7/13/2026 - 8/15/2026) MLV 107-7 to 110-7: Valve Installation & Crossover Work (7/7/2026 - 7/27/2026) MLV 109-4 to 110-4: Valve Installation & Crossover Work (7/28/2026 - 8/11/2026) MLV 109-4 to MLV 110-4: Pipe Replacement (7/28/2026 - 8/11/2026) MLV 109-7 to MLV 110-7: Pipe Replacement (7/7/2026 - 7/27/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 96-3BR to MLV 96-3BL: Spike Test (7/27/2026 - 8/31/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 9/30/2026) Sta 96 Campbellsville: Annual ESD Test (7/14/2026 - 7/15/2026) Sta 96 Campbellsville: Annual Substation Inspection (7/13/2026 - 7/16/2026) Sta 96: Unit 2D Replace Compressor Valves (7/5/2026 - 7/9/2026)
Station 114 (segment 114 BH)	907	600 (307)	907	907	907	907	Sta 114: Unit 1D - Solar Turbine Inspection (6/29/2026 - 7/1/2026)

**TGP - Outage Impact Report
July 2026 (updated 06/04/26)**

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (6/29 - 7/5)	Week 2 (7/6 - 7/12)	Week 3 (7/13 - 7/19)	Week 4 (7/20 - 7/26)	Week 5 (7/27 - 8/2)	Primary Outage(s)
		Est. Operational Capacity (Operational Impact) - Thousand Dth					
Station 204 (Segment 204 BH)	1,828	1,828	1,828	1,828	1,828	1,828	
Station 230C (segment 296 FH)	743	743	743	370 (373)	743	743	Sta 230C: Annual ESD (M) (7/13/2026 - 7/14/2026)
Station 237 (segment 237 FH)	1,006	1,006	1,006	1,006	1,006	780 (226)	MLV 237-1 to MLV 245-1: Pig Run - Cleaning/Gauge (7/27/2026) MLV 237-1 to MLV 245-1: Pig Run - MFL-C (7/29/2026)
Station 245 (segment 245 FH)	986	970 (16)	970 (16)	760 (226)	970 (16)	970 (16)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026) Sta 245-1 to MLV 249-1: Pig Run - Call/IMU (7/15/2026) Sta 245-1 to MLV 249-1: Pig Run - Gauge/Cleaning tool (7/14/2026) Sta 245-1 to MLV 249-1: Pig Run - MFL-C (7/16/2026)
MLV 256 West (segment 249 FH)	1,203	1,203	1,203	1,203	535 (668)	1,203	MLV 249-2 to MLV 254-2: Gauge/Cleaning tool (7/20/2026) MLV 249-2 to MLV 254-2: Hardspot/Geo (7/23/2026) MLV 249-2 to MLV 254-2: MFL-A/IMU (7/21/2026)
Station 261 Discharge East (segment 261 FH)	888	888	888	888	888	888	
Station 307 (segment 307 BH)	1,153	1,153	1,153	1,153	930 (223)	1115 (38)	Sta 219: Unit 1B - Protective Device Checks & GHG (7/20/2026 - 7/24/2026) Sta 219: Unit 1B - Save Air System (7/20/2026 - 7/31/2026) Sta 307: Unit 1A - Protective Device Checks (7/20/2026 - 7/24/2026) Sta 307: Unit 2A - Protective Device Checks (7/20/2026 - 7/24/2026) Sta 307: Unit 3A - Protective Device Checks (7/20/2026 - 7/24/2026) Sta 307: Unit 4A - Protective Device Checks (7/20/2026 - 7/24/2026)
Station 313 Discharge (segment 399 FH)	797	720 (77)	797	797	797	797	Sta 313: Unit 1C - Substation Inspection (6/30/2026 - 7/1/2026)
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	1,823	
Station 321 (segment 321 FH)	2,102	2,102	2,102	2,102	1715 (387)	2,102	Sta 321: Station Valves for ESD System (7/21/2026 - 7/23/2026)
MLV 324 (segment 324 FH)	1,767	1,767	1735 (32)	1,767	1,767	1,767	Sta 325: Units 4A - Water Wash & Borescope (7/6/2026 - 7/7/2026)
Station 405 HC Line (segment 299 FH)	794	794	680 (114)	794	794	794	Sta 405A: Annual ESD Test / Filter Scrubber (7/7/2026 - 7/9/2026)

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

TGP - Outage Impact Report
August 2026 (updated 06/04/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1	Week 2	Week 3	Week 4	Primary Outage(s)
		(8/3 - 8/9)	(8/10 - 8/16)	(8/17 - 8/23)	(8/24 - 8/30)	
Est. Operational Capacity (Operational Impact) - Thousand Dth						
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	
Station 1 (segment 101 BH)	399	399	399	399	399	
Station 9 (segment 109 BH)	1,027	768 (259)	768 (259)	969	969	MLV 11-1A to MLV 11-1: Anomaly Remediation (7/27/2026 - 8/14/2026) MLV 13-1 to MLV 12-1: Anomaly Remediation (7/27/2026 - 8/13/2026) MLV 9-1D to MLV 10-1: Anomaly Remediation (7/27/2026 - 8/14/2026)
Station 17 (segment 117 FH)	1,122	1100 (22)	1100 (22)	1100 (22)	1100 (22)	MLV 19-1 TO MLV 20-1A: Pipe Replacement (M) (7/25/2026 - 9/2/2026)
Station 25 (segment 125 FH)	1,078	925 (153)	925 (153)	925 (153)	1,078	MLV 26-3 Relocation: Highway 59 Widening (M) (8/3/2026 - 8/20/2026)
Station 47 (segment 143 FH)	1,343	1,343	1,343	1,343	1,343	
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1117 (125)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 82-2C to MLV 83-2: Anomaly Remediation (8/3/2026 - 8/7/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	
Station 534 South of Pool (segment 530 BH)	1,550	1528 (22)	1528 (22)	1528 (22)	1528 (22)	Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026)
MLV 548 (segment 542 BH)	1,647	1640 (7)	1640 (7)	1,647	1235 (412)	Sta 542 Dekalb: Annual ESD Test (8/25/2026 - 8/27/2026) Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/14/2026)
Station 860 (segment 548 BH)	1,593	1,593	1,593	1,593	1,593	
Station 860 North (Segment 860 BH)	1,874	1846 (28)	1846 (28)	1846 (28)	1846 (28)	Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2457 (228)	2470 (215)	2308 (377)	2050 (635)	MLV 104-1 to MLV 105-1: Anomaly Remediation (7/13/2026 - 8/15/2026) MLV 109-4 to 110-4: Valve Installation & Crossover Work (7/28/2026 - 8/11/2026) MLV 109-4 to MLV 110-4: Pipe Replacement (7/28/2026 - 8/11/2026) MLV 109-5 to MLV 109-5A: Pipe Replacement (8/18/2026 - 9/1/2026) MLV 109-5A to MLV 110-5: Pipe Replacement (8/18/2026 - 9/1/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 96-3BR to MLV 96-3BL: Spike Test (7/27/2026 - 8/31/2026) Sta 110: Install ESD Silence Covers (8/24/2026 - 8/28/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 9/30/2026) Sta 875: Unit 1A- 8K Solar Turbine Inspection (8/17/2026 - 8/21/2026) Sta 96: Unit 2D - Install Ball Grove Valve (8/3/2026 - 8/7/2026)
Station 114 (segment 114 BH)	907	907	393 (514)	393 (514)	393 (514)	MLV 117-3 to MLV 118-3: Special Permit Pipe Replacement (8/10/2026 - 8/31/2026) MLV 119-2 to MLV 119-2A: Special Permit Pipe Replacement (8/10/2026 - 8/31/2026) Sta 119A: Unit 1A - Solar Turbine Inspection (8/10/2026 - 8/12/2026)
Station 204 (Segment 204 BH)	1,828	1,828	1,828	1770 (58)	1770 (58)	MLV 202-2 to MLV 203-2: CLASS CHANGE REPLACEMENT TGP 202-2 (8/17/2026 - 9/26/2026)
Station 245 (segment 245 FH)	986	970 (16)	970 (16)	970 (16)	970 (16)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026)
Station 261 Discharge East (segment 261 FH)	888	720 (168)	888	888	888	Sta 261: Unit 2D - Engine Inspection & Borescope (8/3/2026 - 8/7/2026)
Station 307 (segment 307 BH)	1,153	965 (188)	1,153	765 (388)	1,153	Sta 219: Annual ESD Test & Scrubber Maintenance (8/17/2026 - 8/21/2026) Sta 307 (Pigeon): Annual ESD Test & Maintenance (8/3/2026 - 8/7/2026)
Station 313 Discharge (segment 399 FH)	797	797	797	515 (282)	797	Sta 313 Coudersport: Annual ESD Test & Maintenance (8/17/2026 - 8/20/2026)

TGP - Outage Impact Report August 2026 (updated 06/04/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1	Week 2	Week 3	Week 4	Primary Outage(s)
		(8/3 - 8/9)	(8/10 - 8/16)	(8/17 - 8/23)	(8/24 - 8/30)	
		Est. Operational Capacity (Operational Impact) - Thousand Dth				
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	
Station 317 (segment 317 BH)	1,548	1,548	1,548	1,548	1345 (203)	Sta 317: Annual ESD Test & Maintenance (8/24/2026 - 8/28/2026)
MLV 324 (segment 324 FH)	1,767	1,767	1,767	1,767	1,767	
Station 405 HC Line (segment 299 FH)	794	794	794	794	794	
Station 224 (segment 224 FH)	388	388	388	388	280 (108)	Station 224: Scrubber Inspections & Filter Change (8/25/2026 - 8/26/2026)

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.