

**TGP - Outage Impact Report
Seven Day Forecast (updated 06/18/26)**

-Primary impact restrictions may be necessary
-Major impact restrictions may be necessary
-Minor impact restrictions may be necessary depending on flow conditions
-Little to no impact, though minor outages may cause incremental reductions

Station / Seg	Est Nominal Operating Capacity (Thousand Dth)	Monday (6/22)	Tuesday (6/23)	Wednesday (6/24)	Thursday (6/25)	Friday (6/26)	Saturday (6/27)	Sunday (6/28)	Primary Outage(s) that may Impact Throughput
		Est. Operational Capacity (Operational Impact) - Thousand Dth							
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	564	564	564	
Station 1 (segment 101 BH)	399	399	399	399	399	399	399	399	
Station 9 (segment 109 BH)	1,027	945 (82)	945 (82)	945 (82)	945 (82)	945 (82)	945 (82)	945 (82)	MLV 4-1 to MLV 5-1: Emergent Repair (6/9/2026 - 7/1/2026)
Station 17 (segment 117 FH)	1,122	1104 (18)	1104 (18)	1104 (18)	1104 (18)	1104 (18)	1104 (18)	1,122	MLV 19-2 TO MLV 20-2A: Pipe Replacement (M) (4/28/2026 - 6/27/2026)
Station 25 (segment 125 FH)	1,078	1055 (23)	1055 (23)	1055 (23)	1055 (23)	1055 (23)	1055 (23)	1055 (23)	MLV 26-1 Relocation: Highway 59 Widening (6/22/2026 - 7/10/2026)
Station 40 KN South (segment 501 FH)	267	267	267	267	200 (67)	267	267	267	Sta 500C1: Install 500 Line Indicator (6/25/2026)
Station 47 (segment 143 FH)	1,343	1330 (13)	1330 (13)	1330 (13)	1330 (13)	1330 (13)	1330 (13)	1330 (13)	MLV 55-1 to MLV 56-1: PHMSA Immediate (5/11/2026 - 7/31/2026)
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1117 (125)	1117 (125)	1117 (125)	1117 (125)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	734	734	734	
Station 834 (segment 834 BH)	683	683	683	590 (93)	590 (93)	590 (93)	683	683	Sta 834: Scrubber Filter Changeout (6/24/2026 - 6/26/2026) Sta 834: Station Outage (6/24/2026 - 6/26/2026)
Station 534 South of Pool (segment 530 BH)	1,550	985 (565)	985 (565)	985 (565)	985 (565)	985 (565)	1528 (22)	1528 (22)	MLV 533-2 to MLV 534-2: Pipe Replacement (M) (6/4/2026 - 6/26/2026) Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026) Sta 534: Unit 6A - Piston Liner & Unloader Replacements (6/30/2025 - 7/10/2026)
MLV 548 (segment 542 BH)	1,647	1600 (47)	1600 (47)	1600 (47)	1600 (47)	1600 (47)	1600 (47)	1600 (47)	Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/31/2026) Sta 542: Unit 3A - Emergent Repair (3/26/2026 - 7/31/2026) Sta 546: Unit 7A - Metal in Oil (7/14/2025 - 7/31/2026)
Station 860 (segment 548 BH)	1,593	1580 (13)	1580 (13)	1580 (13)	1580 (13)	1580 (13)	1580 (13)	1,593	Sta 555: Unit 4A - Engine Maintenance (6/22/2026 - 6/27/2026)
Station 860 North (Segment 860 BH)	1,874	1846 (28)	1846 (28)	1846 (28)	1846 (28)	1846 (28)	1846 (28)	1846 (28)	Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2415 (270)	2415 (270)	2415 (270)	2415 (270)	2415 (270)	2534 (151)	2534 (151)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 9/30/2026) Sta 871 Campbellsville: Annual ESD Test (6/25/2026) Sta 871: Unit 3A - Engine Crankshaft Inspection (8/22/2025 - 6/26/2026)
Station 114 (segment 114 BH)	907	907	907	907	907	907	907	907	
Station 204 (Segment 204 BH)	1,828	1790 (38)	1790 (38)	1790 (38)	1790 (38)	1790 (38)	1790 (38)	1790 (38)	MLV 206-2 to MLV 207-2: Anomaly Remediation (6/22/2026 - 7/2/2026)
Station 219 to Station 224 (Segment 219 FH)	539	539	140 (399)	539	539	539	539	539	MLV 219-1D to MLV 224-1: Pig Run - Maintenance (6/23/2026)
Station 245 (segment 245 FH)	986	830 (156)	830 (156)	830 (156)	830 (156)	830 (156)	970 (16)	970 (16)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026) Sta 249: Unit 2B - 25k Overhaul (6/1/2026 - 6/26/2026)
Station 261 Discharge East (segment 261 FH)	888	888	888	888	888	888	888	888	
Station 307 (segment 307 BH)	1,153	1,153	1,153	1,153	1,153	1,153	1,153	1,153	
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	1,823	1,823	1,823	
MLV 324 (segment 324 FH)	1,767	1,767	1,767	1,767	1,767	1,767	1,767	1,767	
Cranston Lateral South (segment 281 FH)	187	150 (37)	150 (37)	150 (37)	187	187	187	187	MLV 265E-101.1 to MLV 265E-104: PIG RUNS - Cal/IMU (M) (6/23/2026) ; MLV 265E-101.1 to MLV 265E-104: PIG RUNS - Gauge/Cleaning tool (M) (6/22/2026) ; MLV 265E-101.1 to MLV 265E-104: PIG RUNS - MFL-A (M) (6/24/2026)
Station 405 HC Line (segment 299 FH)	794	794	794	794	794	794	794	794	

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

TGP - Outage Impact Report July 2026 (updated 06/18/26)							-Primary impact restrictions may be necessary
							-Major impact restrictions may be necessary
							-Minor impact restrictions may be necessary depending on flow conditions
							-Little to no impact, though minor outages may cause incremental reductions
Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (6/29 - 7/5)	Week 2 (7/6 - 7/12)	Week 3 (7/13 - 7/19)	Week 4 (7/20 - 7/26)	Week 5 (7/27 - 8/2)	Primary Outage(s)
		Est. Operational Capacity (Operational Impact) - Thousand Dth					
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	564	
Station 1 (segment 101 BH)	399	399	399	399	399	399	
Station 9 (segment 109 BH)	1,027	945 (82)	1,027	640 (387)	640 (387)	1015 (12)	MLV 4-1 to MLV 5-1: Emergent Repair (6/9/2026 - 7/1/2026) MLV 5-2 to MLV 1-2D: Pig Run - Cleaning Gauge (M) (7/13/2026) MLV 5-2 to MLV 1-2D: Pig Run - Cleaning Gauge (M) (7/14/2026) MLV 5-2 to MLV 1-2D: Pig Run - Cleaning Gauge (M) (7/15/2026) MLV 5-2 to MLV 1-2D: Pig Run - Cleaning Gauge (M) (7/16/2026) MLV 5-2 to MLV 1-2D: Pig Run - Cleaning Gauge (M) (7/17/2026) MLV 5-2 to MLV 1-2D: Pig Run - TDW MDS (M) (7/21/2026) MLV 9-1D to MLV 10-1: Anomaly Remediation (7/27/2026 - 8/2/2026)
Station 17 (segment 117 FH)	1,122	1000 (122)	1000 (122)	1000 (122)	1000 (122)	1000 (122)	MLV 17-3DL to MLV 18-3A: Anomaly Remediation (7/1/2026 - 7/7/2026) MLV 19-3 TO MLV 20-3A: Pipe Replacement (M) (7/1/2026 - 7/31/2026)
Station 25 (segment 125 FH)	1,078	1055 (23)	1055 (23)	1070 (8)	955 (123)	1070 (8)	MLV 25-2 to MLV 26-2: Pipe Replacement (7/11/2026 - 7/29/2026) MLV 26-1 Relocation: Highway 59 Widening (6/22/2026 - 7/10/2026) MLV 26-2 Relocation: Highway 59 Widening (7/11/2026 - 7/29/2026) Sta 25: Annual ESD Test (7/21/2026)
Station 47 (segment 143 FH)	1,343	1330 (13)	1330 (13)	1020 (323)	1330 (13)	1330 (13)	MLV 55-1 to MLV 56-1: PHMSA Immediate (5/11/2026 - 7/31/2026) Sta 47: Station Transformer Maintenance (7/13/2026 - 7/14/2026)
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1117 (125)	901 (341)	901 (341)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 77-3 to MLV 77-3A: Pipe Replacements (7/20/2026 - 7/27/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	734	
Station 823 Muskrat Line (segment 509 BH)	231	130 (101)	231	231	231	231	Sta 823 to MLV 516: Pig Run - Maintenance (M) (6/30/2026)
MLV 516 Muskrat Line (segment 516 FH)	241	241	100 (141)	241	241	241	Sta 523 to MLV 516: Pig Run - Chemical Cleaning / Gauge 7/6/26 to 7/10/26 (M) (7/6/2026 - 7/10/2026) Sta 523 to MLV 516: Pig Run - MFL-A 7/11/26 (M) (7/11/2026)
Station 534 South of Pool (segment 530 BH)	1,550	1528 (22)	1528 (22)	1528 (22)	1528 (22)	1528 (22)	Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026) Sta 534: Unit 6A - Piston Liner & Unloader Replacements (6/30/2025 - 7/10/2026)
MLV 548 (segment 542 BH)	1,647	1600 (47)	1600 (47)	1600 (47)	1600 (47)	1600 (47)	MLV 539-2 to MLV 540-2: Anomaly Remediation (7/9/2026 - 7/13/2026) Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/31/2026) Sta 542: Unit 3A - Emergent Repair (3/26/2026 - 7/31/2026) Sta 546: Unit 7A - Metal in Oil (7/14/2025 - 7/31/2026)
Station 860 (segment 548 BH)	1,593	1,593	1,593	1585 (8)	1430 (163)	1,593	MLV 557-3 to MLV 559-3: Pig Runs - Cal / IMU & MFL-A 6/4/26 (7/16/2026) MLV 557-3 to MLV 559-3: Pig Runs - Cleaning / Gauge 6/2/26 (7/14/2026) Sta 555: Scrubber/Filter/Separator Clean, Inspect & Filter Change (7/21/2026 - 7/22/2026)
Station 860 North (Segment 860 BH)	1,874	1846 (28)	1846 (28)	1846 (28)	1846 (28)	1846 (28)	Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2534 (151)	2280 (405)	2098 (587)	2150 (535)	2150 (535)	MLV 104-1 to MLV 105-1: Anomaly Remediation (7/13/2026 - 8/15/2026) MLV 107-7 to 110-7: Valve Installation & Crossover Work (7/7/2026 - 7/27/2026) MLV 109-4 to 110-4: Valve Installation & Crossover Work (7/28/2026 - 8/11/2026) MLV 109-4 to MLV 110-4: Pipe Replacement (7/28/2026 - 8/11/2026) MLV 109-7 to MLV 110-7: Pipe Replacement (7/7/2026 - 7/27/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 87-3 to MLV 96-3: Pig Run - EMAT (7/21/2026) MLV 87-3 to MLV 96-3: Pig Run - MDS (7/7/2026) MLV 96-3BR to MLV 96-3BL: Spike Test (7/27/2026 - 8/31/2026) Sta 106: C Building - Install Water Trech System (7/13/2026 - 7/17/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 9/30/2026) Sta 96 Campbellsville: Annual ESD Test (7/14/2026 - 7/15/2026) Sta 96 Campbellsville: Annual Substation Inspection (7/13/2026 - 7/16/2026) Sta 96: Unit 2D Replace Compressor Valves (7/5/2026 - 7/9/2026)
Station 114 (segment 114 BH)	907	600 (307)	907	907	907	907	Sta 114: Unit 1D - Solar Turbine Inspection (6/29/2026 - 7/1/2026)
Station 204 (Segment 204 BH)	1,828	1790 (38)	1,828	1,828	1,828	1,828	MLV 206-2 to MLV 207-2: Anomaly Remediation (6/22/2026 - 7/2/2026)

**TGP - Outage Impact Report
July 2026 (updated 06/18/26)**

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1 (6/29 - 7/5)	Week 2 (7/6 - 7/12)	Week 3 (7/13 - 7/19)	Week 4 (7/20 - 7/26)	Week 5 (7/27 - 8/2)	Primary Outage(s)
		Est. Operational Capacity (Operational Impact) - Thousand Dth					
Station 230C (segment 296 FH)	743	743	743	370 (373)	743	743	Sta 230C: Annual ESD (M) (7/13/2026 - 7/14/2026)
Station 237 (segment 237 FH)	1,006	1,006	1,006	1,006	1,006	780 (226)	MLV 237-1 to MLV 245-1: Pig Run - Cleaning/Gauge (7/27/2026) MLV 237-1 to MLV 245-1: Pig Run - MFL-C (7/29/2026)
Station 245 (segment 245 FH)	986	970 (16)	970 (16)	760 (226)	970 (16)	970 (16)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026) Sta 245-1 to MLV 249-1: Pig Run - Cal/IMU (7/15/2026) Sta 245-1 to MLV 249-1: Pig Run - Gauge/Cleaning tool (7/14/2026) Sta 245-1 to MLV 249-1: Pig Run - MFL-C (7/16/2026)
MLV 256 West (segment 249 FH)	1,203	1,203	1,203	1,203	535 (668)	1,203	MLV 249-2 to MLV 254-2: Gauge/Cleaning tool (7/20/2026) MLV 249-2 to MLV 254-2: Hardspot/Geo (7/23/2026) MLV 249-2 to MLV 254-2: MFL-A/IMU (7/21/2026)
Station 261 Discharge East (segment 261 FH)	888	560 (328)	888	888	888	888	Sta 264 Charlton: Controls Upgrade (6/29/2026 - 6/30/2026)
Station 307 (segment 307 BH)	1,153	1,153	775 (378)	775 (378)	930 (223)	1115 (38)	MLV 302-2 to MLV 303-2: Anomaly Remediation (7/7/2026 - 7/18/2026) Sta 219: Unit 1B - Protective Device Checks & GHG (7/20/2026 - 7/24/2026) Sta 219: Unit 1B - Save Air System (7/20/2026 - 7/31/2026) Sta 307: Unit 1A - Protective Device Checks (7/20/2026 - 7/24/2026) Sta 307: Unit 2A - Protective Device Checks (7/20/2026 - 7/24/2026) Sta 307: Unit 3A - Protective Device Checks (7/20/2026 - 7/24/2026) Sta 307: Unit 4A - Protective Device Checks (7/20/2026 - 7/24/2026)
Station 313 Discharge (segment 399 FH)	797	720 (77)	797	797	797	797	Sta 313: Unit 1C - Substation Inspection (6/30/2026 - 7/1/2026)
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	1,823	
Station 321 (segment 321 FH)	2,102	2,102	2,102	2,102	1715 (387)	2,102	Sta 321: Station Valves for ESD System (7/21/2026 - 7/23/2026)
MLV 324 (segment 324 FH)	1,767	1,767	1735 (32)	1,767	1,767	1450 (317)	Sta 325: Station Outage (7/28/2026 - 7/30/2026) Sta 325: Units 4A - Water Wash & Borescope (7/6/2026 - 7/7/2026)
Station 405 HC Line (segment 299 FH)	794	794	680 (114)	794	794	794	Sta 405A: Annual ESD Test / Filter Scrubber (7/7/2026 - 7/9/2026)

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

TGP - Outage Impact Report
August 2026 (updated 06/18/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1	Week 2	Week 3	Week 4	Primary Outage(s)
		(8/3 - 8/9)	(8/10 - 8/16)	(8/17 - 8/23)	(8/24 - 8/30)	
Est. Operational Capacity (Operational Impact) - Thousand Dth						
Station 409 (Donna Line) (segment 490 FH)	564	564	564	564	564	
Station 1 (segment 101 BH)	399	399	399	399	399	
Station 9 (segment 109 BH)	1,027	985 (42)	945 (82)	945 (82)	1,027	MLV 11-1A to MLV 11-1: Anomaly Remediation (8/3/2026 - 8/9/2026) MLV 13-1 to MLV 12-1: Anomaly Remediation (8/10/2026 - 8/19/2026)
Station 17 (segment 117 FH)	1,122	1100 (22)	1100 (22)	1100 (22)	1100 (22)	MLV 19-1 TO MLV 20-1A: Pipe Replacement (M) (8/4/2026 - 9/12/2026)
Station 25 (segment 125 FH)	1,078	925 (153)	925 (153)	925 (153)	1,078	MLV 26-3 Relocation: Highway 59 Widening (M) (8/3/2026 - 8/20/2026)
Station 47 (segment 143 FH)	1,343	1255 (88)	1105 (238)	1,343	1,343	MLV 40-1D to MLV 47-1S: Pig Run - Maintenance (8/4/2026) MLV 40-3D to MLV 47-3S: Pig Run - Maintenance Cleaning (8/11/2026) MLV 40-4D to MLV 47-4S: Pig Run - Maintenance (8/13/2026)
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1117 (125)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 82-2C to MLV 83-2: Anomaly Remediation (8/3/2026 - 8/7/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	
Station 534 South of Pool (segment 530 BH)	1,550	1528 (22)	1528 (22)	1528 (22)	1528 (22)	Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026)
MLV 548 (segment 542 BH)	1,647	1640 (7)	1640 (7)	1640 (7)	1235 (412)	Sta 542 Dekalb: Annual ESD Test (8/25/2026 - 8/27/2026) Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/31/2026)
Station 860 (segment 548 BH)	1,593	1,593	1,593	1,593	1,593	
Station 860 North (Segment 860 BH)	1,874	1846 (28)	1846 (28)	1846 (28)	1846 (28)	Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2457 (228)	2470 (215)	2308 (377)	2050 (635)	MLV 104-1 to MLV 105-1: Anomaly Remediation (7/13/2026 - 8/15/2026) MLV 109-4 to 110-4: Valve Installation & Crossover Work (7/28/2026 - 8/11/2026) MLV 109-4 to MLV 110-4: Pipe Replacement (7/28/2026 - 8/11/2026) MLV 109-5 to MLV 109-5A: Pipe Replacement (8/18/2026 - 9/1/2026) MLV 109-5A to MLV 110-5: Pipe Replacement (8/18/2026 - 9/1/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 96-3BR to MLV 96-3BL: Spike Test (7/27/2026 - 8/31/2026) Sta 110: Install ESD Silence Covers (8/24/2026 - 8/28/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 9/30/2026) Sta 875: Unit 1A- 8K Solar Turbine Inspection (8/17/2026 - 8/21/2026) Sta 96: Unit 2D - Install Ball Grove Valve (8/3/2026 - 8/7/2026)
Station 114 (segment 114 BH)	907	907	393 (514)	393 (514)	393 (514)	MLV 117-3 to MLV 118-3: Special Permit Pipe Replacement (8/10/2026 - 8/31/2026) MLV 119-2 to MLV 119-2A: Special Permit Pipe Replacement (8/10/2026 - 8/31/2026) Sta 119A: Unit 1A - Solar Turbine Inspection (8/10/2026 - 8/12/2026)
Station 204 (Segment 204 BH)	1,828	1,828	1,828	1,828	1,828	
Station 245 (segment 245 FH)	986	970 (16)	970 (16)	970 (16)	970 (16)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026)
Station 261 Discharge East (segment 261 FH)	888	888	888	888	888	
Station 307 (segment 307 BH)	1,153	965 (188)	1,153	765 (388)	1,153	Sta 219: Annual ESD Test & Scrubber Maintenance (8/17/2026 - 8/21/2026) Sta 307 (Pigeon): Annual ESD Test & Maintenance (8/3/2026 - 8/7/2026)
Station 313 Discharge (segment 399 FH)	797	797	797	500 (297)	797	Sta 313 Coudersport: Annual ESD Test & Maintenance (8/17/2026 - 8/20/2026)

TGP - Outage Impact Report August 2026 (updated 06/18/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1	Week 2	Week 3	Week 4	Primary Outage(s)
		(8/3 - 8/9)	(8/10 - 8/16)	(8/17 - 8/23)	(8/24 - 8/30)	
		Est. Operational Capacity (Operational Impact) - Thousand Dth				
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	
Station 317 (segment 317 BH)	1,548	1,548	1,548	1,548	1345 (203)	Sta 317: Annual ESD Test & Maintenance (8/24/2026 - 8/28/2026)
MLV 324 (segment 324 FH)	1,767	1,767	1,767	1,767	1,767	
Station 405 HC Line (segment 299 FH)	794	794	794	794	794	
Station 224 (segment 224 FH)	388	388	388	388	280 (108)	Station 224: Scrubber Inspections & Filter Change (8/25/2026 - 8/26/2026)

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.

TGP - Outage Impact Report
September 2026 (updated 06/18/26)

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1	Week 2	Week 3	Week 4	Primary Outage(s)
		(8/31 - 9/6)	(9/7 - 9/13)	(9/14 - 9/20)	(9/21 - 9/27)	
Est. Operational Capacity (Operational Impact) - Thousand Dth						
Station 409A (Alamo) (segment 492 FH)	274	274	125 (149)	274	274	MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (9/7/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (9/8/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - Cleaning / Gauge (M) (9/9/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - EMAT (M) (9/11/2026) MLV 409A-101.1 to MLV 409A-103: Pig Runs - MFL-C (M) (9/10/2026)
Station 1 (segment 101 BH)	399	300 (99)	300 (99)	300 (99)	300 (99)	MLV 1-1D to MLV 3-1: Spike Test (M) (9/1/2026 - 9/21/2026) MLV 2-1 to MLV 4-1: Spike Test (M) (9/22/2026 - 10/12/2026)
Station 9 (segment 109 BH)	1,027	1,027	1,027	1,027	1,027	
Station 17 (segment 117 FH)	1,122	1100 (22)	1100 (22)	1,122	1,122	MLV 19-1 TO MLV 20-1A: Pipe Replacement (M) (8/4/2026 - 9/12/2026)
Station 25 (segment 125 FH)	1,078	1,078	1,078	1,078	1,078	
Station 47 (segment 143 FH)	1,343	1045 (298)	1045 (298)	1285 (58)	1,343	MLV 47-4D to MLV 54-4S: Pig Run - AFD Combo (M) (9/8/2026) MLV 47-4D to MLV 54-4S: Pig Run - EMAT (M) (9/10/2026) MLV 47-4D to MLV 54-4S: Pig Run - Gauge Cleaning (M) (8/31/2026) MLV 47-4D to MLV 54-4S: Pig Run - Gauge Cleaning (M) (9/1/2026) MLV 47-4D to MLV 54-4S: Pig Run - Gauge Cleaning (M) (9/2/2026) Sta 47: Unit 1E - Solar Seal Gas System Filtration Install (9/14/2026 - 9/18/2026)
Station 63 (segment 163 FH)	1,242	1117 (125)	1117 (125)	1117 (125)	1117 (125)	MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026)
Station 823 (segment 823 BH)	734	734	734	734	734	
Station 834 (segment 834 BH)	683	683	670 (13)	670 (13)	670 (13)	Sta 834: Unit 1A - Replace Insulation Blanket (9/14/2026 - 9/15/2026) Sta 834: Unit 2A - Replace Insulation Blanket (9/16/2026 - 9/17/2026) Sta 834: Unit 3A - Replace Insulation Blanket (9/18/2026 - 9/19/2026) Sta 834: Unit 4A - Replace Insulation Blanket (9/21/2026 - 9/22/2026) Sta 834: Unit 4A - Replace Lubrication System (9/7/2026 - 9/11/2026)
Station 534 South of Pool (segment 530 BH)	1,550	1528 (22)	1528 (22)	1528 (22)	1528 (22)	Sta 530: Unit 1A - Bearings (8/25/2025 - 12/31/2026) Sta 530: Unit 3A - Crankshaft Replacement (6/9/2025 - 12/31/2026) Sta 530: Unit 5A - Top-End Overhaul (6/9/2025 - 12/31/2026)
MLV 548 (segment 542 BH)	1,647	1640 (7)	1,647	1,647	1,647	Sta 542: Unit 2A - Emergent Repair (4/7/2026 - 8/31/2026)
Station 860 (segment 548 BH)	1,593	1,593	786 (807)	1,593	1,593	MLV 546-2 to MLV 547-2: Line Recoat (9/8/2026 - 9/10/2026) Sta 546: Annual ESD Tests & Maintenance (9/7/2026 - 9/11/2026)
Station 860 North (Segment 860 BH)	1,874	1846 (28)	1846 (28)	1530 (344)	1846 (28)	Sta 563: Unit 1A - Annual Inspection & Safety Device Check (9/15/2026 - 9/16/2026) Sta 563: Unit 2A - Annual Inspection/CAV (9/16/2026 - 9/17/2026) Sta 860: Unit 1A - Aftercooler Jacket Water Inspection (6/17/2025 - 12/31/2026)
Station 110 (segment 187 BH) (south thru Kentucky)	2,685	2534 (151)	2534 (151)	2534 (151)	2200 (485)	MLV 104-3 to MLV 106-3S: HDD at Kentucky River (9/21/2026 - 9/25/2026) MLV 109-3A to MLV 110-3: Pipe Replacement (9/8/2026 - 9/15/2026) MLV 109-5 to MLV 109-5A: Pipe Replacement (8/18/2026 - 9/1/2026) MLV 109-5A to MLV 110-5: Pipe Replacement (8/18/2026 - 9/1/2026) MLV 54-3 to MLV 106-3: Emergent Repair - CAO (2/26/2026 - 12/31/2026) MLV 96-3BR to MLV 96-3BL: Spike Test (7/27/2026 - 8/31/2026) Sta 106: Unit 2D - 4K Solar Turbine Inspection (9/22/2026 - 9/24/2026) Sta 87: Unit 3D - Power side Overhaul (6/22/2026 - 9/30/2026)
Station 114 (segment 114 BH)	907	393 (514)	907	772 (135)	907	MLV 117-3 to MLV 118-3: Special Permit Pipe Replacement (8/10/2026 - 8/31/2026) MLV 119-2 to MLV 119-2A: Special Permit Pipe Replacement (8/10/2026 - 8/31/2026) Sta 118A: Solar Turbine Inspection (9/14/2026 - 9/16/2026)
Station 204 (Segment 204 BH)	1,828	1,828	1540 (288)	1760 (68)	1375 (453)	MLV 214-3 to MLV 219-3: Pig Run - Cal/IMU/MFL-A Combo (M) (9/17/2026) MLV 214-3 to MLV 219-3: Pig Run - Gauge/Cleaning (M) (9/15/2026) Sta 200: Scrubber Filters (9/8/2026 - 9/10/2026) Sta 204: Scrubber Filter Change (9/24/2026 - 9/26/2026) Sta 209 Cambridge: Scrubber Filter (9/21/2026 - 9/23/2026)

**TGP - Outage Impact Report
September 2026 (updated 06/18/26)**

-Primary impact restrictions may be necessary

-Major impact restrictions may be necessary

-Minor impact restrictions may be necessary depending on flow conditions

-Little to no impact, though minor outages may cause incremental reductions

Station # / Lateral	Est Nominal Operating Capacity (Thousand Dth)	Week 1	Week 2	Week 3	Week 4	Primary Outage(s)
		(8/31 - 9/6)	(9/7 - 9/13)	(9/14 - 9/20)	(9/21 - 9/27)	
		Est. Operational Capacity (Operational Impact) - Thousand Dth				
Station 230C (segment 296 FH)	743	743	370 (373)	743	743	Sta 230C: Scrubber / Filter Inspection (M) (9/9/2026 - 9/10/2026)
Station 245 (segment 245 FH)	986	970 (16)	970 (16)	970 (16)	970 (16)	Sta 245: Unit 1A & 2A - Exhaust System & HP Fuel (4/27/2026 - 11/1/2026)
Station 261 Discharge East (segment 261 FH)	888	888	888	888	560 (328)	Sta 264 Charlton: Annual ESD Test (9/23/2026 - 9/24/2026)
Station 307 (segment 307 BH)	1,153	1,153	1,153	1,153	1,153	
Station 315 (segment 315 BH)	1,823	1,823	1,823	1,823	1,823	
MLV 324 (segment 324 FH)	1,767	1,767	1,767	1,767	1,767	
MLV 329 (segment 324 FH)	846	846	846	846	846	
Station 405 HC Line (segment 299 FH)	794	794	794	794	794	

This document is updated on a weekly basis and outage schedules/impacts are subject to change as the week progresses.
 Dates posted on DART should be deemed correct in the event of conflicts between DART posted dates and dates on this report.
 The impacts sheet are based on steady-state hydraulic models assuming recent operating flows, conditions, and various unit outages.